

# WOOD PATTERN-MAKING



PURFIELD














A TRIMMER

# WOOD PATTERN-MAKING

A TEXTBOOK  
FOR THE USE OF HIGH SCHOOL, TRADE SCHOOL,  
TECHNICAL SCHOOL AND COLLEGE  
STUDENTS

BY

HORACE TRAITON PURFIELD

Instructor in Pattern-making and Foundry Work, High School, Fort Wayne, Ind.  
Formerly Instructor in the Shops of the Engineering Department  
of the University of Michigan

With drawings by

EDWIN VICTOR LAWRENCE



---

SECOND EDITION

---

THE MANUAL ARTS PRESS  
PEORIA, ILLINOIS

COPYRIGHT, 1906  
HORACE TRAITON PURFIELD  
COPYRIGHT, 1911  
HORACE TRAITON PURFIELD

## PREFACE TO FIRST EDITION

An experience of seventeen years in teaching pattern-making and kindred subjects has made me feel the great need of such a work as this which I now offer as a textbook for students in technical and manual training schools, and universities. A number of excellent books on the subject have been published, to be sure, but most of them assume on their reader's part previous acquaintance with the fundamental ideas of pattern-making; such as do treat at all of the elementary part of the subject, happen to be works of an exhaustive character, which are consequently too expensive for use as textbooks. The present work, therefore, will, it is hoped, find a field of usefulness for itself.

It is of course to be recognized that as pattern-making is an art, it cannot be learned simply by reading any book on the subject, but only by practice. Still a textbook may afford valuable assistance even to the artisan. This work, however, has a further and more important purpose,—that of imparting to the engineer or the draftsman the fundamental principles of pattern-making. For only as he is in possession of these can he make designs for patterns in accordance with which shopwork can be performed in the most efficient and most economical manner. The reader should also understand that this work, being designed only as an elementary treatise, in no way exhausts the subject.

It is claimed, however, that the examples of pattern-making submitted indicate, on the whole, the best methods of construction and those most easily understood by the student.

In preparing the body of this work, I have received many valuable suggestions which have been incorporated herewith, and which will have contributed to any success the book may attain. The works of many previous writers on the subject have been consulted also; for specific ideas derived from them credit should be given to Joshua Rose, M. E., J. McKim Chase, and P. S. Dingey. In preparing the appendix considerable help was afforded me by the little book of W. F. M. Goss, on "Bench Work in Wood." With these few words of introduction, I leave the book to its readers with the hope that it will assist them to master the important subject of which it treats.

H. T. P.

## PREFACE TO SECOND EDITION

In presenting the second edition of Wood Pattern-Making, I wish to express my appreciation of the hearty reception given to the first edition, and at the same time to bespeak as kindly treatment of the present effort.

The book has been thoroly revised and several additions made to it. The drawings for the illustrations have all been re-made by Edwin V. Lawrence, and the arrangement of the subject matter has been changed so that the chapters on tools and their use now appear at the beginning instead of the end of the book. It is hoped that this change will add to the usefulness of the book, especially for schools giving a short course in general woodworking just previous to taking up pattern-making.

Fort Wayne, Ind.  
April, 1911.

HORACE T. PURFIELD





## CONTENTS

CHAPTER I.—HAND TOOLS FOR WOOD.....	9
Measuring and Lining Appliances .....	11
Chisels and Chisel-like Tools .....	19
Saws .....	22
Boring Tools .....	27
Miscellaneous Tools .....	30
Planes and Plane-like Tools .....	33
Cutting Wedges .....	41
Laying Out Work .....	45
CHAPTER II.—LUMBER .....	46
CHAPTER III.—READING WORKING DRAWINGS.....	53
CHAPTER IV.—PATTERN TURNING.....	60
Sharpening Lathe Tools .....	69
Tools for Measuring Turned Work .....	70
CHAPTER V.—INTRODUCTION TO PATTERN-MAKING.....	72
CHAPTER VI.—MOLDING .....	77
CHAPTER VII.—GENERAL PRINCIPLES .....	83
CHAPTER VIII.—MATERIALS .....	91
Sandpaper, Glue, Varnish, Beeswax, Nails.	
CHAPTER IX.—FILLETS .....	101
CHAPTER X.—CORES .....	107
CHAPTER XI.—MOULDERS' JOINTS OR PARTINGS.....	116
CHAPTER XII.—CONSTRUCTIONAL JOINTS .....	125
CHAPTER XIII.—TYPICAL PATTERNS .....	136

CHAPTER XIV.—PULLEY PATTERNS .....	163
CHAPTER XV.—PATTERNS FOR CAST GEARS.....	182
Bevel Gear Patterns .....	196
CHAPTER XVI.—PIPE FITTINGS .....	202
CHAPTER XVII.—ESTIMATING WEIGHT OF CASTINGS.....	209
CHAPTER XVIII.—MISCELLANEOUS PATTERN WORK.....	213
Skeleton Patterns .....	215
Gluing Feather-Edged Board.....	219
Large Lathe Chucks .....	221
Lugs or Projections for Machinists' Use.....	222
Finishing Patterns .....	225
Loose Pieces .....	227
Standard Patterns .....	229
Stove Pattern-Making .....	231
INDEX .....	239

## CHAPTER I

### HAND TOOLS FOR WOODWORK

For all handwork the bench is the first requisite. The best form of bench for pattern-making is that illustrated by Fig. 1. If this is fitted with a No. 1 Emmert Pattern-Maker's Universal Vise, Fig. 2, instead of the one shown at the head of the bench, it will be the best




FIG. 1.

that can be obtained for this part of the shop equipment for pattern-making, and also for cabinet making. The **bench-hook** is a very useful part of bench equipment, one form of which is shown at Fig. 3; it should be 12 to 14 inches long. Some form of saw-horse is also a necessary part of the pattern shop equipment; a handy and easily built form is shown in Fig 4. Another almost indispensable article, something like a

bench in its nature, is what is known as a **laying out table**, or large drawing board, on which work can be laid out full size when necessary. It should be built very solid, and have a top that is a true plane. This




FIG. 2.



FIG. 3.

will be found very convenient on which to build some classes of patterns, for by using this they may be built up over the lines laid out, as is sometimes necessary. In some shops this laying out table is of iron, with the top planed true.



FIG. 4.

## MEASURING AND LINING APPLIANCES

The standard of length used by mechanics and engineers in the United States is the English yard. The standard for reference is the "Troughton Scale," a bronze bar with an inlaid silver scale, made for the coast survey of the United States, by Troughton, of London. This was adopted as the standard by the Treasury Department in 1832, on the recommendation of Mr. Hassler, who was at that time the superintendent of the United States Coast Survey. The **meter** has since been made the legal standard; the act of Congress making it such was passed July 27, 1866.



FIG. 5.

The most commonly used measuring appliance, however, is what is known as the **two foot rule**. This is a strip of wood, usually boxwood, 24 inches long, and about  $\frac{1}{2}$  inch wide. For convenience in carrying, it is jointed so that it can be folded into two or four folds. These rules for general woodworkers' use are graduated in 16ths of an inch on one side and 8ths of an inch on the other. The better class have the inside of each leg graduated in 10ths and 12ths of an inch, Fig. 5. Another form of rule is what is known to pattern-makers as the **shrink rule**. By the use of this in pattern-making, due allowance is made in the pattern for the shrinkage that will take place in the metal of the

casting. The common form of this rule is a strip of boxwood  $1\frac{1}{4}$  inches wide, and  $24\frac{1}{4}$  inches long. It is divided equally into twenty-four parts, and each one of these parts is subdivided as in the ordinary two-foot rule.

Another measuring instrument that is very useful to all woodworkers, especially to those having much laying out to do, is the **framing square**. This consists of two flat, thin pieces of steel, united at right angles to each other. One piece is 2 inches wide and 24 inches long; the other  $1\frac{1}{2}$  inches wide and 17 inches long, Fig. 6. These are graduated along the edges of the flat sides the same as the two-foot rules; but besides these graduations there are others running through the center of the sides. On one side of this **blade**, as the wider side or leg is called, is the Essex board measure, which is very useful for reading off the area in square feet of a board or any surface, when its length in feet and its width in inches are known. On one side of the short leg, or **tongue**, as it is called, is the **brace measure table**. This table is composed of sets of three figures, two of which are the lengths of two sides of a right-angled triangle, the other the length of the hypotenuse.

The use of the Essex board measure may be demonstrated by working the simple problem of finding the number of feet contained in a board of certain outside dimensions. But first let us learn what is meant by the term "a foot of lumber" or a **board foot**. The board foot is the unit used in computing lumber and is 12 inches long and 12 inches wide and 1 inch thick, so that if a board is 12 feet long and 12 inches or 1 foot wide, it contains 12 feet of lumber if it is 1 inch thick;




FIG. 6.

if it is 2 inches thick it will contain 24 feet ; if 3 inches thick, 36 feet, and so on.

The space surface, or area, 12x12 inches, is also called a square foot, and sometimes a superficial foot. These terms, however, refer only to the surface, and in no way do they recognize the third dimension or thickness. The Essex board measure as it appears on the blade of the steel framing square is made up of a series of parallel lines or columns, one series being parallel with the edges of the blade, and another perpendicular to these. The figures representing dimensions are located in these columns. The figures on the outside edge of the blade, 1, 2, 3, and so on up to 24, are employed to represent the width of a board in **inches**, and all the lengths in **feet**, included in the table, in the column under figure 12 of these outside graduations. The numbers in this column vary somewhat on the different makes of squares, but it usually contains the numbers 8, 10, 14, 16, and 18, these numbers representing the length of the board in **feet**. It should be noticed that these numbers represent the commercial lengths to which most lumber is cut, and to be found

in all lumber dealers' yards. To find the number of board feet or feet of lumber in any board, first look in the column of the outside graduations under 12 for a number representing its length in feet. Having found it, pass the finger along on the same line until it comes under the figure in the outside graduations that corresponds to the width of the board in inches. The figure on this line nearest the finger represents the number of board feet the board contains if it is 1 inch thick.




FIG. 7.

Example 1: How many feet of lumber are there in a board 10 feet long, 7 inches wide and 1 inch thick? Under 12 of the outside graduations the 10 is on the second line, and the figure on this line that comes under the figure 7 is 5—10—5 feet 10 inches. This example may be stated and worked in figures thus:  $10 \times 7 = 70 \div 12 = 5-10$ .

Example 2: What is the superficial area of a board (or any surface) whose length is 8 feet, and width is 21 inches. As in example 1, look under 12 of the outside graduations for the figure 8. On this line, under the number 21, will be found 14, which represents the area in feet. Again,  $8 \times 21 = 168 \div 12 = 14$ .



This scale may be used to find the area of any surface within its limits when the length of the surface in feet and its width in inches are known.




FIG. 8.

A try-square is shown by Fig. 7. The beam A is of wood, faced with a strip of brass to protect it from wear.




FIG. 9.

The blade B, at right angles to the beam is of steel. In some try-squares the blade is graduated. Some try-squares are made entirely of metal. Fig. 8 represents a combination square; the blade is movable so it can

be used at any length on either side of the head. The **bevel**, Fig. 9, sometimes improperly called a bevel square, is made up of parts which are similar to those of the try-square, and have the same names. The blade is adjustable to any angle with the beam, and when set, the thumb-screw fastens it. The size of both square and bevel is expressed by the length of the blade in inches. The **miter-square** is similar to the try-square,




FIG. 10.

but has the blade set permanently at an angle of  $45^\circ$  to the stock or beam.

The dividers are used in spacing and laying out circles. They are also very useful for laying out and transferring angles. One way of using them for this purpose is illustrated in Fig. 10, which shows how to set a bevel at an angle of  $60^\circ$  and  $120^\circ$ . To do this, take a board that has been planed flat, and one edge jointed; that is, planed straight. Gage a line at any distance from this straight edge. From any point on this line, with any radius, use the dividers to make the arc C. With same radius from B make the arc D. Now draw

a line passing through the intersection of C and D and the point first selected on the line AB. This line will make an angle of  $60^\circ$  with the edge of the board if measured on one side, and  $120^\circ$  if measured on the other.




FIG. 11.

To set the bevel, place the stock or beam against the edge of the board and swing the blade until it exactly coincides with the line.

Fig. 11 shows the usual form of **marking gage**. The steel spur should be filed to a thin cutting edge; the




FIG. 12.

long way of this edge is to stand at or near right angles to the beam in such a way that when pushed along with the left hand, its tendency will be to pull the gage onto the piece gaged. The square-shaped piece through which the beam slides is called the **head**. The graduations on the beam are not to be depended on for

accurate measurements. The **mortise gage** has two spurs; one of them is movable on the beam, being fastened to a brass slide that is moved back and forth by a thumb-screw at the end of the beam. This is shown at Fig. 12.

## CHISELS AND CHISEL-LIKE TOOLS

There are two general forms of chisels used by woodworkers, viz., the tanged or shank, and the socket. These terms refer to the style of handle and to the way it is fastened to the chisel. Almost all chisels are now made entirely of steel. The tanged form is shown in



FIG. 13.

Fig. 13, and is called a **firmer** chisel. It has a long tongue or **tang** which is driven into the handle, the bolster coming up against the end of the handle, and so preventing its being driven further in. It is this



FIG. 14.

form of chisel that is usually used by workers in soft woods, such as joiners and pattern-makers. The better quality of this form of chisel has beveled edges as shown in Fig. 13. The other form, known as the **socket firmer**, is shown in Fig. 14. It is so called because the handle sets into a socket provided for it. This form of chisel is more generally used than any other, as all classes of woodworkers except joiners and pattern-makers employ it almost exclusively, while even some

of these prefer this kind because it is stronger than the tanged firmer. Socket firmers are made of different weights and lengths for different kinds of work. The better grades of these also are made with beveled edges.




FIG. 15.



FIG. 16.

**Gouges** have blades that are curved in section throughout their length, and are named and used like chisels. There are two general forms of this tool, viz: the inside gouge, Fig. 15, and the outside gouge, Fig. 16. The bevel of the first is ground on the inside of




FIG. 17.

the curve; that of the other on the outside. The latter is generally the more useful. The straight side, that is, the side opposite the bevel, is called the back in all chisels, gouges and plane irons, and should be kept perfectly straight, not beveled in the slightest degree. Gouges can be bought with the cross section of three different curvatures, known as **quick, middle, and flat sweep**. These are shown in Fig. 17, which represents the cutting edge

of each. The sizes of all gouges and chisels are designated by the width of the blade; a 2 inch chisel or gouge, for instance, has a blade that is approximately 2 inches wide. They are made in sizes as follows: from  $\frac{1}{8}$  inch up to 1 inch by 8th inches; from 1 inch to 2 inches by 4th inches.



FIG. 18.

The **drawing-knife**, or, as it is sometimes called, the **draw-shave**, is in reality a very wide chisel, but is not used in the same way. It is shown in Fig. 18.

## SAWS

The saw is one of the most useful and effective woodworking tools, but is perhaps the most difficult to keep in good order. Saws are of two general kinds—rip-saws and crosscut-saws. The **rip-saw** is intended to cut with the grain of the wood, the **crosscut-saw** is used for cutting across the grain. A rip-saw should be



FIG. 19.



FIG. 20.

from 24 inches to 26 inches long and should have from four and a half to six teeth to the inch. A crosscut-saw for bench use, is called a **panel-saw**; it should be about 20 inches long, and should have from eight to ten teeth to the inch. A full-sized crosscut-saw, called a **hand-saw**, is 26 inches long and should have from seven to nine teeth to the inch, Fig. 19. The **back-saw**, Fig. 20, is a crosscut-saw with a very thin blade and fine teeth; the blade is reinforced with a strip of brass or steel



along its back edge, hence its name. The **keyhole-saw**, Fig. 21 is a narrow-bladed saw used for entering small holes for the purpose of cutting a short distance until a larger saw may be used, or for cutting along curved lines. Another saw that is sometimes used for similar work but is somewhat larger, is called a **compass-saw**, Fig. 22. The keyhole and the compass-saw are likely




FIG. 21.




FIG. 22.

to be used both across the grain and with the grain, and are therefore filed differently from those designed especially for just one of these purposes.

As the rip-saw has to cut or sever the ends of fibres of the wood, its teeth should have chisel-like points. The crosscut-saw has also to sever the fibres of wood, but in a different way. As the cutting is done across the fiber of the wood, it requires what may be called a **scoring** of the fiber. The friction of the other parts of the teeth on the wood loosens the particles cut or separated, and carries them away in the form of saw-

dust. The size of the teeth is governed largely by the size of the pieces of wood to be sawn: for cutting trees into saw logs the teeth are very large; the back-saw has very small teeth because it is used for cutting comparatively small pieces of lumber.

In the actual filing of saws the size of the teeth is determined by the number of teeth in a given distance.




FIG. 23.

The size of its teeth, other things being equal, does not help or hinder the smooth cutting of a saw. For a rip-saw the best form of tooth is a **chisel-pointed** one; the best form for crosscutting is a **triangular-pointed** one. These two forms of teeth are shown in Figs. 23 and 24. The angles most suitable for general work are also indicated in the same figures, Fig. 23 representing the teeth for a rip-saw and Fig. 24 the teeth for a crosscutting-saw. These should be varied according to the kind of wood; they should be less acute for hard wood and more acute for soft wood. The keyhole-saw and compass-saw are filed with a combination of these angles.

In fitting or sharpening a saw for use, there are four distinct operations to be performed:

1. It must be **top-jointed**; that is, a file should be passed along the tops of the teeth, so that they may all be of the same height and extend in the same general line, the line being a slight curve. **Top-jointing** is best done with a flat file set in a block of wood as shown by Fig. 24 a. In use, the slot A is set over the saw blade. This holds the side of the file perpendicular to the sides of




FIG. 24.

the saw making the tops of the teeth square with those sides. A very convenient little tool for this purpose may be purchased of tool dealers.

2. It must be **set**; that is, the point of each tooth is bent sidewise, adjacent teeth being bent in opposite directions. This is done so that the **saw kerf** (as the path made by the saw in passing thru the wood is called), will be cut wider than the thickness of the saw plate, and will therefore allow the saw to be moved back and forth without sticking. Setting is sometimes done with a hammer set, but usually with some form of plier set, of which there are several good ones in the market.

3. It must be **filed**; that is, the individual teeth must be filed to a point. This must be done very carefully,

having the saw firmly fastened in a saw clamp, preferably an iron one. The file should be moved over the saw with a **firm, steady** stroke, as nearly the whole length of the file as possible, and with just enough **pressure** and **no more**, to make the file cut. If a chattering noise is made by the file it is an indication that the saw is improperly supported, or that the file is dull.





FIG. 24a.

4. It should be **side-jointed**; that is, a file or, preferably, an oilstone should be passed along the side of the teeth, which will even up the set. This can be done very readily by laying the saw on one of its sides on a flat board or on the bench top and passing an ordinary oilstone along the teeth, care being taken to keep the larger part of the oilstone above the teeth so as not to round off their points.

## BORING TOOLS

In Fig. 25 is shown the auger bit. This is the Russel Jennings pattern, one of the best of its kind. Fig. 26 represents what is called a square-hole auger. The boring is done by a common auger bit on the inside of a thin shell, which is square; the corners are sharp-



ened, and, as the extra long spur or screw on the end of the auger draws it into the wood, these square corners cut the hole made by the auger into square form. Fig. 27 is the Syracuse drill-bit. This is the best all-round drill for wood. Because of its shape, it will bore in any direction of the grain, and it will also operate close to the end of a piece without splitting it. If

it becomes dull it can easily be sharpened. In Fig. 29 is shown the expansive bit, one of the most useful boring tools, because of its range in size. It can be set to bore any sized hole within its range. Two sizes can be purchased, one boring holes from  $\frac{1}{2}$  inch to  $1\frac{1}{2}$  inches, and the other from  $\frac{7}{8}$  inch to 3 inches. Fig. 28




FIG. 33.

shows another boring tool that is very handy, especially to pattern-makers and to others who want to bore holes with smooth bottoms. It is called the **Forstner bit**. It has no spur or leading screw, so it must be pushed to its work. Fig. 30 is what is known as a center bit. It is very convenient for boring holes in work, as it (the work) revolves in the lathe. The central spur is not a screw, but simply a triangular point, so that this bit, like the last one, must be forced to its work; thus it can be made to do its work rapidly or slowly as the job may demand.

In providing holes for screws it is found to be almost necessary, especially in hard wood, to countersink the

top for the screw head. In Fig. 31 is represented one form of tool used for this purpose; it is called a **counter-sink**. Fig. 32 shows one form of combination drill and countersink.

In Fig. 33 is shown one of the best forms of what is called a **bit-brace** or **bit-stock**. This is Fray's ratchet bit-brace. For general use the auger-bit is preferred, as when sharp it will cut a very clean, smooth hole, and do it rapidly. In boring a hole through a piece of wood with this bit, when it is desired to leave both sides smooth, care should be taken not to let the bit go clear through from one side, but to bore just far enough so that half the length of the screw comes through; then remove the bit and finish the hole from the other side. Another way this may be done is to clamp a piece of waste wood to one side of the piece through which the hole is to be bored before boring the hole.

## MISCELLANEOUS TOOLS

Hand screwdrivers are of several shapes. Fig. 34 shows one very common form which is a very good one for the bench worker. Some of the other forms are better for special uses. The part of a screwdriver that enters the slot of the screw head should never be wedge-shaped; otherwise, when force is applied, the tendency is to lift it from the slot instead of turning the




FIG. 34.

screw. The correct shape is shown in Fig. 34. Brace screwdrivers instead of having a handle, are provided with a shank for use in a brace.

A hammer and a mallet are needed for bench work. The **square** form of mallet is for some reasons the best. What is known as the **claw-hammer** is the best for general bench use. The nailset, though small, is a very necessary tool for bench work.

The miter-box, one form of which is shown in Fig. 35, is an almost indispensable tool for bench workers. It is the most useful when small pieces of irregular outline, such as mouldings, have to be cut to a miter



line, as in the case of a picture frame, for instance. The word **miter**, when used without a qualifying word, is understood to mean the intersecting line between any two pieces of wood at right angles to each other,




FIG. 35.

as the diagonal of a square which makes it a  $45^\circ$  miter. When pieces are to be mitered at any other angle than  $45^\circ$ , the angle of the intersecting line is indicated in degrees; for instance, a sixty-degree miter.

When pieces of wood have to be held together temporarily, for gluing or any other purpose, some form of clamp is necessary. The form shown in Fig. 36, known as a **handscrew**, is the most used by pattern-makers. In using handscrews care should be taken

not to force the jaws too far from their normal parallel position; otherwise, the threads of the screws may be stripped, or even a screw broken. There are several forms of iron clamps on the market, one of the best of




FIG. 36.




FIG. 37.

which is illustrated by Fig. 37. These are sometimes very useful, but, all things considered, handscrews are the best for bench work.

A grindstone of some form is a necessity for grinding the cutting edges of woodworking tools. It should be selected with reference to its grit; one that is rather fine and soft is best. A power grindstone should have a speed of from 500 to 600 peripheral feet per minute, depending upon the steadiness and accuracy with which it runs. When a stone throws water from its face it is running too fast for doing good work in tool grinding.

## PLANES AND PLANE-LIKE TOOLS

A bench-worker's "set" of planes consists of four, the **jointer**, the **short jointer** or **fore-plane**, the **jack-plane** and the **smoothing-plane**. To separate these into a class they are usually spoken of as surfacing planes. These differ in length from 8 inches in the smoothing-plane to 30 inches in the jointer.

The jack-plane is the first one used in planing a rough surface, or in removing surplus material. If the surface is simply to be smoothed, then the smoothing-plane may immediately follow the jack-plane; but if a true surface is wanted the jack-plane should be first followed by the short jointer, and then by the jointer. With the last named plane in good condition, practically a true plane surface may be made. The carpenter or joiner would call this a surface that is **out of wind**.

To test a surface during the process of planing, **winding-sticks** or strips are used. A winding-stick is a strip of wood of wedge-like cross-section about two inches wide, and with both edges straight and parallel to each other. Two of them are needed to test a surface, one being placed near each end of it. After setting them on the surface exactly parallel to each other the workman should sight across from one to the other. As the eye is lowered, if the one farther away is lost sight of all at once, the surface, if straight between the points on which the strips rest, is a true plane, and is said to be **out of wind**. If the farther one does not disappear all at once, but the top edges appear to cross each other, then the surface is not a true plane, and is

spoken of as a winding surface or **in wind**. If the surface is in wind, notice which ends of the winding sticks are the higher. Then, if a true surface is wanted, plane off some of the surface at the points under the higher ends, and test again. In order to obtain the greatest advantage to be gained from the use of winding sticks, they should be considerably longer than the width of the surface to be tested. Thus the width of the surface is exaggerated, which is one object sought in using these strips. The blades of two framing squares answer admirably for this purpose.

The use of the surfacing planes, especially the jointer, should be thoroughly mastered, so that the surfaces of any piece or pieces to be used for the construction of any object may be readily and correctly planed. As plane surfaces are to a degree the foundation for the future work to be done on them, it is very essential that they should be correct; otherwise, poorly fitting joints will result. Good work cannot be done if the working faces are incorrectly planed. In order to obtain the best results from the use of these planes they should be so placed and held on the surface being planed that their sides are **parallel** with the **direction** of the **motion** given them as they are pushed over the surface. This is particularly true of narrow surfaces such as the edge of a board. If this one principle is applied in the use of the jointer, and the jointer is at the same time held **down firmly** on the surface being planed, little difficulty will be experienced, even by a beginner, in making a true surface.

The cutting irons of all these planes are true cutting wedges of different widths, the width varying with the

length of the plane. To each of these cutting wedges is added a supplementary iron called a **cap** or **back-iron**, which is placed, as its name indicates, on the back of the cutting iron, thus making it a **double iron**. The purpose of the back-iron is to break the shaving as it is made by the cutting wedge.

The exact way in which this is done can be explained better with a cut than with words alone. Fig. 38 shows




FIG. 38.




FIG. 39.

how the cutting wedge acts as a single iron. In Fig. 39 is shown the double iron and the effect of the back-iron on the shaving. As the shaving is cut and bent by the cutting wedge, its tendency is to follow the back of the plane-iron as at A, Fig. 38. As seen at A, Fig. 39, the back-iron prevents this, by changing its course and breaking it before it has time to split down into the wood. The single iron does very good work so long as the grain is favorable, but when it comes to a place on the board that is cross-grained, as at B, the shaving will split ahead of the cutting iron and leave the surface rough.

Fig. 40 shows the wood plane and the advantage of a **narrow mouth**, which the iron-plane shown in Fig. 39 lacks. This, too, changes the direction of the shav-

ing. It has also the advantage that it aids the plane in doing smooth work at a spot where the lumber is cross-grained because the wood directly in front of the narrow mouth holds down the wood being planed immediately in front of the cutting iron, and so prevents its being torn up before it is cut. This is one of the advantages that the wood plane has over the iron; another is the comparative ease of working. Still,



FIG. 40.

when everything is considered, iron planes are the best. Their principal advantage is that they will not warp or appreciably wear; consequently the face or sole of the plane is always a true plane surface.

The cutting edge of plane-irons should not be straight but slightly curved. For the jack-plane this curve ought to be much quicker than for the other planes. The jack-plane is frequently used for removing very thick shavings, and if the iron was straight, it would tear out a rectangular groove for the whole width of the iron. This would be very likely to clog the plane, and would also consume much more force than if the edge was curved. In a given time with a given amount of force applied, much more wood can be removed if the iron is curved than if it is straight.

Theoretically, the outline of the cutting edge for the jointer and smoothing-plane irons should be straight in order to produce a straight flat surface, but in practice this is not the case. On these irons the corners should be slightly rounded, or, what is better, be



FIG. 41.

slightly curved the whole length of the edge, but the radius of the curve should be much larger than the jack-plane iron.

Fig. 41 shows the iron jack-plane; the other three of the set are of the same shape. Fig. 42 shows one



FIG. 42.

form of the block-plane. The principal use of this plane is to smooth end grain. The angle at which the iron is set in this plane is much smaller than that of other planes. This being the case, the iron, which is always a single one, is inverted. If it were not inverted, the angle of the cutting wedge would have to be so small that it would not stand up to the work.

To prevent this plane from breaking the corners of the wood, when being used on the end of a board, another piece should be placed back of the one being



FIG. 43.

planed. If the board is of considerable width the plane may be worked from both edges and not carried clear across.




FIG. 44.

Another plane that is very useful to woodworkers is shown at Fig. 43, called a **rabbet** plane. The iron is set **askew** in the plane, and extends the whole **width** of the face. It is used for cutting a rectangular space called a **rabbet**, into the corner of a piece of wood.



Another plane-like tool is illustrated by Fig. 44. This is the carpenter's **plow**. Its principal use is the cutting of **rectangular grooves** into wood **parallel** with the grain. It is adjustable and can be set to cut the groove at any distance from the face of a board. Irons




FIG. 45.

of different widths are supplied so that grooves of any width and depth within their range may be cut.

A plane called a **dado plane**, shown at Fig. 45, is used for cutting **rectangular grooves crossways** of the



FIG. 46.

grain. Its iron is set askew. It has a depth gage to regulate the depth of the groove. Combination planes made of metal, which may be used in the place of the plow, dado, matching planes, beading planes, etc., are on the market and some of them are very serviceable tools.

Spoke-shaves have the action of planes but are not usually classed with them. A simple form is shown at Fig. 46. It has a very small face which adapts it for use on irregular surfaces. There are several other forms of planes in use, but most of them are designed




FIG. 48.

for specific uses, and are not commonly used by the pattern-maker.

There is one plane, however, used by pattern-makers, which is mentioned in another chapter, and there represented in the wooden form, that should be noticed here, namely, the latest form of iron core-box plane, represented in Fig. 48.

## CUTTING WEDGES

From the woodworker's point of view, the chisel is the typical cutting tool. It has two operations to perform when in action, viz.: **cutting** the fiber of the wood, and **breaking, crushing** to one side, or **bending** the wood out of the way, so that the cutting edge may go on with its work. Every cutting tool is a wedge, more or less acute. To widen the cut the wood must be bent; this the cutting wedge of the plane does, and thus forms a shaving. The chisel, when driven into the wood, as in cutting a mortise, crushes the wood and so widens the cut. When the wedge is driven in parallel with the grain, the fibres are pressed apart, the cut is widened and the wood split. It can be demonstrated that much less force is required to carry the wedge forward when first entering the cut than after it has extended into the material for some distance. It is reasonable, therefore, to suppose that the larger part of the force applied to form a shaving or chip, is consumed in this bending or crushing, and a very small part in the actual cutting of the fiber of the wood. A very acute-angled wedge will do a given amount of work with less force than one not so acute. But the one with the larger angle will do the actual cutting as easily as the other. The angle of the wedge has very little to do with the force required to do the **cutting**, at least up to any angle that would or could be used for cutting wood. The acuteness is **limited** only by the **strength** of the **steel**, so it must vary as the kind of work and material varies. A more acute one may be used for soft wood than for hard wood. And again, a larger-angled wedge is needed in a chisel that is to be

used or driven to its work with the mallet than in one that is to be used with the hands only.

If it was insisted that a cutting wedge should always have its maximum of delicacy, it would necessitate that the angle be changed for almost every shaving or chip made. This would be impracticable, so that the results of the experience of woodworkers may be expressed as follows: "Make the cutting wedge as acute as the metal will allow without breaking, when fairly used." The angle of the wedge for all wood-cutting tools for general use should be from  $22^{\circ}$  to  $30^{\circ}$ .



FIG. 49.

The sharpening of a cutting wedge requires considerable care and skill, if first-class work is to be done with it. If the chisel or other edge tool is new, or very dull, it must first be ground. This is best done on a medium grit, soft grindstone. Emery wheels are largely taking the place of grindstones for this purpose. Greater care is necessary in the use of emery wheels than with grindstones for grinding **woodworking** tools, for the wedge being thin, the temper of the steel is very liable to be drawn by the heat generated by the friction. In grinding a cutting wedge, the grindstone should revolve **toward the cutting edge**. The correct position in this regard, and also to produce the best angle for general use is shown in Fig. 49. Plently of water must be kept

on the stone during the process of grinding. The water serves two purposes; one is to reduce the temperature generated by friction, the other to keep the stone clean or to carry off the particles of sand and metal loosened in the process of grinding. The surface produced by the grinding is called the **bevel**.

As the coarse grit of the grindstone will not produce a clean, smooth cutting edge; the tool will have to be **whetted**. This is done on an oilstone, either natural or artificial. The latter kind, if made by a reliable firm, is better, as it wears more evenly. The tool, while held in such a position that the **heel** of the wedge does not quite touch the stone, should be carried back and forth along the whole length of it, care being taken not to give the tool a rocking motion, which would produce a curved instead of a straight line. This operation should be continued until a slight wire edge is produced on the **back**, as the straight side is called. The wire edge must be removed in order to produce a sharp edge that will cut smoothly. To do this, lay the tool on its **back**, flat on the oilstone, and give it a few light strokes toward the edge, from the operator. Great care should be taken **not** to raise the handle of the tool, as that would bevel this side of the wedge and impair the proper working of the tool. There are two tests that may be used to determine whether the edge is sharp; one by the eye, the other by the sense of touch. If a sharp edge is examined by the eye, it will be noticed that a dull line appears where the edge is. If the edge is not sharp, a bright line will be seen. The more dull the tool is, the larger the bright line will appear. To test by the sense of touch, place the thumb or finger on the edge, and try to move it,

along the edge. If it is not sharp, no difficulty will be found in doing this. If, however, the edge is sharp, a clinging or pulling sensation will be felt. The best test, however, is to cut wood in the same direction as the work to be done. If the surface cut is smooth and glossy, the tool is sharp. If the tool is dull it will cut a surface that is rough and dull to both touch and sight.

## LAYING OUT WORK

The production and location of lines is one of the most important parts of woodwork, as of all mechanical work, in the production of work of a definite size and shape. Any carelessness in this direction will always make itself manifest in the finished product. This is so much the case that one who is habitually careless in this regard seldom makes a good mechanic. Let it be understood at the outset that a scratch is not a line, and that patience and accuracy in the making and locating of lines is one of the first requisites to success in all mechanical manipulations, and in the production of all articles made by mechanical processes.

The tools used for making lines are four,—the chalk line, pencil, gage and knife. For bench work the knife and gage are the most used. The knife is used for marking across the grain, and should have a sharp point so that it will cut into the wood, not merely scratch it. In making a mark where a cut is to be made with a saw, it is advantageous to cut the lines about  $\frac{3}{8}$  of an inch deep. If this is done and the saw kerf made close up to it, the side that is left makes a nice clean surface to abut against another piece, for instance the shoulder of a mortise-and-tenon joint. The gage is the best implement for marking lines lengthwise of the grain. A great deal more might be said about this part of wood-working, —**laying out work**, as it is usually called—but lack of space forbids.

## CHAPTER II

### LUMBER

Lumber is produced by sawing trunks of trees lengthwise into planks or boards of commercial sizes. In order to produce special sizes and shapes, the sawing is done in several different ways without regard to the grain of the wood. There are, however, two general methods used, by one or the other of which the larger part of all lumber is produced. One of these is called **straight** or **bastard** sawing; the other **quarter-sawing**. Straight sawn lumber, sometimes called "rift sawn," is produced by passing the saw thru and thru the log, without any regard to the grain. Quarter-sawn lumber is made by passing the saw through the log approximately parallel with the medullary rays, or radially with the log. There are several ways of doing this, one of which is as follows: The log is first squared and then sawn into four quarters. Each one of these is set on the carriage of the sawing machine so that the saw will pass thru it diagonally. The sides of the center board will then be parallel with the medullary ray. This method gave rise to the term "**quarter-sawn**." The larger part of all quarter-sawn lumber produced is made by this method, and other similar ways that vary with the requirements of the consumer. What is known as No. 1 quarter-sawn lumber has one side of each board sawn radially to the log and therefore is parallel to the medullary ray, or as near as can be if the crookedness of the ray is considered. This last



mentioned method is very wasteful of timber, therefore the product is much more expensive than lumber sawn in other ways.

If the trunk of a tree is cut transversely, it is found to be composed of a series of concentric cylindrical layers, the cross sections of which form rings that are quite distinct from each other. These layers are formed, one each year, during the period of the tree's growth. They vary in thickness in different kinds of wood, and in different specimens of the same kind. They also vary in density and color; the more dense or hard are always found near the heart. These variations are due to the difference in rapidity of growth, length of season, and other circumstances that may change from year to year. The location and soil in which the tree grew also modify to a degree the above characteristics of these layers. It is these layers of woody fiber that give to boards the appearance called **the grain**. This appearance varies according to the position the board occupied in the log. The part of the wood next to the bark is called **sap-wood**; all on the inside of this is called **heart-wood**. Heart-wood is generally more dense, of a darker color, and is much more durable than sap-wood. During favorable weather the sap of the tree circulates through the sap-wood, but during the winter it is supposed to cease; it is this period of non-circulation of sap that causes the distinct lines that appear between successive annual rings. The darker color and greater density of heart-wood is caused by the closing up of its cells by the gums of the wood which were previously held in solution. For this reason it is nearly or quite impervious to sap. There is a difference in the propor-

tion of sap-wood in different kinds of trees, and in different individual trees of the same species. The slower growing trees usually have the least.

For a tree to afford the best quality of lumber it should not be cut until it has arrived at maturity. The oak is said to reach this period in about 100 years, the pine in 70 to 100 years, and ash and elm at from 50 to 100 years. Midwinter or midsummer are the seasons of the year best adapted for the felling of timber to secure the best quality of lumber. The principal reason for this is the fact that at these seasons the trunk of the tree contains less sap than at others.

Seasoning lumber is **driving out the sap** from its pores. This may be done by natural or artificial means. However it is done it should be a slow process, especially in its first stages; therefore, natural, or air seasoning, gives the best results. For any purpose where strength or permanence of form is very desirable, it is best to properly **stick up** the lumber in a seasoning shed that will protect it from the sun, rain, and snow, for at least one year, and then put it in a drying kiln to complete the process. If lumber is put into the kiln when green, the sap is driven out so rapidly by the high temperature that it carries with it more or less of the gums of the wood. This is prevented by **sticking up** in the shed, as during the time it is under these natural conditions the process is comparatively very slow. All these gums should be retained, if possible, as they add strength and density to the lumber; and the more dense wood is, other things being equal, the more permanent will be its form under varying conditions of the humidity and the temperature of the surrounding atmosphere. Con-

versely, then, if these gums are driven out during the process of seasoning, the wood is not as strong, and is more porous, also, and will therefore absorb and give off moisture more readily, which will interfere with its permanence of form. Lumber cannot be so well seasoned as not to shrink when placed in a dryer atmosphere.

If wood is placed in air that is devoid of moisture, it will continue to retain a portion of its original moisture. A log taken from a freshly cut tree contains about 50 per cent, by weight, of water. (The sap-wood contains more than this percentage, the heart-wood less). When the log (stripped of its bark), is allowed to remain in the open air, more than half of this water will evaporate in a few months. If it is sawn into lumber and stuck up in a seasoning shed, the water will be further reduced to from 12 to 15 per cent. of the total weight; if it is put into an ordinary living room it will be reduced to from 8 to 10 per cent; if it is put into a drying kiln operating at a temperature of from 160° to 180° F., only from 2 to 4 per cent. of water will be left; but tho the temperature be raised to 300° F. (when chemical destruction begins), water will still be given off. Immediately after wood is taken out of a kiln it begins to absorb moisture. In a week it will have regained from 5 to 6 per cent of moisture; in a month or so, its condition, if kept in the open air, will be normal—that is, 12 per cent of its weight will be due to the water it contains. Whenever wood gives off moisture it shrinks. Green wood will, in seasoning, shrink about 8 per cent of its width across the grain. One of the objects of seasoning is to reduce the moist-

ure to the proportional limit that will obtain between the wood and the air with which it will be surrounded after it is manufactured into some article of use or ornament. Neither air seasoning nor kiln-drying at a temperature below 200° F., will affect the capacity of wood for taking up moisture when there is an excess of humidity in the air, and whenever wood takes up moisture it increases in size (swells).

This faculty in wood of resuming original size, of being larger or smaller according to atmospheric conditions, is one of the most difficult problems with which woodworkers have to deal. To paint woodwork, or to varnish it makes little difference to these qualities; these coatings simply retard these changes, they do not overcome them. For this reason, whenever it is required to cover large areas with woodwork, some method must be adopted to nullify the effect of, or of concealing altogether, the "working" of the various pieces of wood after they are placed in position. The combined precautions of intelligent framing, and the application of protective coatings fail to secure immunity from these hygroscopic effects. Wood is doubly affected by the cold, damp air of the winter months. By the natural or air seasoning process, two years for small or thin, and four years for large or thick lumber, is necessary to secure good results. Lumber is, however, rarely overseasoned. It may be much more rapidly seasoned by high temperatures in drying kilns. It is not impossible to season 1 inch thick boards by this means in two days, but it "kills the life" of the timber. As a rule, the softer a wood is, the more readily it will shrink or swell. Great care should be taken in

preparing the foundation on which to pile lumber for the purpose of seasoning it both in the shed and dry kiln. The edges of the timbers on which the boards are laid should all be in the same plane, so that the boards (which will retain the shape given to them by the pile), may be true planes when taken out of the pile after seasoning.

Warping in wood is a **change of form** resulting from unequal shrinking or swelling. It is sometimes caused by unequal exposure; in fact this is its most fruitful cause. When a board is so placed that one side is exposed to the direct rays of the sun or other heat, and the other to a damp atmosphere, the first side will become concave. A board, especially a green one, will also warp when it is equally exposed, that is, when it is surrounded by equally dry air. The cause of this is, that the board, because of the arrangement of its cells, gives off the moisture it contains more rapidly from one side than the other. The side that dries first will become concave. Now if a board is cut from a log midway between the heart and sap, there will be a larger number of the cells (which lie parallel to the sides of the annual layers), opened on the sap side; therefore, moisture will be given off more rapidly from that side, and, as wood always shrinks when it gives off moisture, that side will shrink first and become concave and the heart side convex. The medullary rays, as they shrink, also conduce to this form in a slight degree.

If these facts are kept in mind, and the end of a board is examined it may be known in what direction the board will warp when any of the above conditions obtain as to its surroundings. Quarter-sawn lumber

is cut radially to the log, and so does not contain these characteristics, therefore will not warp much..

From these facts, then, the following principle may be deduced: In all woodwork, the heart side of the board should always be placed on the side of the work that will be the most exposed to any change that is likely to take place in the surrounding atmospheric conditions, for the reason that, of the two sides, it is the least susceptible to change.

Because of the above noted characteristics of wood, it is best to cut the pieces to be used in any construction roughly to size, and allow them to stand for some time before they are cut to the finished size. If this is done, they may warp into a more permanent form, and so will be less likely to change the form of the final construction. A board that has recently been planed to a true surface should not be left lying flat on the bench, as it will warp and become concave on the upper side. This is due to the greater exposure of the upper surface compared with the under, which remained in contact with the bench. A board that has been planed to a true surface all over, should be left on its edge or end.

## CHAPTER III

### READING WORKING DRAWINGS

Mechanical drawing has been defined as the universal language of the engineer. A drawing made in one country can be read and worked to in another ; that is, the drawing proper. Notes on the drawing in the language of a country could not be read except by one acquainted with its language ; and, the unit of measurement also might be different, but the main idea represented by the drawing would be readily apprehended.

One who desires to read working drawings and get from them the information they are intended to convey, must know something of the principles underlying their construction, and the conventionalities used. All working drawings are made on the principle of orthographic projection, and are usually spoken of simply as **projection** drawings. That is, all the imaginary lines of sight, (projectors), are parallel, and perpendicular to the picture plane. There are three principal **views** used in the representation of objects by drawings, viz.: the **plan** or **top view**, the **front view**, and the **end** or **side view**. It is sometimes necessary to introduce a **fourth view**, which becomes a **second end** or **side view**. Each of these views is drawn so as to represent the different sides of the object at right angles to each other. When some parts of an object extend at an angle other than a right angle, auxiliary views are projected on the center lines of these angular parts, in order to show their



true shape. In the representation of simple or symmetrical objects, one view is omitted, usually the plan, as it is not necessary. Many objects or parts of machinery, with which the pattern-maker has most to do, can be represented with sufficient clearness by two views. When these do not clearly delineate the object, the third, and, if necessary, a fourth, is used.

The obscured parts of a simple object, that is, parts that do not appear on the surface represented, are shown by broken lines. In complicated objects this is not practicable because of the many lines that become necessary, which would be confusing and lead to mistakes. When for this reason this method of broken lines is not feasible, it is customary to imagine the object cut, or that an assumed plane has been passed through it, and the surface thus produced exposed. A drawing of such a surface is called a **section**, and indicates the shape of a piece at the place cut by the imaginary plane. A piece of varying section may be imagined to be cut by planes at as many places as is desired, and the section shown at each. Complete sectional views show not only the parts cut by this assumed plane, but also any other parts of the object which may be seen beyond. In symmetrical objects a line of centers or other line of symmetry is usually chosen through which to imagine an assumed plane has been passed. To indicate on the drawing the space representing this surface (the surface produced by the passing of this assumed plane through the object) is filled with uniformly spaced diagonal lines. Figs. 51 and 52. This is called **cross-hatching**. Different pieces of material appearing in the same section are indicated by the lines



running in different directions. Different materials are indicated by using different kinds or grouping of lines. An incomplete section shows the objects partly in full elevation, and partly in sectional elevation. Such drawings are also called broken drawings. Long, symmetrical parts, as a piece of shafting, may be shown by making drawings of the ends close together with the middle portion broken out. These are also called broken drawings, and are used to save space or to represent a long piece on a small sheet.

Various arrangements of views on a drawing are possible, each of which may be equally effective in conveying the necessary information. Attempts have been made to establish uniformity of practice in this respect, without effect, for the reason that such a vast variety of forms are encountered, and difficulties of execution are met in practical work, that in general it is not possible to follow any cut-and-dried rules. When making drawings for use in engineering construction, especially for workshop use, that draftsman is the best one who can convey the necessary information with the least expenditure of time and labor spent in making the drawing, consistent with neatness of execution and accuracy of dimensions.

A good general method of procedure in reading a working drawing is as follows: First, ignore for the time being the dimensions and dimension lines entirely until an idea is obtained and fixed in the mind of the general shape of the object. Second, referring to the several views, notice if its outline is to be a cylinder, a cube, a cone, etc., or a combination of several of these elementary forms. This being clearly impressed on

the mind, observe how it is modified by details, and, always referring to the several views, determine whether they project from the main body, or are recesses or holes. Finally form an idea of the relative





FIG. 50.

sizes of the component parts by referring to the dimensions. Pay strict regard to all conventional representations that have been used.

In Fig. 50 is shown how the views are usually arranged when three views of an object are given. This arrangement may be modified when some other will better convey the meaning. If still another view was thought necessary to represent the object as it would



appear when looking at its left side it would be located at the left of the front view; this would be called the left side view. In the drawing, A is the plan or top view, B is the front view, and C is the right side view. These names are purely arbitrary, and any side of the object may be assumed as the front view, except




FIG. 52.

when the object has a natural base, as a table, or a machine, etc. Then the plan is a drawing of the top side of the machine as it stands in its normal position, that is, on its natural base.

One good way of determining the shape of an object from a drawing is to imagine the paper on which the drawing is made to be bent on a line somewhere between two of the views until the surfaces are perpendicular to each other, or actually to bend the paper with the drawing on it in this manner; then imagine some object which if projected on the two planes would give outlines like the ones shown on the drawing, treating sectional views in the same manner as full views.

Fig. 51 is a working drawing of the headstock of a lathe. It illustrates several of the conventions previously mentioned. One of these is the arrangement of the views.

What is known as a broken drawing is also illustrated in Fig. 51 at D and D. In this case one-half of the object is supposed to be broken away, and a view given as the object appears at that point after its removal; this makes it easily understood as to the desired shape. Another convention illustrated is the method of indicating which surfaces are to be machined. It is by the use of the letter F, placed on or near the surface to be machined or finished. One method (broken lines) of indicating the location and size of tapped holes for the reception of bolts is also shown in the center of each bearing. Fig. 52 shows one way of representing simple circular objects that is used quite frequently in machine drawings. The sectional view is a complete section.

## CHAPTER IV

### PATTERN TURNING

The term **wood-turning** is generally understood to mean the making or forming of any circular form required of wood, while revolving at a high rate of speed in some form of lathe. Wood-turning is done in two distinct ways; first, along or parallel with the grain;




FIG. 53.

and second, across the grain, or, as it is sometimes called, **plankwise**. Wood-turning may be divided into two kinds, **cabinet turning**, by which balusters and other decorative articles are produced; and **pattern turning**, a method used by pattern-makers, by which the many circular forms required in that trade are made. The same tools are used on both kinds of turning, but

the processes are, in some respects, quite different. The cabinet turner is more concerned as to the beauty of outline and finish than with exact size, and uses methods that will accomplish these results. The pattern turner, on the other hand, **must have exactness** in size, the finish being a secondary matter. This being the case, whereas the cabinet turner actually cuts the **fibres** of the wood, the pattern turner uses what is called a **scraping** cut for most of his work.



FIG. 54.

A common form of turner's lathe is shown by Fig. 53. In the figure, A is the bed, B is the **head-stock**, C is the **tail-stock**, D is the **step-cone pulley** on which the belt runs that drives it and the **spindle** G, and with it the **driving or fork center**, which in turn drives the work. The fork center is driven into a tapered hole in the spindle, and is held by friction only. In the tail-stock is the **back center**, H. At F is the tool or hand rest. E is the tool-rest post.

Fig. 54 shows an enlarged view of the most common form of fork chuck. The **fork chuck** at the **left hand**, and the **back center** at the **right**, make up the common appliance for holding work in the lathe, when the turning is to be done **lengthwise** or **parallel** with the grain. For turning **plankwise** or across the grain, there are several kinds of **chucks** employed, the simplest being the **screw chucks**, shown at Fig. 55, in two forms. A

face-plate is shown in the center of Figs. 139 and 140. For small work, a chuck may be simply a **disk** of wood. Each chuck must have a face-plate fastened to it during its use. There are several different ways of **fastening work** to these chucks, generally determined by its




FIG. 55.




FIG. 56.

size and shape. It may be fastened with **screws** or **nails**, it may be **glued directly** to the chuck, and it may be **glued** to **paper** already glued to the chuck. When this last way is used, the work may be taken off without damaging it, because the paper will split. When it is glued directly to the chuck it will have to be cut off, so this way is not usually employed except for patterns of **thin cross section**, such as pulley rims, that can be easily cut through. Besides these plain chucks, several other forms are in use for special work, one of which is represented by Fig. 56, and is called a **cup chuck**. One of its uses is to hold a sphere in the lathe while it is being given the finishing touches.



Not many different forms of tools are required for pattern turning, but quite a number of different sizes of the same form are needed. The first to be noticed is the turner's gouge, shown in Fig. 57, and the **skew**, or **turning chisel**, illustrated in Fig. 58. These two, in their different sizes are the only tools used by the turner for **cutting** the fiber of the wood. All the others are



FIG. 57.



FIG. 58.

really **scraping** tools, and do not actually cut. The other tools most used for pattern turning are illustrated by Fig. 59. At A is shown a pair of the ordinary scrapers, the tool most used on flat and convex surfaces. At B is shown the round-nosed scraper, used for concave surfaces; several sizes of this are needed for a medium range of work. At C the ordinary parting tool is shown. This is a very useful tool for working wood plankwise; its special form gives **clearance** in whatever position it may cut the wood. The tool shown at D is also a very good tool for turning wood across the grain, especially if a large amount of wood is to be removed. This it will

do rapidly and easily. It is called a **diamond-point parting tool**. Fig. 60 shows a straight scraper, which is very useful for finishing large straight surfaces. It is made from a firmer chisel that is worn too short for its original use. Indeed, worn-out chisels of this type make first-class turner's scrapers. All the scraping




FIG. 59.

tools, except those shown at A and D, may be made of these and will serve their purpose admirably. The two noted above are sometimes needed longer than the others, and are better if made of heavier stock.

The art of turning can be learned by the student only in the same way that any other mechanical trade or craft is learned, i. e., by actually doing the work and performing the operations involved in the practice of that art. This being the case, only a few simple directions will be given here. These directions will be given by explaining the operations that must be performed in turning a cylinder. The first thing to be done is to saw out the stock square, with the sides about one-eighth inch larger than the diameter of the proposed cylinder. Next make a center mark on each end by drawing diagonal lines across it; at these points the lathe centers

are to enter. To set the work in the lathe, place one end against the driving center, or head center, and with a hammer or mallet strike the other end until the chuck has entered the wood far enough to revolve the wood against the tools; now while holding the right-hand end in the left hand, slide up the tail-stock with the right hand until its center touches the wood, and clamp it to the bed. With the handle or hand-wheel connected with the tail center, push the center into the right-hand



FIG. 60.

end far enough to make it secure. Adjust the tool rest so it will just clear the corner of the piece when revolving, and about a half inch above the **center** of the lathe. It is a good plan, before applying the power, to give the belt a pull with the hand to ensure that everything is clear.

The gouge is the first tool to be used on this kind of turning; the cutting done by it at this stage of the work is termed the **roughing cut**. The gouge is so held that a center line through the tool will be perpendicular to the axis of the work. The bevel of the cutting wedge should be held tangent to the proposed cylinder, and rolled on its side as indicated by Fig. 61 at A. The direction in which the tool is moving is indicated by the arrow in each case. In this position the angle of the cut will be about  $25^{\circ}$  to  $30^{\circ}$  with the axis of the cylinder, which is the best for this kind of turning. The gouge is

used by good turners for doing a very large proportion of the work on plain cylindrical and concave surfaces.

Plain cylindrical and convex surfaces are finished with the turning or skew chisel, the only other cutting




FIG. 61.

tool used by turners. Its use requires a great deal of skill on the part of the operator. On account of its shape it has a great tendency to rip or tear into the



FIG. 62.

work with its long corner. One reason for its so doing lies in the fact that it **cannot be laid flat** on the tool rest, but must be supported as shown in Fig. 62, and at the left in Fig. 63. This being the case, the keeping of the edge of the chisel in its proper position and angle with

the work depends entirely on the skill of the workman. This skill cannot be imparted, but some suggestions can be given that will aid the student in acquiring it. Do not let the chisel cut above the central point of the length of the cutting edge, that is at D, in Fig. 62. Retain a firm grip on the handle with the right hand.




FIG. 63.

The bevel of the skew, like that of the gouge, should be laid on the cylinder exactly tangent, and held so that the handle is perpendicular to the axis of the cylinder. As **one corner only** of the chisel touches the rest, it is very difficult to keep it in its correct position. If the bevel is exactly tangent, it will not cut; so it must be tipped enough to be tangent to a circle slightly smaller than the one already cut. This is best done by simply rolling the chisel with the hand until it cuts a shaving of the desired thickness. As a general rule, the cylinder should be cut almost to size with the gouge, leaving only a shaving or two to be removed by the chisel.

Pattern-makers do almost all this finishing with a scraper like the one shown in Fig. 60. The position of this tool for scraping plain cylindrical surfaces is, as

shown in Fig. 64, exactly on the diameter of the cylinder. The cutting of shoulders like those in Fig. 63, also the squaring of the ends of the cylinder, is done with a skew chisel. The chisel is held as there shown, that is, at a slightly larger angle than the one at which it is




FIG. 64.

sharpened; so no part of the **edge**, except the extreme point, touches the wood. The ends of nearly all plain cylindrical patterns have to be made **convex**. To make them so, the chisel may be held with the center line of its length perpendicular with the axis of the cylinder, while at the same time the edge of the chisel is perpendicular. For making other forms in the lathe, the tools shown in Fig. 59 are used. These are all scraping tools.

## SHARPENING LATHE TOOLS

The cutting wedges of the turning gouge and the turning chisel are sharpened in the same way as other cutting wedges. The wedges for soft wood, however, should be more acute than the bench chisel for general work. The wedge of turning chisels for use in soft wood may be ground to an angle of  $20^{\circ}$ , and must be kept very keen if good work is to be done. The side angle for the skew chisel should be about  $70^{\circ}$ . The **roughing gouge** should have a wedge of  $30^{\circ}$ . The scraping tools should have wedges of about  $45^{\circ}$ , and be ground on one side only, as shown in Fig. 64. As the cutting edge of the scraping wedge is on the side instead of on the end as in the cutting wedge, it requires a different treatment to secure the best results. After sharpening the chisel in the usual way, place it on the oilstone on its bevel, and, while holding it in that position, give it two or three strokes parallel with the back. This will give a continuous wire edge, which is just what is needed. Pushing the chisel back and forth in the usual way also produces a wire edge, but it is a serrated one, and therefore is quickly dulled.

## TOOLS FOR MEASURING TURNED WORK

The special tools for measuring turned work are shown at Figs. 65 and 66. The former is the outside caliper, the latter the inside caliper. The outside caliper is used for measuring the outside of round or cylindrical work, the inside caliper for measuring holes and cavities either cylindrical or of other forms. The outside caliper may be used when the work is revolving, provided it is



FIG. 65.



FIG. 66.

very nearly cylindrical. The inside caliper should **not** be applied to work that is revolving, as it is likely to be caught by the wood and jerked out of the hand. The common two-foot rule is used for measuring along a cylinder when the caliper would be unhandy. When a number of pieces, balusters for instance, are to be made alike, a special measuring device is usually made use of by turners. It consists of a light stick of wood with sharpened wire brads driven into it at certain points along its length, where the deeper cuts are to be made.



After the piece is turned down roughly to size, this scriber, as it is called, is laid on the tool rest in such a way that the sharpened nails will just touch the cylinder as it revolves, thus making a line around it where it is to be cut. This, of course, saves time, for the reason that the lines are all made at once, and the distances between them are measured at the same time for all the parts. It is not often, however, that the pattern-maker has any use for this device, as his work is seldom duplicated.

## CHAPTER V

### INTRODUCTION TO PATTERN-MAKING

A pattern may be defined as a model about which is to be formed a sand mold, in which a casting is to be made. It is usually of wood or metal, and often constructed in several parts so as to facilitate removal from the mold. In the foundry and machinery business the word **pattern** is understood to mean any **form** or **device** by the use of which a **mold** may be **made**. Pattern-making differs from all other woodwork in several ways. The product of the pattern shop becomes a part of the working outfit of another workman, viz., the molder. The joiner, in making a door, makes it just the size required by the drawing or specifications; the cabinet-maker does the same when called upon to make a table or other piece of furniture; the carpenter also follows this same idea when building a bridge. In all these, the ultimate object is reached when the work is complete. It is not so, however, with the pattern-maker; his product is only one step in arriving at the desired end, that end being the production of one or more castings in some kind of metal. Allowances must be made in constructing a pattern, that do not have to be considered in other woodwork; the principal of these allowances are for draft, shrinkage of the metal of the casting, and the machining of the casting where this is required. A pattern-maker must be a good woodworker, and able to work wood to accurate dimensions, both on the bench

and in the lathe, as pattern-making consists largely of fitting, joining, and making circular and other forms to correct size. This knowledge and ability are necessary to the pattern-maker, because a large majority of patterns are made of wood. The pattern-maker must also know something—and the more the better—of the practical work of the molder. This is necessary in order that he may be able to produce easily molded patterns. He should possess a good practical knowledge of the properties of metals, as, for instance, the contraction or shrinkage that these undergo in passing from the molten to the solid state, the strength of cast metals, and their relative rate of cooling. He should also thoroughly understand the principles of orthographic projection, so that, if it becomes necessary, as is frequently the case, he can make full-sized working drawings of the work in hand.

The production of ordinary metal castings, such as those of iron or brass, involves three distinct operations:—First, making the pattern; second, from this pattern a mold is made in sand or some other substance that is refractory enough to withstand the action of melted metal; third, the metal is melted and poured into this mold. Each of these operations require especial skill, and has given rise to a special trade, although the second and third, called respectively molding and founding, are often performed by the same person. These operations are sometimes so intricate, and admit of so much variety, that the above statements are only true in the main. Nevertheless, they hold good in general, and in consideration of this subject the pattern-maker may be understood to be a woodworker, the

molder as one who makes the mold, and the founder as the one who has charge of the furnace and the melting of metals.

In the first of these operations, that of the pattern-maker, there is needed a fine degree of skill in the arts of cabinet-making and wood-turning. Moreover, the two trades, the molder's and pattern-maker's, are so intimately connected that it is almost impossible to describe one without frequent reference to the other, and as a matter of fact there is almost as much to be learned of pattern-making in the foundry as in the pattern shop. So intimately connected are the operations of pattern-making and molding, that one of the chief qualifications of a good pattern-maker is the ability to form a rapid and reliable judgment as to the best of the several ways of molding a given pattern. As there is usually more than one way, it is advisable that the pattern-maker, if in any doubt, confer with the molder as to his preference in the matter; as the molder is responsible for the production of the casting, he should have the pattern as he wants it. As pattern-making, therefore, is to be regarded primarily from the molder's standpoint, and not from that of the wood-worker, the following matters are of first importance:—

(1) Patterns, when in use, being entirely enclosed in matrices of sand, provision must be made for pulling them out; this involves draft, or taper, which is a thinning down of certain parts, division into sections, and provision for loosening by rapping.

(2) Molding sand is always used damp, and patterns are subject to rough usage; consequently they must be made so as to resist any tendency to change

their form and size from the absorption of moisture from the damp sand, and they must be strongly constructed.

(3) Most metals shrink or contract in passing from the molten to the solid state; therefore, patterns must be made larger than the required casting to allow for this.

(4) Patterns may be entire or complete, exactly like the castings wanted; if, however, there are cavities to be formed in the casting, these hollow places will be represented by core prints. Moreover, the part the pattern-maker has to do with getting out a given casting may be the preparation of a sectional part or parts of a pattern from which only one part of the mold is made; the other part is made with a sweep, the boards for which are also prepared by the pattern-maker.

(5) The practice of pattern-making is largely governed by the requirements of the engineer; these requirements are that patterns must correspond to drawings in all dimensions, that all centers be correctly located, and that all necessary allowances be made both for machining and for the shrinkage of the metal of the casting.

It will thus be seen that the pattern-maker has very little in common with the carpenter, or indeed, with any other woodworker, except for the fact that he uses the same tools and processes. To understand, then, the fundamental principles of pattern-making, it is necessary to master the principles of molding, and much of its details as well, and to have a good working knowledge of modern machine shop practice. It is well to remember also that mere outside polish or finish on a

pattern does not count for much if such matters as correct construction and others already spoken of, are neglected.

In many trades, to become an expert in handling tools, is the most necessary requirement; but this is not the case in pattern-making, there being something far more important than cutting wood. In the construction of many patterns it is not so much a question of workmanship, as of knowledge. Certain patterns, for example, are very difficult to design, but after they are once made, they can be duplicated by any good woodworker. In fact, it often requires but little skill to construct the necessary core boxes, etc., that may be required to produce certain castings; on the other hand, there is much pattern-making that calls for fine workmanship. In any event, pattern-making is not merely cutting wood.

From what has been said, then, it will readily be appreciated that pattern-making is an important and responsible trade. For while the duty belongs to the draughtsman of preparing the design, yet the pattern-maker must be able so to interpret that design as to get the idea the draughtsman intended to convey. Moreover, he must look forward to the requirements of the molder; consequently, from the drawing alone he must be able to imagine the completed casting, and build a pattern that will produce it. As the medium by which the designer's ideas are put into the tangible form of a casting, the pattern-maker then has a two-fold responsibility. Another fact that adds to this is that there are so many different ways of molding. This gives a great field of study for the pattern-maker.

## CHAPTER VI

### MOLDING

A pattern-maker should know something about the operations of the molder, so that he can make a particular pattern of such a shape that it can be molded in the easiest way possible. This being the case, it is necessary to explain some of these operations. The form of pattern shown in Fig. 68 is what is known as a **parted pattern**. The molding operations that this form in-



FIG. 68.

volves are generally few and simple. As will be seen, the pattern is made in two parts, the **parting** or joint being along the axis of the cylinder. It is made in this way for the convenience of the molder. These two parts are held sideways in relation to each other by what are called **pattern pins**, represented by dotted lines, c and d. Parts marked A and B are core prints, and will not appear on the casting.

The appliance used by the molder in which to make the mold is called a **flask**, and is illustrated by Fig. 69. The upper part, A, is called the **cope**, the lower part, B, the **nowel** or **drag**; C is the **bottom board**; D, the **cope**

bars; E, the **guide pins**. Each flask is composed of at least these three main parts, viz., cope, nowel, and bottom board. Sometimes another part is introduced between the nowel and cope, called the **cheek**, or **middle part**. This is necessary when the casting is of such shape that its pattern cannot be taken from the mold




FIG. 69.

with the one parting obtained by the use of cope and nowel alone—that is, with the simple form of flask shown by Fig. 69. In addition to these parts a **molding board** is needed, which may be just like the bottom board. Only one molding board is required by one workman for any number of flasks of the same size.

The words **top** and **bottom** will be frequently used in writing of this flask. They refer to the flask when standing in what may be called its **normal position**—that is, as it stands when the mold is ready for the **melted metal to be poured in**. The relative position of these two parts is that the cope is always on top, the



nowel at the bottom. Each part is a box having neither top nor bottom, the sides generally being about 5 or 6 inches high, and rough inside.

In order that, after being separated, these may be put together again in the same relative position, they are provided with guide pins, E, Fig. 69, the pins proper being on the cope, and the lugs into which they fit being on the nowel. The cope is also provided with some form of handles. In Fig. 69 one of these is shown above E, being in this case a strip of wood about 1 inch square nailed across the end, directly above the guide pins. These handles are provided for the purpose of lifting the cope from the nowel at any time it becomes necessary to do so during the process of molding.

There are also cross bars fastened across the cope, D, Fig. 69, to assist in retaining the sand, which is held in place by friction only, the cope from necessity having no bottom. In all other respects cope and nowel are alike, except that in some cases one may be deeper than the other.

In using this appliance the molder first places the molding board on the sand floor of the foundry in an approximately level position, and so it will not rock. He then places the half of the pattern that is without pins on its flat side in the center of the molding board. The nowel, or drag, which is the lower half of the flask, is next placed on this board, bottom side up, with the half pattern in the middle of it. Next he sifts molding sand on to this board until the half pattern is covered to a depth of an inch or more. He now shovels in sand until the nowel is filled and heaped up; then, with an implement called a rammer, he rams it down

solid. The sand is now struck off even with the bottom of the nowel, some loose sand thrown on, and the bottom board placed on and rubbed around so as to make a solid bed for the body of sand in the nowel. Clamps are now put on so as to hold all together; the whole is turned over, the clamps removed, and the molding board lifted off. This completes one-half of the mold, or, as the molder expresses it, "the nowel has been rammed up and turned over." He now sleeks the surface with his trowel until it is even with the flat surface of the half pattern, which is exposed to view, surrounded by sand. He next scatters on some parting sand, which is a very dry sand, usually burnt sand that has been cleaned from castings already made. The purpose of this is to prevent the next body of sand from sticking. The other half of the pattern is now laid on, its position being determined by the pins already spoken of, and the corresponding holes in the other half of the pattern. The sprue pin or stick is now set up on the sand or parting just finished. This pin is a piece of wood, whose shape is the frustrum of a cone about 10 inches long; its purpose is to make a hole through the cope sand into which the melted metal may be poured. Sand is put into the cope in the same way as was done with the nowel; it is struck off even with the top, the sprue pin is pulled out, and the whole surface brushed over so as to remove all loose sand. The cope is lifted off carefully, and set to one side. Both halves of the mold now appear exactly alike, except that the cope has the sprue hole running through it.

The two halves of the pattern must now be drawn

or **pulled out**. This the molder proceeds to do in the following manner: If the pattern is provided with lifting plates, as all standard patterns should be, he introduces the end of the lifting-screw into the hole provided for it in the lifting plate, and turns it in so that it is solid. If there are no lifting plates, he drives what he calls a draw-spike into one of the halves. Then, with a mallet, a small hammer, or perhaps a sprue pin, he raps on all sides of the lifting-screw or draw-spike, so as to loosen the pattern. This operation, called **rapping the pattern**, enlarges the mold so that the pattern may be pulled or drawn out. This he now does, very slowly and carefully, gently rapping the pattern until it is entirely free from the mold. This is done to both halves. A channel is now cut in the sand of the nowel from the spot on the parting where the sprue pin was set, to the mold or cavity left by removing the pattern. Thus is provided a passage through which the melted metal may run and fill the mold. This channel is called the **gate**. The mold is now ready to have the core set in. After the core is set, the cope is put back into its original or normal position, which is determined by the guide pins; the whole is then clamped together, and set in position for pouring. As stated at the beginning, this process applies **only** to parted patterns. This same flask may be used in several different ways, the particular way being determined by the **shape** and **size** of the pattern. For some shapes of patterns it is necessary to use three boxes or **parts**; this is usually called a **three-part flask**, thereby meaning that the mold is composed of three distinct bodies of sand. The central part of a three-

part flask is called the **cheek**. The cheek has on it a set of guide pins the same as the cope, and also a set of lugs like those on the nowel, on the opposite edge. It is made in this way so that any cope or nowel of the same size may be used with it.

These simple explanations will be enough to give the student of pattern-making a general idea as to the use of patterns in the foundry. Of course there are many details to be observed and carried out in the production of castings that are not mentioned above, but as these more particularly concern the molder than the pattern-maker, they will not be noticed here.

## CHAPTER VII

### GENERAL PRINCIPLES

In building foundry patterns several ideas must be kept in mind, either consciously or unconsciously. These are four in number, or (when we have no source of information as to what is wanted, except a drawing of the required casting), there may be five, as follows:

(1) What may be called the **designer's idea**; (2) the way in which the pattern is to be **pulled** from the sand; (3) the **draft**, or taper, which is a thinning down of certain parts of the pattern in order to **facilitate** its **removal** from the mold or sand; (4) the **shrinkage** of the metal of the proposed casting, while passing from the molten to the solid state; and (5) the **machining** or **finishing** of the casting after it is made or cast.

An experienced pattern-maker may not be conscious that he has in mind any one of these ideas, because he uses them so frequently that he does so without thinking especially of them; in other words, they become second nature to him. It is these last four ideas, among others, that separate this trade from all other wood-working trades and connect it with the engineering profession, for there is not one of them that has even to be thought of by those working at any other of the wood-working trades. Before we explain these ideas in detail, it will be best to have them arranged before the mind in such a way that they may be easily remembered, and in the order of their use and import-

ance. For convenience, then, we will put them in a vertical column, thus:—

1. **Designer's idea.**
2. **Way to be drawn from the mold.**
3. **Draft.**
4. **Shrinkage of metal.**
5. **Machining.**

Besides these five ideas, the last three of which are called **allowances**, there are two others that sometimes have to be considered, viz., for **shake** and for **warp**.

The first two of these five ideas are purely abstract. If it is desired to make a pattern from a drawing only, that is, if there is no other means of knowing what is wanted, then it will be necessary for the one building it to form as nearly as possible the same mental picture that the designer had in mind when making the drawing. This may be called the **designer's idea**, and to some extent, at least, must be realized before much can be done towards building the pattern. After having thus formed in mind the general shape and approximate size of the required pattern, it should be decided which way it shall be **drawn** from the **mold**. This **must** be decided before very much can be done towards building the pattern, so that the **draft** may be made in the right direction, which is a very important matter.

The other three points that were mentioned are sometimes spoken of as the **allowances** to be made in pattern-making. They are really **additions** made to the size of the pattern in some one direction, or, as in the case of shrinkage, in all directions. The first of these, and in some respects the most important, is what is technically termed **draft**. This is a thinning down of

certain parts of the pattern; that is, the **vertical** sides of the pattern are tapered, and it is sometimes spoken of as **the taper**.

The amount of draft to be allowed is governed by the case in hand, some patterns requiring more than others. The usual amount is  $\frac{1}{8}$  inch for 1 foot in height; this is generally enough for small and comparatively plain work, but for complicated work it is not enough. No hard-and-fast rule, however, can be given for this allowance, or indeed for any work in pattern-




FIG. 70.

making. What is nearest to a general rule may be stated thus: Give the pattern as much draft up to  $\frac{1}{4}$  inch per foot in height as will not **interfere** with the **design**. Whatever amount is allowed should be added to the size of the casting as given in the drawing. For small and plain work  $\frac{1}{16}$  inch will be enough, but if the pattern is at all complicated,  $\frac{1}{4}$  inch will not be too much. Of course, the requirements of the molder have to be considered, and if he were asked about it, he would always say, give it the larger amount. To make this more plain, we will suppose that a pattern is

wanted from which to make a mold for the casting represented by Fig. 70.

Now, applying the above principle, we should make the top longer and wider than the size given by  $\frac{1}{4}$  inch, so that the top of the pattern would be  $8\frac{1}{4}$  inches long and  $6\frac{1}{4}$  inches wide. This addition, or allowance, is shown by the dotted lines. In this case the pattern would be drawn out of the mold in the direction of the arrow. In practice it would not be necessary to allow so much draft on as plain a pattern as this, but we use it as an illustration of what is meant by the term draft. **All vertical** sides of the pattern, whatever its shape, **must have some taper** in order that the molder may get it out of the mold without breaking the mold. If no draft is allowed, the molder has to rap the pattern so much that the mold will be distorted and the casting will not be like the pattern.

The next important principle to be observed, especially when the casting is required to be exact in size, is that relating to **shrinkage**. Whenever this word is used in connection with pattern-making, it always means the shrinkage or contraction of the **metal** of which the **casting** is made. An iron, brass, or steel casting is always smaller than the mold in which it was made, and this is true also of castings made of any of the other metals in common use. This is due to the **shrinkage** of the **metal** when cooling. The amount of the shrinkage varies in the different metals, and also in the same metal under varying conditions. Brass will shrink more than iron, and iron that is very hot when it is poured into the mold, will shrink more than iron that is comparatively cool when poured. The



size and the shape of the casting also have much to do with the amount of shrinkage. An iron that will shrink  $\frac{1}{8}$  inch to the foot in light work, will shrink only  $\frac{1}{10}$  inch, or less, in large work. For instance, in casting large box or cylindrical-shaped castings,  $\frac{1}{8}$  inch per foot is usually enough to allow for this shrinkage in




FIG. 71.

the diameter, but  $\frac{1}{8}$  inch will not be too much in the length. The reason for this difference is due to the fact that the castings are practically unrestrained in their length, and are comparatively free to shrink in this direction, while in the diameter they are restricted by the cores and internal parts of the mold. The amount of allowance usually made in common practice is  **$\frac{1}{8}$  inch per foot**, measured in all directions. But since the coefficient of shrinkage is different for different metals, this is only approximate. The following allowances for the different metals are made in the pattern when it is surely known just what metal the casting is to be made of, as, of course, is usually the case. One good way to remember these is to arrange the figures that represent these amounts in a group like Fig. 71.

For iron, then, this allowance is  $1/10$  inch; for brass,  $3/16$  inch; aluminum,  $1/4$  inch, and for steel,  $1/4$  inch; the general amount, which is in the center of the group, is  $1/8$  inch. It must not be understood by this that these metals will always, and under all conditions, shrink just these amounts; for, as has already been mentioned in the case of iron, the amount of shrinkage varies somewhat under varying conditions. For the use of pattern-makers, scales or rules are made. The one most commonly used provides for an allowance of  $1/8$  inch per foot; that is, the rule is made  $1/8$  inch longer than the standard foot rule, and each "inch" on the rule is correspondingly longer than the standard inch. The use of one of these scales, however, does not solve all the problems in shrinkage that may arise in practice. For instance, if it is required to make a pattern for a casting 8 feet long, and an allowance of  $1/8$  inch per foot is made (which would be the case if the above mentioned scale was used), the casting would be longer than required by the difference between  $1/8$  inch and  $1/10$  inch taken eight times, viz.,  $2/10$  inch, or nearly  $1/4$  inch. In such a case, then, it would be better to make an allowance of  $1/10$  inch per foot (the approximate shrinkage of iron). Then the casting would be more nearly the required size. Scales or rules can be bought at dealers, graduated for the other shrinkages above mentioned.

It has been a mooted question as to just when this shrinkage or contraction takes place in the casting, but it is generally conceded now that it takes place in passing from the plastic condition to the solid state. All metals, in passing from the liquid to the solid state,

suffer **expansion** when in the plastic condition. It is this feature in the transition that enables metals to take and retain the impressions of the molds with such fidelity. Allowance for shrinkage is not regarded on patterns that measure **6 inches** or **less** in any one direction, as the rapping of the pattern will usually make up for any shrinkage that may take place. Patterns that are **4 inches** or **less** in size, are made slightly smaller than the desired size of the casting. This is called an allowance for **shake**. It is not regarded unless it is necessary that the casting be exact in size. Patterns between 6 and 4 inches may be made without regarding either shrink or shake.

In building machinery it is often necessary to fit two castings together. Wherever this is done, the two surfaces that come into direct contact are usually machined in some way in order to obtain a smooth, clean surface of metal. This is the case, whether the two surfaces are to slide or rotate on each other, or whether one is simply bolted to the other, and is called an allowance for **machining** or **finish**. When the words "machining" or "finish" are used in connection with pattern-making they always refer to work to be done on a casting. A part of a pattern that represents a surface of this kind on the casting, must be made larger. The amount of this allowance is generally  $1/8$  inch, measured perpendicular to the surface to be machined or finished. If the surface is simply to be machined to fit another surface, and the work is comparatively small, this will be enough. But if it is required to have a very nice finish, free from all sand holes, or if the work is large, it might not be enough;

in some cases it might be necessary to make it twice the amount, or  $1/4$  inch on each surface. Moreover, as the casting increases in size, its irregularities also increase, so that a larger amount must be allowed. In the case of large work, such as engine beds, the allowance is frequently made from  $3/4$  to 1 inch. A large allowance is especially necessary on very irregular and new work, as the amount of distortion caused by the strains set up in the casting by shrinkage is very uncertain. Large steel castings are usually very rough, and also become more or less distorted in cooling and annealing, so that it is necessary to allow more on this account. Of course, the exact amount must be determined by the circumstances of any given casting, but there should be enough so that in taking the first cut, the tool used may get **beneath** the **sandy scale** that is always present on a casting, and still leave enough for a second cut at least, and a third or finishing cut if necessary. It, therefore, cannot be much less than  $1/8$  inch.

There is one other allowance to be mentioned that is not usually called for in making machinery patterns, but is frequently in making what are called architectural patterns. Some castings, because of their varying thickness, or because of one surface being more exposed than another, therefore cool more rapidly, warp or become distorted in the mold when cooling. To overcome this, patterns for castings of shapes that are known thus to warp, are made of such a shape that in cooling they will assume the desired shape. This change in shape of patterns is called an allowance for **warp**.

## CHAPTER VIII

### MATERIALS

Wood is the material used for a large majority of patterns. At first thought it would seem that wood is a particularly unsuitable material to be used in matrices of damp sand, and to be subject to such rough usage as the ramming and rapping of a pattern necessarily involves, but there are several reasons why wood is used. The first that may be mentioned is that it is easily worked and altered. Secondly, it is light and portable. Furthermore, by exercising due care in construction, its disadvantages may in a degree be overcome. The pattern-maker, of course, meets the same difficulties with which other woodworkers have to contend, and such as interfere with the durability of patterns. The chief one among these is due to the tendency of wood to shrink and swell, which causes warping and change in form and size. This cannot be wholly overcome, but by arranging the different pieces in a given pattern with due regard for this natural tendency, it may, to a degree, be counteracted. To prevent warping, it is necessary to know the effect this tendency has upon the individual board; and this may be determined, if the position of the board in the log is known, which may be determined by examining the end. If a board is cut from the middle of, and directly through the diameter of the log, it is not very likely to warp; but if a board is cut from a position midway between the

heart and the outside of the log, it is sure to do so, for it will assume a curved outline between the edges, the heart side always becoming convex. This is caused by the more rapid drying of the board on the sap side. For as the board is cut through the concentric cylindrical layers of which the log is composed, the outer side of the board contains more exposed fibre ends and more open pores than the heart side. Consequently, the sap side of a board gives off the moisture it contains more rapidly; it will also absorb moisture more rapidly. In view of this fact, the sap side of any board should be placed where it will be the least likely to be exposed to any change in atmospheric conditions. That is, whenever it is possible, this side of the board should be placed on the inside of any pattern-work.

What is known as **quarter-sawn** lumber is the best for pattern-work and all woodwork, because it is not so likely to warp as is the regular, or bastard-sawn. Quarter-sawn lumber is lumber that is sawn approximately parallel with the medullary ray. The trunk of a tree is made up of concentric cylindrical layers, bound together with radial fibres, which are known as medullary rays. It is the exposure of these rays that gives to quartered oak the beauty that is so much prized. However, quartering is a very wasteful way of sawing lumber, and involves an extra cost. But for pattern work that must be made thin, it pays to use quarter-sawn lumber, even if it does cost more.

Another very important factor in connection with lumber for patterns is, that it should be thoroughly seasoned before being used, if possible, by what is known as the **natural** or **air-seasoning** process. The

seasoning should continue for at least **two years**, in order that the natural gums of the wood may be fixed; that the rapid drying of the kiln will not drive them out, and in that way make the wood more porous. Lumber intended for pattern work, if allowed to remain in a shed with a waterproof roof for two years, will give better results than lumber exposed to all sorts of weather for six months, and then placed in a dry kiln to finish the process. For 1-inch lumber two years is enough; thicker planks will, of course, need more time, say four years for 2-inch. However, lumber cannot be so thoroughly seasoned as to give entire permanence of form and durability to patterns made from it.

Besides being thoroughly seasoned, lumber for patterns should be **straight, and even in grain**, not too **hard** to be **easily** worked, yet not so **soft** as to be **unduly injured** by the rough usage patterns must necessarily undergo in the foundry. There is no wood that fulfills these conditions better than what is known as White Pine (*Pinus Strobus*), sometimes called "cork pine," because of the cork-like appearance of the bark. This wood, when thoroughly seasoned, will retain its shape very admirably under the excessive atmospheric changes that patterns have to undergo from pattern-shop to foundry, and from foundry to the storage loft. When first cost need not be considered, and it should not be in the case of small standard patterns, Mahogany, what is known in the market as Honduras M., is the best wood for all patterns; it is very even and straight in the grain, not so hard but that it can be easily worked, and retains its form and size to a remark-

able degree. One thing to be mentioned in this connection is the arranging or combining the several pieces of which a pattern is made in such a way that any shrinking or swelling of the wood shall not change the shape or size of the pattern. This is an important matter in some classes of work, and should have the careful consideration of the pattern-maker, especially in the case of standard patterns. If this is done it will add considerably to the durability of a pattern.

There is one principle it is well to observe in combining the several pieces of wood in a pattern, and that is to have the grain of the wood run in the same general direction, or as nearly so as possible, so that, as it shrinks or swells, it will do so in the same direction, and therefore will not distort the pattern.

Special patterns are often made of **brass, iron, white metal or aluminum**. These metals would be used in light or curved work, and also when a large number of castings of the same size and shape are wanted. With few exceptions, however, original patterns are made of wood. Statuary and other ornamental work is usually modeled in wax or clay, which serves as the pattern. When it is proposed to use a metal pattern for the production of castings, the original pattern is made of wood and is called a **master pattern or double-shrinkage pattern**. This is made with a **double-shrinkage** allowance, so that a casting made from it will still be large enough for the pattern from which to make the castings wanted. Patterns made of wood must be varnished or they will soon go to pieces.



### Sandpaper.

In pattern work sandpaper should be used with discretion. The pattern should be formed as nearly to shape and size and finished as accurately as possible with the cutting tools before sandpaper is used. Under no circumstances should sandpaper be used for cutting down or removing any considerable amount of stock, or for doing anything that can be done with tools. Otherwise the draft and the accuracy may be impaired. Sandpaper, as its name implies, is made of sharp sand (quartz or garnet) glued on paper. It is graded according to the grains of sand, and numbered accordingly. The grades most useful to the pattern-maker are Nos. 0 to 2. No. 1½ is best for use directly on the wood, and No. 1 for the varnished surface. Ordinarily, sandpaper should be rubbed across the grain of the wood. In the last two or three years, what are called pattern-grinding or sanding machines have been introduced to the trade to take the place, in some kinds of work, of sandpapering by hand, and they accomplish the work much better and more rapidly. Any kind of abrasive that can be fastened to the machine may be used.

### Glue.

In pattern-making, as in most of the woodworking trades, glue is depended on for adhesive fastening. For fastening leather fillets, shellac varnish is sometimes used. Since much depends on the character of the glue used, it should be of the best. There are many kinds and qualities of glue on the market, including liquid, pulverized or ground, and sheet. The liquid glue is

always ready for use and is very good for small work. The sheet or flake form, ground, dissolved and applied hot is the best for general use. Animal glue comes in thin sheets; it is the best, and likewise the most expensive. Of late years the large manufacturers of glue have taken up the practice of grinding these sheets, which makes it much handier for use. However, this enables dishonest dealers to grind the cheaper kinds of glue and pass them off as the best, for when ground it requires an expert to tell the difference, but when it is cooked, the odor given off will generally indicate its quality. As a rule, the best quality of glue is of an amber color, and the sheets rather thin. Whichever kind (excepting of course the liquid) is used, it should be soaked in cold water for a short time before cooking; only a small quantity should be prepared unless the shop is provided with a steam glue heater that is kept hot. Glue is much stronger if used while fresh, as frequent heating and cooling destroys its strength. To obtain the best and strongest joint, the wood should be slightly warmed to, say, from 90 to 120 degrees, and the glue applied as hot as possible, and the work quickly clamped. As a rule, the harder the glue the better it will resist moisture. A glue that will resist moisture quite effectively may be made by adding a small quantity of raw linseed oil to glue while hot. When it is necessary to glue two pieces of wood together so that the joint is on the end grain, the end should first be given a coat of thin glue, which should be allowed to dry before applying the glue for the joint. This is called **sizing** the joint. Plenty of time should be given the joint to dry—ten to twelve hours, according to the size of the work, will

usually be enough if in a warm and dry shop or room. Too much care cannot be exercised in the use of glue for pattern work; indeed, it is not advisable to use it at all when nails or screws will answer the purpose. However, in complicated patterns glue, in addition to nails and screws, will add to the rigidity of the work, which is very desirable; and there are some patterns that cannot be made without it.

### Varnish.

All wooden patterns should be covered with some kind of protective coating so as to prevent as much as possible the absorption of moisture from the damp sand of the mold, for this is very injurious to all wood-work. The protective coating should be of such a nature as to be unaffected by **moisture** and also to **insure a hard, smooth surface** that will "draw" easily from the mold.

In practice there are two general classes of varnishes used, shellac and copal. The first, which is the kind most generally employed, is composed of common gum shellac cut with alcohol and colored, if so wanted, with some kind of coloring ingredient. The second comprises the better grades of copal varnishes used by finishers. This may also be colored. By changing the color of the varnish employed, it is possible to distinguish between core prints and the body of the pattern, and also between patterns for castings of different metals, such as brass, iron and steel.

For shellac varnish a good grade of gum should be used, as the cheaper grades will not stand up to the work. This is usually called **yellow varnish**. **Black**

varnish is made by adding lampblack; a good quality of lampblack should be used, one that is free from grit. **Red** varnish is made by adding some red powder, usually Indian red, or vermilion (Chinese is best) to the yellow varnish. The use of these in varnish seems to give it a better body and greater durability. Copal varnish, however, is still more durable, and if time (about three days) can be given it to dry, it is much the better and will outlast several coats of shellac varnish.

### Beeswax

Beeswax is used for making small fillets, and filling small holes, such as nail holes, etc., and any other slight defect in either material or workmanship. It may also be employed for making a slight change in the form of a pattern that is not much used. It is not good practice, however, to use it in this way on standard patterns, as it is very liable to melt and run out in the storage loft during warm weather.

Wax is sometimes used for coating iron patterns to prevent them from rusting. To cover iron patterns with wax, they should first be made as warm as they can be handled, then the wax should be spread on them as evenly as possible and brushed over with a soft brush.

### Nails.

For pattern work, what are known as wire brads are the best nails. They can be driven almost anywhere in the wood without splitting it. They may be had of all lengths from one-half inch to three inches and of different sizes of wire. However, owing to the neces-

sity of rapping patterns when drawing them from the mold, it is always best to use screws when fastening the different parts of a pattern together. They are much better than nails on account of the clamping effect they give to the pieces to be joined. This is a very desirable effect in the case of standard patterns. Another reason why screws are much better than nails for this purpose is that when it is necessary to change or repair a pattern, screws can be taken out without tearing the wood of the pattern, and if needed, can be replaced exactly in the same place. Screws are also handy for temporarily securing loose parts of a pattern, and for this use are much superior to nails or pins. When screws are to be used for fastening two pieces of wood together, holes as near the size of shank of the screw as possible should be bored through the upper piece. If this is not done the screw will cut a thread in both pieces, thus hindering the clamping effect that is otherwise obtained by the use of screws for this purpose.

As is well known to most woodworkers, end grain wood, especially soft wood, does not hold a screw very securely, unless some special method is used. One of the best ways of putting screws into end grain is to bore a hole of a size as near as can be to the size of the solid part of the screw at the bottom of the thread. The thread of the screw will then cut its way into the wood without disturbing the fiber and thus the full shearing strength of the wood will serve to hold the strain put upon the screw. The hold of a screw in end wood may be increased by taking it out, placing a small amount of glue in the hole, and putting the screw back in at

once while the glue is soft. It is sometimes necessary to take out and reinsert screws in end wood, repeatedly,—for instance, when pattern work has to be taken apart for convenience in molding. In such cases, simply screwing them into the end wood should not be depended upon, as they get loose and do not hold. A good way to overcome this difficulty is illustrated by Fig. 72. It is to bore a hole at right angles to the direction of the screw in such a position that the screw shall pass through it; fill this hole with a hardwood




FIG. 72

plug, bore a hole of suitable size for the screw and insert the screw. If now the screw from frequent taking out and screwing in becomes loose, the plug may be taken out and another put in its place. As noted elsewhere, screws make a much stronger fastening than nails and should always be employed in pattern work that is to be much used, as in the case of a standard pattern.

## CHAPTER IX

### FILLETS

Sharp corners on a casting, whether inside or outside, generally detract greatly from its appearance, and also, in the case of internal angles especially, injure its strength. This being the case, sharp corners must be avoided in the pattern, as the casting will be of the same shape as the pattern. The weakness due to sharp




FIG. 73.




FIG. 74.

corners, especially in the case of internal angles, is caused by the way iron acts in cooling, or in passing from the molten to the solid state. There are always more or less strains set up in a casting by the shrinkage or contraction that takes place at that time. As the iron hardens the crystals seem to arrange themselves in such a manner that their lines of strength are perpendicular to the faces of the casting. For instance, in a casting of the general shape shown by Fig. 73 these lines arrange themselves as shown by the short lines

drawn perpendicular to each face and thus leave the space, A, open or honeycombed; consequently the casting will be very weak through the line, B, C, and when a strain is put upon it, it will be likely to break. In some shapes of castings these strains caused by shrinkage will of themselves crack the casting at this point and at all similar sharp internal angles. If the above casting is made with a **fillet**, or rounded-in-angle, this is not so likely to be the case, and if it is made as represented by Fig. 74 it will be just as strong at that point as at any other. For, as will be noticed, there is no place for this irregular crystallization to take place. In view of these well-known facts, **all** internal angles should be thus rounded in or "filleted" on the pattern. When fillets are used on patterns for the purpose of strengthening the casting **only**, care must be taken not to make them of too large radius, as this will be very liable to counteract the very effect desired by making the casting so thick at that point that the metal will be drawn away from that part by shrinkage and so make the casting porous and weak. Some large flywheels have burst because of this. Therefore, in large work the best practice is to make the fillets comparatively smaller than they are made in small or light work. There can be no arbitrary rule given for the radius of the curve of a fillet. If the two webs or other parts to be connected by a fillet are approximately the same thickness, then a radius equal to one-half of that thickness will be very effective in adding strength to the casting and will at the same time please the molder.

In molding a pattern of the general shape of Fig. 75 that for some reason has to be pulled or drawn from the



mold in the direction of the arrow, a very sharp corner of sand will be left at the point C. As the pattern is pulled up past it, a slight movement of the pattern side-wise would break it; then as soon as the pattern became clear of the mold, the sand would fall down into it, thus




FIG. 75.

making what the molder would call a dirty mold. It would cause him some trouble to remove this sand from the mold, and it must be all cleaned out, for otherwise it would surely make a poor spot on the casting and might render it unfit for the use to which it was intended to be put. This applies to all **internal** angles in patterns. Therefore, for the molder's benefit, as well as to strengthen the casting, it is best to "round in" any internal angles. Fillets may be made of wood, wax or leather. The last is undoubtedly the best; it also is the most expensive, at least in its first cost. Wood is generally used for straight work, the best practice being to fit and glue a piece of wood of the right size into the angle and allow it to dry before cutting the required curve. By working the curve after it is glued in place, the tendency of thin edges of wood

to curl when made wet, which of course is done in the gluing, is entirely overcome. There is no objection to using wood for this purpose if the wood that is used is straight in grain, and if the grain of the wood of which the fillet is made lies in the same direction as the grain of the wood composing the part of the pattern to which it is glued. Leather is the best material of which to make fillets, since it is elastic enough to come and go with the wood as it shrinks and swells. It is as permanent as the pattern itself, gives a very smooth finish, and is easily applied. Wax is not very good except for very small fillets or for temporary patterns. It should not be used for fillets on standard pattern work as it is likely to melt and run out when exposed to summer heat in the storage loft.

In making and applying fillets of wood, the process is something like this: First, a piece of wood of the proper length is ripped out square, so that each side is equal to the radius of the curve of the proposed fillet. One corner is fitted to the angle proposed to be filleted; it is better if this does not exactly fit clear into the angle—that is, the fillet piece may be a little loose at the apex of the angle, but should fit tightly on the other two sides of the triangle. When this is properly fitted the remaining or outside angle may be planed off with the jack-plane so as to make a triangular-shaped piece, Fig. 76. The third side, the one last made, is a good place in which to drive brads for holding the piece in place while the glue is drying. The brads should be placed about four inches apart. When a sufficient number of brads have been started, the glue may be applied to the piece, the piece set into the angle and the

brads driven in as far as can be, while still leaving the heads protruding, so that they may be pulled out when the glue is dry. When the glue is thoroughly dry the nails may be pulled out, and the required curve cut or worked with gouge and sandpaper, making it as nearly **tangent** as possible to the two sides it connects.




FIG. 76.

In order to apply leather fillets successfully, a tool known as a "filleting tool" is needed. It consists of a sphere of iron, or, still better, of brass, fastened to a short rod somewhat smaller than the sphere. The radius of the sphere should be equal to that of the fillet. After the leather fillet is cut to the required length, moderately thick, clean glue, not too hot, is applied; the leather is placed in the angle, and the filleting tool is run along the angle, pressing the leather firmly into place. The pressing should be done heavily enough to squeeze out all surplus glue, which should be cleaned off **at once** with a piece of cloth or waste, dampened with hot water; then the surface thus made wet should be wiped as dry as possible with a dry piece of the same material. In order to secure the best re-

sults in performing this operation, the filleting tool should be hot. This may best be accomplished by putting the tool into hot water for a few seconds.

Wax fillets are put in in the following manner: Some wax is softened by heat and rolled into a small cylinder, the diameter of which is governed by the size of the fillet. It is then laid in the angle. The filleting tool before mentioned is warmed enough to soften the wax, and the cylinder is pressed into the angle. The wax, being softened, conforms to the shape of the tool, which, as it is passed along, leaves a circular surface tangent to the two sides of the angle. The surplus wax should be cleaned off up to the line made by the tool. This makes a very nice job, and is a good way of making fillets for patterns that are not to be much used. There are on the market small presses that turn out cylinders of wax for making wax fillets. They are so arranged that different sizes of cylinders are made for different sizes of fillets. These small cylinders of wax are also used for venting cores and molds. These machines save considerable time and trouble in this kind of work, and also do it more satisfactorily.

## CHAPTER X

### CORES

When castings are to be made with holes through them, or with internal cavities, a projecting body of sand must either be made in the mold at the same time as the other parts of the mold are made, or else be introduced into the mold after the pattern is removed or pulled out. These projecting bodies of sand are




FIG. 77.

called **cores**. When the pattern can be withdrawn from the mold and leave a core as a part of the mold, it is said to **leave its own core**. This is illustrated by Fig. 77. This illustration represents a mold with the pattern **b** removed, thus leaving the core **a** projecting above the lower surface of the mold. When the cope is closed the cope sand will, of course, touch the upper surface of this core; when the mold is filled with melted metal, it cannot flow into the space occupied by the

core. The result is that the casting will have a hole through it the shape of the core *a*. Where patterns cannot be so made, and molded with the ordinary appliances of the foundry, to form their own cores, there is added to the pattern an attachment or projection that forms a mold or recess in the sand, into which a separate core may be placed. These attachments are called **core-prints**.

Cores that are made separate from the mold are usually what are called **dry-sand** cores, although **green-sand** cores are sometimes made in the same way. A simple form of pattern for a mold with a dry-sand core is represented by Fig. 68, parts A and B being core-prints.

A dry-sand core is made in a separate device called a **core-box**. In the case of a symmetrical core, a core-box is made only for a small portion of it. For a cylindrical core only a half box need be made, two cores from such a box being pasted together, thus forming a complete core. This same principle may be used in the case of very large work. A symmetrical mold, like one for a fly-wheel, may be built up almost entirely with cores.

Core-boxes require as great care in their manufacture as patterns, and as much thought must be given to their shape, durability and finish. The shape of a pattern is nearly like the required casting; but the inside of the core-box, which is, of course, the necessary part, is just the reverse, resembling more nearly the shape of the mold. When cores are made in boxes and inserted in the mold, it is necessary that they be supported in such a way that there will be no chance for a change

of position by the action and weight of the molten metal as it is being poured into the mold. To give this support, special recesses are made in the mold to receive them. These recesses are made by the core-prints previously mentioned. The core should exactly fill the recesses left by the core-prints, and this part of the core should be large enough to support the core




FIG. 79.

properly in place, so that the sand of the mold will not be crushed out of shape by the weight of the core, nor by the action of the metal while being poured into the mold.

Core-prints should be given **more taper** than the pattern itself, so that the work of withdrawing the pattern from the mold may not be **unduly increased** by their presence, and also that the core may be the more easily adjusted to its proper position. In the case of plain cylindrical cores, whose length does not exceed five times their diameter, or of such as may be stood on end while drying, a full box may be constructed and the cores made whole. This, of course, saves the time

of the core-maker, as he does not have to cement the two halves together. A core made in this way, with its box, or mold, is represented by Fig. 79. As it is necessary to vent cores, boxes that form a complete core should be provided with some means of doing it. The most common way is to bore holes through the sides of the box that form the ends of the prints of the core, so that rods (large wires) may be placed in the core while being made. These rods are, of course, pulled out before the core is taken from the box. In making all core-boxes and core-prints, care should be taken that the part of the box **corresponding** to the **print** on the pattern should be exactly the same **size** and **shape** as that **print**, so that when the core is set into the mold it will **exactly** fit.

All core-prints should be of ample size, so that their **impression** will hold the cores in their place, and so that the weight of the core and the weight and action of the melted metal will not change their position. It is well to remember that the material that must do this holding is only loam, or, as it is technically called, sand. It therefore requires a comparatively large surface to make it secure against the weight and action of melted metal during the process of pouring it into the mold. On account of the varying shapes and conditions there can be no exact rule given for the sizes of these prints, that will cover all cases. The **length** of the core-prints for a plain cylindrical **horizontal** core should approximate its **diameter**, and its shape should be **cylindrical**. For a **vertical** core of this same general shape, the print should be the **frustum of a cone**, with the large end next the pattern; the height should be



1 inch, and the diameter of the small end  $1\frac{1}{2}$  inch less than the large end.

In core work that requires prints of other shapes than those mentioned above—that is, where the opening into or through the casting is not round, then the prints should correspond in shape.




FIG. 80.

The making of core-prints properly located and of correct size and shape is a very important part of the pattern-maker's art, especially so from the molder's standpoint. Prints that do not show the exact position of the core may be very misleading and may result in the loss of the casting. One form of core where this mistake might easily occur and not be noticed until after the casting is made is illustrated by Fig. 80. The figure represents a casting that requires a cylindrical horizontal core with a part enlarged to make the cavity, A, which, it will be noticed, is not in the center of the

length of the casting. In this case, if both core prints are made of the same size, the molder will be quite likely to set the core wrong end to. The molder would not be altogether to blame for this mistake, as he generally does not have anything to guide him in this work except the pattern and core-box furnished by the pattern-maker. But if one core-print is made larger than the other, then it will be impossible for him to set it incorrectly without deliberately cutting the mold. In all core work, therefore, the prints should be of such size and shape that it will be impossible to set the core into the mold in any other than the correct position. For cylindrical cores, this is the best method, and is sure to accomplish the desired result. Sometimes it is required that a cylindrical core should lie in the mold in a certain position with regard to its circumference. In that case it would be necessary to change the shape of at least one of the prints, making one or both square so that the core cannot be set wrong or revolve after being set.

Some prints for horizontal cores are not made long enough, consequently the metal when poured into the mold will, by its own static pressure, raise or displace the core and make the casting thinner on the cope side because of this movement.

It is advisable to make the prints of cylindrical horizontal cores about **equal in length to the diameter** of the core. This may seem excessive and in some cases it may be, but it had better be too long than too short. When it becomes necessary to make them shorter than this on account of the size of the flask to be used, or of the core oven, and the casting is quite heavy, it is good

practice to imbed a plate of iron in the mold for the core to rest on; thus the weight of the core will be distributed over a larger area of sand than the core-print alone would afford.

A great many castings are lost because the lower print of vertical cores are made nearly **parallel**, or with the ordinary pattern draft. The probable cause of this is that the core does not go down to the bottom of the mold since the sand is cut down by the core on setting; so, when the cope is closed, being too long, it breaks the mold around the print of the core, allowing metal to flow into the vent and thereby causing the casting to "blow." This may be overcome to a large degree by tapering the lower print as is usually done in the case of the upper one. If this is attended to there can be no trouble in setting the core. Indeed, in the case of small cores, the molder can set them enough faster to pay for the extra work of pasting such cores together. As this is the main objection to this shape of print, viz., the necessity of making the cores in halves, it will be more than overbalanced by the advantage of the greater facility and rapidity with which the cores can be set, to say nothing about the larger output of **sound** castings.

The subject of taper core-prints for vertical cores is one of considerable importance, especially from the molder's standpoint. It is well to adopt some standard taper, so that if a core-print is lost, another may be made of the correct size whether the core-box is in sight or not. Probably the best taper for the purpose is one of one-fourth inch to one inch in height. This is an easily remembered taper and will give entire satisfaction

to the molder. This taper can be employed for all vertical prints large or small (the smaller sizes being reduced in length) one inch is long enough for any size of cylindrical **vertical** core. A good rule to follow for cores less than one inch in diameter, is to make the length of the print equal to the diameter, while preserving the same taper. It might be objected that one inch is too short for large cores, say of 12 inches or more in diameter. But there is not much strain on the print—




FIG. 81.

that is, on the print in the sand of the mold which holds the core in place—for it simply locates the core. Nearly all the strain, if, to be sure, there is any, comes on the end of the core. Therefore, any extra length given the print would be of no advantage, and one inch is as good as a greater length. One reason why there is but a slight strain on the sides of these prints is that the metal on entering the mold completely surrounds the core so that the pressure is practically equal in all directions. This, however, is not the case with the horizontal cylindrical core. As has been already mentioned, a taper of  $1/4$  inch on each side is the best. This is illustrated in Fig. 81, where it is reduced to a system.

In this system the dimensions of the prints for cores that are less than 1 inch in diameter are derived from the diameter of the core; for instance, if it is required to provide for a core that is  $\frac{7}{8}$  inch in diameter, the length of the prints will be  $\frac{7}{8}$  inch, or the diameter of the core, the large diameter also,  $\frac{7}{8}$  inch, the small diameter  $\frac{7}{16}$  inch or one-half the large. Therefore, in using this system, and, knowing the diameter of the core, the dimensions of the prints may be derived therefrom. Now if a print is lost, as often happens, another can be made without seeing the core-box, if this system is carried out for all cores of this kind.

A summary of the above for the shapes and sizes of cylindrical core prints is as follows:—

	SHAPE.	DIAMETER.	LENGTH.
HORIZONTAL.	Cylindrical.	Same as Diameter of the Core.	Equal to the Diameter.
VERTICAL.	Frustum of a Cone.	Large end = Diameter of Core. See Fig. 81.	1 in. when Diameter of the Core is 1 in. or more. See Fig. 81.

## CHAPTER IX

### MOLDERS' JOINTS OR PARTINGS

The jointing of patterns is fundamental, and must be considered from two points of view; that of the molder, and that of the woodworker. The first is concerned more particularly with the removal of the pattern from the mold, or, as the molder expresses it, **pulling the pattern**. The second is constructional, and into it en-




FIG. 82.




FIG. 83.

ters the combination and arrangement of the different pieces of wood composing the pattern. The joints that are arranged for the purpose of removing the pattern from the mold are usually called **partings**, or **pattern-makers' partings**, and strictly speaking, are not joints. The joints made in the **construction** of the pattern are true joints, and should be made as nearly perfect as possible, since the strength and durability of the pattern depends largely on their efficiency as joints.

The first mentioned of these joints, the **molder's partings**, will be considered in this chapter. Whether

a pattern is made correctly or not, from the molder's standpoint, will depend largely on the understanding that the pattern-maker has of these partings, and of their position in the mold itself. In order to explain these points a few examples will be used. It requires at least one of these molder's partings for every pattern, as the mold must consist of two bodies of sand, so that the pattern may be taken out. The simplest form of pattern is a square block like that represented by Fig. 82. The parting will be made on the line



FIG. 84.

A B, the part of the mold below that line being in the nowel; in this case **all** the mold will be in the nowel, the cope forming the top surface only. The next in point of simplicity is known as a **simple parted** pattern, and is represented by Fig. 68, on page 77. In a mold made from this pattern, one half would be in the nowel, and one in the cope, as represented at the right in Fig. 83. The line C D is the parting line of the mold and also of the pattern. In this form of pattern, it will be noticed, the molder's parting and the pattern-maker's parting exactly coincide. When a pattern is so made that the partings can be arranged in this way, the molding may be very easily and quickly done. The process of molding such a pattern is described in Chapter VI. Fig. 84 may be considered typical of a large class of

pattern work. It is a pattern for a small car wheel having a central web. The molder's parting will be made on line A B. No parting is required in the pattern because of the position of the molder's parting, which is made along the line A B on the outside of the




FIG. 85.

pattern; and on the inside of the rim the cope sand will extend down to the top of the web. The hub or boss C is usually left loose so it will lift with the cope sand.




FIG. 86.

Fig. 85 represents a pattern of a double flange wheel, and is a good example of a class of patterns where the molder's and pattern-maker's joints **do not** coincide. This would need what is called a **three-part flask**, meaning that the mold is composed of **three distinct bodies of sand**, which, of course, involves the making of two molder's partings. One of these will come in the centre of each flange on lines A B and C D. The pat-



tern will be parted at E F. The sand, or cores, that will form the part of the mold at G and H will be lifted with the cope down to the upper line of the web.

The mold for a worm wheel is another good example of molding where the parting of the pattern does not coincide with that of the mold. Fig. 86 will make this quite clear. The pattern will be parted along the line A B; the molder's partings, of which there must be two




FIG. 87.

will come on the lines C D and G H. All of the teeth will come in the middle part, or cheek, included in the space K. The two halves will, of course, be drawn from the mold in opposite directions, the inner curves of the rim, and the taper of the hub, affording plenty of draft. There is another form of molder's parting known as an **irregular parting**, that must frequently be used on account of the shape of the pattern. The pattern represented by Fig. 87 is an example of this form of parting. In the molding of this pattern the molder's parting will be made along the dotted line D D, so that

most of the mold will be in the nowel, which is very desirable, as it leaves less sand to be lifted by the cope. As indicated by the tapered prints shown at A' and B' in Fig. 122, a core will be used for forming a round hole through the casting. Another, but a more simple joint of this kind is shown by Fig. 88, which represents a




FIG. 88.

cast-iron bracket. The parting of the mold will be made along the dotted line A B. If a number of comparatively small brackets of this shape is wanted, the pattern can be parted through the central web, or a follow board can be made and fitted to a one-piece pattern, which would be the better way. A follow board is a board to which a pattern that must have an irregular parting has been fitted, the surface of which has also been cut to form the parting or joint on the sand of the nowel. A follow board takes the place of

the molding board for molding a pattern that must, because of its shape, have an irregular parting.

A contrivance frequently used in molding, called **skewering on loose pieces**, saves considerable time and work in both pattern-shop and foundry. An example of this is illustrated by Fig. 89, which represents a part of a cast-iron base for a woodworking machine. The




FIG. 89.

whole casting is cored out; and, for convenience in molding, the pattern has been boxed up to form a one-piece pattern, to be pulled from the mold in the direction indicated by the arrow. If the two bosses, A and B, were fastened on, they would tear up the sand. In order to prevent this they are **skewered on**—that is, held in place temporarily with wire skewers, as shown. As the mold is being rammed up, after sand enough has been rammed around the bosses to hold them in place, the skewers are pulled out. This, of course, allows the main pattern to be pulled out, thus leaving in the mold these loose pieces which can be pulled side-

wise into the mold. Of course, this pattern could be parted through the center line, but that would entail a large amount of extra work in both the foundry and the pattern-shop. By the use of this method, therefore, the extra work of making another parting is saved.




FIG. 90.




FIG. 91.

Another way sometimes adopted for forming projections on a casting is made clear by Figs. 90 and 91. They represent a hollow, cylindrical casting, with a flange on both ends, a projecting boss for a pipe on one side, about midway of its height, and an opening through the top. The pattern will have to be parted on the line CC, and will require a three-part flask, with molder's parting along line B B. To form the projection on the side, one of two methods may be adopted—

the use of a core-print and core, or a core only, to be set in place at the time of ramming up the mold. If the second method is used, all that the pattern-maker needs to do is to make a core-box with a pattern projection located in it. This core-box is represented by Fig. 92. If the first method is adopted, a core-print will have to be put on the side of the pattern, so as to extend




FIG. 92.

from the top parting down to a point just below the projection. If a hole is to be cored thru the projection, this would be the best way of doing the job.

The examples given above of molder's joints do not introduce nearly all the ways and means employed by the molder for making molds; but they do give a good general idea of the most common ways, and will afford such suggestions to the beginner in pattern-making as to enable him to make patterns so that they can be "pulled" without injury to the mold. This should be

the first consideration of the pattern-maker, as on it depends in a large degree the accuracy of the casting. If the mold is injured in any way by the pulling of the pattern, so that the molder has to mend it, the casting is rarely correct in shape. In the next chapter the matter of constructional joints is taken up—that is, the building of wood patterns from the viewpoint of the woodworker.

## CHAPTER XII

### CONSTRUCTIONAL JOINTS

In a consideration of this part of the general subject of pattern-making, two things must be given prominence, viz., the strength and durability of the pattern, and its permanence of form. This latter is very likely to be interfered with by the absorption of moisture from the damp sand, thereby causing the wood to swell, and perhaps to warp. The amount of moisture thus absorbed depends upon the time the pattern has to remain in the mold, and upon the condition of its protective coating of varnish. To overcome any change likely to take place from this cause, several methods of arranging the various pieces of which the pattern is built up, are used. The particular method to be employed in a given case depends on the size and shape of the pattern, and also depends, to a degree, on whether a large number of castings is wanted or only one. In order to secure the requisite permanence of form, it is better, other things being equal, to build a pattern of several pieces rather than to cut it out of one piece. For then the warping in the whole pattern is reduced to a minimum. In small patterns, however, this warping may be disregarded; therefore, a **small** pattern may be cut from a single piece of wood. This matter of constructional joints may be most easily comprehended by studying examples of forms likely to be required.

When thin disks are wanted it is best to build them

up of three layers with the grain of the pieces running tangentially to a small circle in the center, as illustrated by Fig. 93. The grain of the wood must run parallel to the longest side of each sector. After the pieces have been fitted together, a groove is cut in the edge of each, in which tongues of wood are glued and driven as illustrated in the right-hand view, Fig. 93. When one disk has been glued up and the glue has dried, the




FIG. 93.

sectors for the other disks may be glued directly to it, with the joints running across the others, the angle depending on the number of sectors used to form the circle. This makes a very rigid construction and one which will not warp.

If in building a pattern a thin, wide board is required and the other parts of the pattern are of such shape that they do not afford to it sufficient support to keep it from warping, a good way is to rip the board up into strips from 2 to 4 inches wide (according to the width of the required board) and then glue the strips together, with each alternate strip reversed, as shown at A, Fig. 95.



In this way the warping will be reduced to the minimum because the alternate pieces are inclined to warp in opposite directions.

A good way to support patterns of this general shape during the process of molding is illustrated by Fig. 95. The additional pieces B and C are called **counter ribs**. The recesses made by them in the sand will be filled by the molder, or, as he expresses it,



FIG. 95.

they are “stopped off in the mold,” and therefore will not appear on the casting. The shape of these counter ribs, which is more clearly shown at D, indicate to the molder that they are to be stopped off in the mold. Whenever possible these should be put on the pattern so they will come in the novel of the mold. These are also called “stop-off” pieces. Another way of building patterns which are round and flat and are supported by segments running around them, is to make the flat part of several strips rather than of a wide board. This is illustrated in Fig. 96. These strips should not be glued

together, but held in position by the segments that are built on to them. If the pattern is more than 12 inches in diameter on the inside, it is advisable to insert at least one dowel in each of the joints between these strips to keep them from springing sidewise. This need be done only for three or four of the joints near the center. A slip tongue joint may also be used instead of dowels.




FIG. 96.

Another way to overcome the effect of shrinking and swelling in large patterns is the use of what is termed **open joints**. If it is required to build a large pattern that is flat and comparatively thin, either circular or square, it should be built as shown in Fig. 97—that is, the sides should not be built up by gluing narrow boards together, but they should be laid side by side with open joints between, of from  $1/16$  inch to  $1/8$  inch in width, and a slip-tongue inserted. If the boards expand with moisture the width of the pattern as a whole does not increase; the only effect is to partly

close these open spaces. If the boards shrink the only effect is that the spaces increase in width. As work of this general shape—that is, of large area but comparatively thin in cross-section—is usually stiffened with ribs and flanges, the fact that the joints are open will not materially affect the rigidity of the pattern. If a




FIG. 97.

case should occur where there was not support enough in the pattern itself, then the boards could be held in place as shown in Fig. 97, by a method which is, practically, paneling. A frame is made as for a panel door, and the ends of the boards fitted into a groove. This method may be used in connection with what is known as **boxing up** a pattern. This is illustrated in Fig. 98. Open joints are represented at a, a, a, Fig. 97. This term, boxing up, is used in speaking of a class of patterns that are built of comparatively thin lumber, the pattern itself, being large, making a box-like structure

that is both light and strong. This method, **boxing up**, is frequently used for large patterns which, if made solid, would be unduly heavy and would be especially liable to be affected by moisture or dryness. The rabbeted joint should always be used at the corners in boxing up a pattern that is of a square or rectangular cross-section. This is illustrated by Fig. 98. If the pattern was to be pulled from the mold in the direction




FIG. 98.

indicated by the arrow, and was built as at a, Fig. 98, then any change due to shrinking or swelling of the relative position of pieces b and c would leave an uneven surface on the vertical side which, on being pulled from the mold, would be likely to tear up the sand and thereby cause the molder some trouble. If the joints are arranged as at A, Fig. 98, this cannot occur. This form of joint has another advantage, for if the joint were simply a butt joint, the ramming of the sand of the cope down on the face E would be likely to drive the top board down below the edges of the sides, but in this case the piece E, being rabbeted into A and C, cannot be driven down.

Fig. 99 represents an example of another type of hollow work, which, however, is not called boxing up, but **lagging** or **lagging up**. This method may be defined as the building of patterns of cylindrical shape with longitudinal strips that run parallel with the axis of the proposed cylinder. The figure represents a section of the pattern of a pipe or column of any diameter over




FIG. 99.

four or five inches. A A is the joint of both pattern and mold. B B are cross-bars of polygonal shape on which the strips or lags are laid and fastened with glue and screws. The lags are also glued to each other except on the line A A.

Fig. 100 illustrates another way of building by lagging. In this way much narrower strips are used, thereby reducing the work of turning and also requiring less lumber. The parts for the core-prints are built up first, and then the lags for the rest of the pattern are fitted and glued and screwed to these, as is indicated by the figure. Should the body of the cylinder be long, two or more semi-circular discs must be used to insure rigidity. Fig. 101 shows how this method of building

up may be used for large cylindrical core boxes. If the work is done accurately, the work of finishing the inside of the box is reduced to a minimum.

When annular patterns of 6 inches or more in diameter are wanted they are made by what is known as **building up with segments**. This is illustrated by Fig.




FIG. 100.




FIG. 101.

102, and when properly done makes a very strong construction. The several pieces should be cut from the board in such a way that the grain of the wood follows the circle as near as may be. Therefore, in laying out the segments the **chords** of the **curves** should be **parallel** to the **grain** of the wood. In building patterns of this type, a number of short segments are sawn out and glued in courses, one over the other, with the end joints alternating, or **breaking joints**. When the glue is dry the correct outline is imparted by turning or otherwise.

By this construction shrinkage in the segments is reduced to practically nothing.

Examples of constructional joints used in still another type of pattern, sometimes termed **plate work**, is represented by Figs. 103 and 104. Fig. 103 shows a frame cut from the solid wood, 18 inches wide and 2 feet 6 inches long, by 1 inch thick. It is clear that strength




FIG. 102.

and permanence of form is entirely lacking in bars A A A. Contrast this with the construction in Fig. 104. In the latter there cannot be any material alteration in width or length, in general or local dimensions, and there is the maximum of strength. The frame is made of five narrow strips. Alternative methods of making half-lap joints are shown. At the corners plain halving is shown. At D the dovetailed form of halving is illustrated. The plain halving, if properly made, glued and screwed, is very strong and permanent. For standard patterns, however, it is advisable to employ the dovetail form.

Another example of this same type, but of a very distinct form, is shown in Fig. 119. The finished casting is shown in Fig. 118. It will be noticed that the joints are of the half-lap form. This figure (Fig. 119) shows the plate part of the pattern only, made up of three pieces. The pieces are so arranged that wherever there is a curve there is wood with the grain running



FIG. 103.



FIG. 104.

practically tangent to it; consequently, if the joints are properly made and glued, it can be worked into shape without being broken out. Moreover, there is wood enough at all the angles so that the fillets may be worked in the solid wood instead of separate pieces being glued in for the fillets. For standard plate work it is always best to do this, even if it does take wider material. The added durability will more than pay for the extra lumber, and then it also saves the time of making and gluing in the separate pieces.

Round corners may be formed, as shown by Fig. 105. In this case the two pieces, A and B, are joined in the



usual way with a butt joint as at C; the piece D is glued into the angle and allowed to stand long enough to dry; then the corner is worked to the required form outside and inside. In work of this kind it is best to work the inside first, because the piece can usually be held better if the outside corner is square than if it is rounded. The block, after being fitted to the angle, may be sawed or planed to form, as indicated by line E. This can be




FIG. 105.

done more easily before than after it is glued in place.

As pattern-making is one of the most comprehensive of trades, and the demands of the engineering profession for complicated castings are limitless, it is impossible to anticipate the next form a pattern-maker will be called on to make. This being the case, only general methods can be considered in a volume of this size. The joints and methods of construction that have thus far been considered are those most frequently employed in pattern-making. Special examples of types of pattern-making will next be taken up, for which one or more methods of construction will be given in detail.

## CHAPTER XIII

### TYPICAL PATTERNS

Before taking up the subject of making special types of patterns, certain matters that apply, not only to special types, but to all patterns, may be considered. One of these is the preparation of the lumber. This consists, in the first place, of cutting roughly to size, the several pieces required for making the proposed pattern. They are then allowed to stand for as long a time as the job will allow, so that they may warp into and assume a nearly permanent form. If this is done, when they are cut to the final shape they will not again warp and change the original form of the pattern. This additional seasoning is necessary, because lumber will change more or less in shape when much of it is cut away, exposing a surface that has heretofore been on the inside of the plank or board. The foregoing constitutes the first step and may be termed **cutting the stuff roughly to size**.

The next step is **planing up** one or two sides of each piece to a true plane, and **marking** them as **working faces**. Usually these planes should be made at right angles to each other. This is quite important, as, generally speaking, the accuracy of the work will depend to a large degree upon the accuracy of these two faces. All lumber to be used in making patterns should be planed by hand, before being put into the pattern, especially if a flat surface is desired. The ordinary rotary knife planer

will not plane stuff flat, therefore the hand plane must be used. If there is a Daniels planer in the shop it may be used to plane one side of the board; the other may be passed through the ordinary planer. But even if this is done, the lumber should be planed by hand to insure a good finish, as the rotary knife will leave the surface more or less corrugated.




FIG. 106.




FIG. 107.

The simplest patterns are those which are made in one piece, and which require no coring, although the castings themselves may be hollow. In commencing a pattern, one must first decide how it is to be removed from the sand, and where the parting should be, if one is needed. A simple one-piece pattern around which to form a mold with a dry-sand core, is exemplified by the stuffing box gland shown in Fig. 106. This figure shows the finished casting, which is to be

finished all over. This typifies a very large class of patterns which must be cast on end. It is what is generally known as a stuffing-box gland. The finished casting is represented by Fig. 106, the finished pattern by Fig. 107 and the requisite core-box by Fig. 109. Fig. 106 represents also the drawing that would be sent to the shops. The gland is made from this drawing.




FIG. 108.

Considering this pattern from the molder's standpoint, it is clear that if it is molded endwise, with the flange up, and if the molder's parting is made along the top of the flange, it can be readily pulled. The draft in this case should be  $\frac{1}{8}$  inch for 12 inches. Each core-print should be 1 inch long.

When the amount of draft and finish is decided on, it is a good plan to make a full-size sketch of the pattern as it will appear when ready for the molder, and with all required dimensions plainly shown on it. This should be done before one begins to make the pattern. Indeed, one may well follow this method in the case of **every pattern**, for thereby many mistakes and much loss of time will be avoided.

According to the drawing, Fig. 106, this gland is to be finished all over, so that in making the pattern there must be allowance for both finish, or machining, and draft. As none of the dimensions are over 6 inches in any one direction, shrinkage may be disregarded. As this pattern is to be pulled from the mold endwise, the draft on the outside will have to be like that shown in Fig. 70 on page 85. One way to make a pattern for this

casting is shown in Fig. 108. If it is made in this way, it may be molded and leave its own core, but the hole can not have its opposite sides parallel. It is usual to allow double the amount of draft on the inside for all small cores similar to this one. This would make considerable more work for the machine shop if the hole had to be finished. For this reason, if a large number was wanted, the pattern would be made as described in the following paragraphs.

To make this pattern it will be necessary to build up a block of wood that is at least  $3\frac{3}{4} \times 3\frac{3}{4} \times 7$  inches long. The best way to do this is to use two pieces  $1\frac{1}{2}$  inches thick, and one piece  $\frac{3}{4}$  inch thick, gluing them all together, with the **thinner** one between the other two. In gluing up work of this kind, it is always best to have the thicker pieces on the outside; for if the piece on the outside is too thin, it will, during successive moldings, be likely to become loosened on account of the action of the damp sand on the glue. If the two outside pieces are thin, the wedge-shaped parts that are formed by the turning will be so thin that they will be very likely to curl under the influence of the damp sand. As soon as the glue is quite dry, the corners may be cut off with an axe or a chisel and mallet. The piece is now ready to be mounted in the lathe, and should be turned to a




FIG. 109.

cylinder of  $3\frac{5}{8}$  inches in diameter, which is the outside dimensions of the flange. Now, laying a rule along the tool rest up against the cylinder, point off the




FIG. 110.

measurements as indicated by the drawing, preferably commencing at the right-hand end—that is, next to the back or dead center of the lathe. By commencing at that point any surplus material will be left at the other end, so that it will not be necessary to get so close to the chuck or driving center with the tools. First, then, make a

mark about  $\frac{1}{16}$  inch from the right-hand end for the end of the print. From this point measure 1 inch for the length of the print; from this  $3\frac{3}{4}$  inches for distance from the end of the pattern to the under side of the flange; from this point measure  $\frac{3}{8}$  inch for the thickness of the flange; from this mark measure 1 inch for the length of the print on this end. Check up by measuring total length between the outside marks, which should be  $6\frac{1}{8}$  inches. Now hold the point of a pencil at each of these marks, allowing the side of the pencil to lay on the tool rest; give the belt of the lathe a pull which will turn the cylinder, making a mark all the way around it. Now cut the cylinder to the required size below the flange, remembering that the core-prints will have to be tapered, because this will be a vertical core. Now, if the successive steps have been done correctly, the pattern will be like Fig. 107. The top print should be made loose for the convenience of the molder.

The next thing will be the making of the core-box in which to make, or form or mold the dry-sand core. This box is shown by Fig. 109. This being a symmetrical core, one half box will be enough. To make this we proceed as follows: Take a piece of straight-grained pine, of such a width that after the semi-circular groove forming the body of the box is cut out, there will be left about  $\frac{3}{4}$  inch on each side. In this case, the box being  $2\frac{1}{4}$  inches in diameter, and  $1\frac{1}{2}$  inches for the two sides, the width of the piece will be  $3\frac{3}{4}$  inches. The depth of the groove will, of course, be  $1\frac{1}{8}$  inches, and there should be at least  $\frac{7}{8}$  inch thickness of wood below this, which will make the required block  $2 \times 3\frac{5}{8}$  inches and 5 inches long. The block should be planed on all sides; one of the wide sides (for the top of the box) and its adjacent narrow sides are to be straight, parallel, and exactly at right angles to each other. To lay out the lines for the inside of the box, fasten the block in the vise with one end even with the top of bench, or vise. Now set the dividers to the radius of the required curve,  $1\frac{1}{8}$  inches, and put one leg of the dividers in between the block and the vise jaw, on the side intended for the top of the box, approximately in the center of the side; then describe a semi-circle on the end of the block, as shown at Fig. 110. Now with the gage set to the distance c to a, make a mark along the top or face side for the whole length from the point a, then extend the gage to point b, making another line the whole length of the block. On the other end make another semi-circle, connecting with the ends of the gage lines. This completes the laying out of the core-box. The wood must now be taken out

just to these lines. This may be done in two ways, the better of which is by the use of the core-box plane. This is a plane whose face instead of being just one surface, is composed of two surfaces set at right angles to each other, as shown by Fig. 111. The cutting iron




FIG. 111.

is narrow, and ground to an acute angle, so as to conform to the shape of the plane at the apex of the angle forming the two sides of the face of the plane. The principle of its construction and use is, that the greatest inscribed angle in a semi-circle is a right angle. The whole of the wood on the inside of the semi-circle cannot be cut out with this plane, so first use a gouge to cut it out to within  $\frac{1}{8}$  inch of the mark; next cut it exactly to line along both gage marks; then, holding the plane in such a way that the fingers of the left hand will form a guide to keep the plane to the line, cut a shaving along the line on the side farthest from the operator. This is illustrated by Fig. 112, in which the upper curved line represents the work as done by the gouge, and the semi-circle immediately below it is the circle to which the wood is to be cut. There is now a guide for both sides of the plane, so that by exercising



a little care the plane may be passed along throughout the length of the block, cutting a shaving at each stroke. This may be continued until about one-third of the whole is worked out. Now the block may be turned end for end, and the other side treated in the same way down to about mid-way of the distance; then turn the block again and finish the other side. This will make a very neat and accurate job if the plane is in proper condition.

Another way by which the plane may be started is to nail a thin strip of wood along the gage line as represented at a, Fig. 112. This is used as a




FIG. 112.

guide for the plane. After the groove has been cut down a short distance (about  $1/16$  inch), this extra piece **must** be removed to the other side and again used as a guide. This guide piece **must** be taken away before working the groove down very much, for if allowed to remain, it would change the size of the semi-circle made by the plane. The cutting iron of the plane should be so sharpened and set as to cut on one side only, preferably on side A, Fig. 111. If it is allowed to cut on both sides, and used as indicated by Fig. 112, it will cut the groove too large, making the core-box larger in diameter than wanted. This plane may be made to do more accurate work by having a shallow rabbet cut along one side of the apex of the angle, as shown at A, Fig. 111. If this is not done the cutting iron must be

set out a little beyond the face of the plane in order to cut a shaving, and so will make the semi-circular groove larger than wanted.

Another way to cut out this part of the core-box is to use a gouge to remove almost all the material, using a round plane to finish with. Doing the job in this way will involve the use of a straight edge to test the straightness of the work from end to end. For this




FIG. 113.

purpose, a straight edge with a thin cross-section is necessary. A try-square if long enough, is a very good tool for this purpose.

The core-box plane is almost indispensable for making core-boxes of the shape represented by Fig. 113, for what may be called conical cores. As the curve changes continually throughout the entire length, it is almost impossible to make a cavity that is uniform, if one uses the gouge and round plane. A straight edge and templet must be used frequently to test the work. But the core-box plane overcomes all these difficulties, and if only the two sides of the cavity are correctly located, and then worked to the lines with the gouge, the plane will do the rest of the work. There are ma-

chines on the market which do this kind of work very accurately and rapidly.

Whichever method is used in making this part of the core-box, it needs to be smoothed on the inside with sand paper. If the box is small, this is best done with sandpaper placed around a cylinder of wood, the cylinder being about  $\frac{1}{4}$  inch smaller in diameter than the box. If the box is large, a piece of wood about 4 or 5 inches wide and 1 inch thick, with one side planed approximately to the curve of the inside of the box, will be better.

To form the ends of the box marked A A in Fig. 109, the following is the best way: Make two pieces of wood 4 inches long, 2 inches wide, and 1 inch thick. Plane them so that two of the narrowest faces will make a good joint at right angles to the wider sides. Now face up a chuck about 6 inches in diameter, and while it is revolving in the lathe, make a fine pencil mark or dot in the center. Place one of the pieces flat on the chuck, so that one of the face edges will pass thru this dot mark. There should




FIG. 114.

also be a mark put at the center of the length of the corner that comes in contact with the chuck; this mark should also be placed at the center so that the work be balanced in the lathe. Nail it to the chuck in this position, and then place the other piece alongside and nail it also. If this work is correctly done, the chuck, with pieces nailed on, will look something like Fig. 114. This is now to be put on the lathe, and a hole of

the shape of the core-print on the pattern turned into it. If the blocks have been properly placed, each will have a semi-circular hole in it, representing one-half the frustum of a cone, whose dimensions correspond exactly with those of the core-print on the pattern. These are




FIG. 115.




FIG. 116.

now to be taken from the chuck and nailed and glued, one on each end of the body of the box previously made. This must be cut to the exact length required, which in this case will be  $4\frac{1}{4}$  inches. It is necessary that a core-box for a vertical core should be about  $\frac{1}{8}$  inch longer than the pattern, so that the cope of the mold will be sure to fit tightly around the core; then no metal can flow up alongside of it and over the end of the core,

thus covering up the vent and causing the casting to blow. For the above reason all **vertical** cylindrical cores should be  $\frac{1}{8}$  inch longer than the total length of the pattern and prints. To complete the box it is only necessary to nail pieces B B, Fig. 109, one on each end, and then give a taper at the point C, Fig. 109. To make the core two halves are made in this box; after drying, they are pasted together, making a complete core.

The next example is very similar to the former one, but, having a flange at both ends, it will have to be molded **horizontally**, and will therefore require a **horizontal** core. The completed casting is represented by Fig. 115, and a pattern for producing it by Fig. 116. On account of the shape of this casting it will be best to make the pattern a **parted** pattern. This will save the molder some time and work, as it will give a form that is easily removed from the sand. In making this pattern, the first thing to do will be to get two pieces of wood of such dimensions that when they are put together the pattern can be turned out of them. As will be noticed by the drawing, there is no finish required except on the face of the flanges. Allowing for finish, the length of the pattern without the core prints will be  $6\frac{1}{4}$  inches. The core is to be  $1\frac{1}{2}$  inches in diameter, so the prints will be  $1\frac{1}{2}$  inches long; then 2 inches more must be added for fastening together at the ends, making a total of  $11\frac{1}{4}$  inches for rough size. Two pieces, then, are needed,  $11\frac{1}{4}$  inches long, 4 inches wide, and 2 inches thick. The next step will be to plane

one of the larger sides of each piece to a true surface, to form a joint between them.

The next thing is to locate the holes for the **pattern pins**, so that no mistake will be made in putting together the two parts of the pattern after being separated. The most practical way to do this is as follows: On the plane surface of one of the pieces locate these holes with a pencil mark; these marks to be, say 4 and 5 inches, respectively, from the center of its length and approximately on the center of its width. If the pins are thus located, the molder will not err in putting the two halves together, for if he happens to do it incorrectly, he will at once recognize his mistake.

Having marked the points where it is desired to put the pins, take two small brads and lay them on the block with the heads at these points; now carefully lay the other pieces on these brads, and, having brought it into exactly the desired position, strike the top piece a light blow with the hammer or mallet. This will cause the heads of the brads to make corresponding impressions on both blocks. At these impressions, bore holes  $\frac{1}{2}$  inch deep. The diameter of the hole is of small moment; for patterns of this size,  $\frac{1}{4}$  inch is about right; the larger the work, the larger the pins should be.

The next thing to be done will be to make the pins, for which a piece about 10 inches long will be found the best. Select a piece that is straight in the grain, and rip to such a size that one side of the square stick equals the diameter of the hole plus  $\frac{1}{8}$  of an inch. With the jack-plane plane this into an octagonal form. Then, grasping one end in the left hand and laying the other

end on the bench, with the block-plane plane off the corners, making it as nearly round as possible for about 3 inches of its length. This round part should be made to fit the hole exactly—that is, at the extreme end. With knife and sandpaper, or file, round this end to an approximately parabolic form. Now set it into the hole in the piece into which the pins are **not** to be fastened, far enough so that it exactly fits the hole. Make a pencil mark part way around it right at the surface of the block. Now measure the depth of the hole into which the pin is to be fastened, and mark this distance along the pin from the mark previously made. This is the point at which to saw the pin off. Now, if this pin be driven down into the hole clear to the bottom, the first mark will come even with the parting and will exactly fit. By means of these pins, the two parts, after being separated, may be brought together again in exactly the same relative position, and will be held firmly so that they will not slide or shift sidewise during the process of molding. They should be loose enough so that the pattern will fall apart of its own weight, but still not loose enough so that there is any perceptible movement sidewise.

When both pins are in place, the blocks are ready to be fastened together. There are three ways in which this may be done. If there is time to wait for glue to dry, the best way is to put glue on the ends of each piece for a distance of about  $\frac{1}{2}$  inch, and clamp them together with a handcrew or other clamp. If it is desired not to wait for the glue, then a screw may be put through the ends, fastening them together in that way. It is advis-

able, for convenience in turning, to use a short screw, deeply countersinking its head. For a piece of this size a  $1\frac{1}{4}$  inch No. 14 screw may be used. If care is taken to have one-half the length of the screw in each piece, it can be turned to the required size of the print, out to the extreme end. The third method is to clamp them together with "dogs," which are small square staples made for the purpose. When the pieces are thus fastened together, they are ready to be placed in the lathe




FIG. 117.

and turned. This may be done practically in the same way as in the previous example. For a piece of this size it is advisable to cut off the corners of the block before mounting it in the lathe; this may be done with a hand axe or mallet and chisel. One must allow for draft, and also for finish on the faces of the flanges, making these faces, and the ends of the prints, convex as shown in Fig. 116.

The next thing to make will be the core-box. As this pattern requires what is known as a plain, cylindrical, horizontal core, and is therefore symmetrical, only a half-box is needed. But if it is desired to reduce the cost in the foundry, a core-box like the one represented




by Fig. 79, page 109, in the chapter on cores, would be used, the core being made complete at one operation. The half-box would be made as directed for the straight part of the core-box in the last example, with end pieces, as represented by Fig. 117. If a whole box is made, then the block would need to be twice as long, and worked out as in Figs. 109 and 110. After this is worked out, it should be cut in two pieces and pinned together in the same way as was done with the two pieces for the pattern. One way of doing this that is quite practical is the following: After cutting the pieces the correct length, place them together in their proper relation to each other; fasten them in the vise in a vertical position, with one end above the bench top, and bore a hole of the size required for the pin clear through the first piece and about half an inch into the other. Now by putting the pin through the hole, it will be filled and make an accurate and workmanlike job. If brass pins are used, this could not be done, because the pin would not fill the hole; and as the pin and its tube are of a different size, the hole could not be bored with the same bit. The inside length of this core box should be  $\frac{1}{8}$  inch shorter than the total length of the pattern and prints, so that the core may be more easily set into the mold.

The next example to be taken up is typical of a quite large class of pattern work, generally known as plate work. It is usually comparatively thin in cross-section in at least one direction. This class of work includes

shafting hangers of different patterns, some kinds of small pump standards, and any kind of work that is composed of two webs running into or crossing each other. This last is illustrated by Fig. 118. The example to be used to demonstrate the methods usually followed in building patterns of this type is represented by Figs. 118 and 119. In order to make the best pattern for durability and permanence of form, the foundation should be built of three pieces, as shown in Fig. 119, which is almost self explanatory. Of course, this part of the pattern could be built of one piece of board, but it would be very weak through the portion marked A. By building it as represented, two things are gained: it is uniformly strong throughout, and smaller pieces of wood may be used. As in the case of all other patterns, so in this, it should be first determined how the pattern is to be withdrawn from the mold. It will soon be seen that the best way will be to have the face marked B, Fig. 118, down in the nowel; thus there will be left an almost flat surface for the molder's parting, which will then occur along line C D. It will, of course, be necessary to make part E loose, so it will lift with the cope sand. This is a type of what is known as **loose pieces** molded in the cope and drawn therefrom after it is **lifted off** from the nowel. The method now to be described of laying out and building this pattern, may be used in building any pattern of this general type; modifications of it may be introduced when needed.

The first step to be taken in making this pattern is the making of two pieces of board about 15 inches long



by 3 inches wide and  $\frac{5}{8}$  inch thick, and one piece about 9 inches long, 4 inches wide and  $\frac{5}{8}$  inch thick. These must be planed on one side to a true plane, with the edges straight and at right angles to the side; a **face mark** should be put on each piece. Now the two long pieces should be cut to shape, so as to make a good joint at F, Fig. 119, care being taken that the two lower corners are far enough apart to include all of the pattern at that end. Tack these to the bench or laying-out table in their proper position with relation to each other; then locate points G H, and lay the third piece on the others with its edge at these points, and make knife marks against this and across the two pieces. Now, without moving the third piece, make marks on it with the point of the knife at the points K, L, M, and N; connect these points with good, clean knife marks across the face; then finish the laying-out by making gage marks in the center of the edges where needed to limit depth of gains; now cut the gains to these lines. Then cut out the ends of the short piece to the same thickness, but on the opposite side; fit them together and glue them and put them in clamps till dry.

While this is drying, a piece of board about 15 inches long, 6 inches wide, and  $\frac{1}{2}$  inch thick, can be gotten out. Out of this can be sawn pieces for making the curved pieces that are built on to form the raised portions that are to be glued on to the main piece. These should be cut from the board so that the grain of the wood will run parallel with a chord of the curve, making the segment not to exceed one-quarter of the circumfer-




FIG. 119.

ence of the circle. If they are made longer than this, there will be too much end grain. The straight pieces may also be gotten out at this time, so they will be ready when wanted.

When the glue is dry on the three pieces that together form an A-shaped piece, it is to be planed on both sides to true planes until it is  $\frac{1}{2}$  inch thick. It is now ready to have the lines laid out on it as shown by Fig. 119. In laying out these dimensions, the shrink rule should be used, as that will allow for the shrinkage of the metal in the casting. After these are all laid out, it may be sawn out on the band and jig saws. In doing this sawing, it is best to cut just outside the line, so that in filing and finishing the edges, the marks may serve as a guide. It is now ready to have pieces set on to form the projecting webs, which may be cut from the  $\frac{1}{2}$ -inch piece already mentioned. It will be best to commence at the top of the pattern.

The first will be a solid piece extending all over the upper end down to and including the semi-circle that joins the long outside webs. After this the other circular parts may be cut out and put on. Now the pieces to form the feet may be made and glued in place; then the straight pieces should be nicely fitted to these and glued in place. Now a piece of wood may be gotten out to form the fillet around the bearing, or top part of the pattern, where it joins the main part of the pattern. This should be about  $\frac{3}{8}$  inch thick, and should be large enough to extend  $\frac{3}{8}$  inch all round outside the bearing. For convenience in cutting out the fillet, it is best to let the grain of the wood in this piece

run parallel with the outside line of the pattern at this point. A piece is also needed to go on the other side to form a fillet on which to pin the loose piece, E, Fig. 118. Now a piece to form the bearing itself may be made. As this is required to be more than a half circle, it will be best to make it with the planes. According to the dimensions given, it will need to be of the following finished measurements: about 4 inches long,  $2\frac{1}{4}$  inches wide, and  $1\frac{3}{8}$  inches thick. It should be planed square to these dimensions, and a semi-circle described on each end, and then planed and sandpapered down to it. A piece can now be cut from this just 2 inches long, and fastened on top of the  $\frac{3}{8}$  inch fillet piece. Both ends of this piece must be square, so it will set in vertical position on one end, and so the core-print to be made later will fit well. A piece of this is required for the other or cope side 1 inch long. This, however, will not be fastened in place permanently, but will be pinned on so that it will lift with the cope sand when the cope is lifted off. The best way to do this is to place it in a correct position and drive two small brads through it, taking care not to put them where the pin holes are to be bored. Now, with brace and bit, bore two holes clear through it and into the other part of pattern to a depth of about  $\frac{1}{2}$  inch. A  $\frac{1}{4}$ -inch auger bit is a good size to use for this purpose. Now make pins as directed for use in the parted pattern on page 149. In this case they can be put through and fill the holes, as they will have to be on the loose piece.

The next thing will be to make the core-prints.

These will extend the whole length of the bearing, and of course the length of the prints besides, and as this is a vertical core, will project 1 inch beyond the pattern on each side. To make these prints for this particular job, take a piece of wood about 7 inches long and  $1\frac{1}{2}$  inches square, place it in the lathe and turn to shape and dimensions as shown by Fig. 120. The




FIG. 120.

shaded portion will be cut out so it will fit down on to the pattern already made. The line just above the shaded part is the point to cut through so as to coincide with the pattern parting.

To complete this problem a core-box will be needed, which will be made as shown at Fig. 121. The process is the same as already described, except as to pieces marked X. These are to form a crease or groove in the core, to form the babbitt pieces on the casting shown at O, Fig. 118. These are simply pieces of wood  $\frac{1}{8}$  inch thick, of a size equal to the cross-section of the core-box, and with a semi-circle cut in on one side, whose diameter is 1 inch, as that is the size of the shaft the bearing is intended to carry. In building the box, the pieces must be nailed in between the body of the box and the parts forming the prints. The completed box is shown in Fig. 121.



The pattern for a hook lever for Corliss valve gear will be the next problem taken up. This gives a good example of what is known in the foundry as an **irregular parting**, and is illustrated in the chapter on molders' joints by Fig. 87, the molders' parting following the heavy broken line. It is also a good example of what may be called a built-up solid, **one-piece pattern**,




FIG. 121.

meaning that the completed pattern has **no parting**. This is typical of a very large class of patterns, as all patterns would be made **one-piece** if they could be conveniently molded in that shape. Before commencing the actual work on this pattern, notice particularly the position of the molders' parting, and then the direction of the required draft. The first pieces to be gotten out will be the two of which to make the arms, each about  $4\frac{1}{2}$  inches wide, 10 inches long and  $\frac{3}{4}$  inch thick. These should be planed to a true surface on both sides to the exact thickness,  $\frac{3}{4}$  inch, then nailed together so that their lines will be at the required angle of 105 de-

grees. On one surface of these lay out the shape accurately as indicated by the drawing, allowing about  $\frac{1}{16}$  inch for draft around the central boss. The arms may now be sawn out on the band-saw, leaving the marks as a guide for finishing with a file. The round boss or disk




FIG. 122.

A, Fig. 122, may now be made. This should be sawn out about  $4\frac{1}{4}$  inches in diameter,  $1\frac{1}{4}$  inches plus  $\frac{1}{8}$  inch for "finish" in thickness, and mounted on the lathe and turned to exact dimensions, which are 4 inches in diameter at B and  $4\frac{1}{8}$  inches at C, Fig. 123. Another boss is needed at D, Fig. 122, but only  $\frac{3}{8}$  inch thick. These may now be nailed in place on the arms, care being taken as to the side on which each is put, as the position of these pieces will determine whether the




FIG. 123.

pattern is to be a right or left hand lever. This can be easily settled by comparing the work already done with the drawing. A screw chuck affords a good means for holding these pieces in the lathe, to turn the four bosses required for the ends of the arms. These four may all be turned out of one piece by cutting off a piece from a two-inch plank about 2 inches long, measured in the direction of the grain, and 6 inches long, across the grain, and mounting it in the lathe so that the grain is perpendicular to the axis of the lathe. This is plainly shown by Fig. 122. After these bosses are all fastened in place (they should be so placed that the grain will run in the same direction as it does in the arms), the arms may be shaped or rounded into the elliptical form indicated at L, Fig. 123, and all the different surfaces blended into each other so as to make one even and well-molded surface. The central hole, or bore, as it is sometimes called, will of course be made with a dry-sand core, so that it will be necessary to use core-prints and a core-box. This being a vertical core, the **shape** of the prints and the core-box will be the same as for the first exercise, Fig. 109. For the convenience of the molder the top print B should be left loose.


## CHAPTER XIV

### PULLEY PATTERNS

The next type of pattern work to be considered is the making of patterns of the general shape of Fig. 102, sometimes called **annular** patterns. The example used for the purpose of explaining how such work is done is the pattern for an 8-inch pulley with a 3-inch face. The technical description for shop use is written like this: Pulley 8"x3", hub  $2\frac{1}{4}$ ", four arms, rim  $\frac{3}{16}$ " thick. The "8'" refers to the outside diameter of the pulley; the "3'" to the width of face; " $2\frac{1}{4}$ " to the diameter of the hub or central boss, through which the shaft runs; and "four arms" to the radial arms or spokes that connect this central boss with the rim of the pulley; the " $\frac{3}{16}$ " rim" refers to the thickness of the rim at its outer edge. The finished pulley is represented by Fig. 124.

The first step in this pattern as of all others, is to determine how it is to be molded. As to mold it from a one-piece pattern would be quite difficult, it is best to make a parted pattern, the parting being made on a central plane running through the center of the arms; this means that two halves will be made. The first thing to do is to prepare a chuck about 9 inches or  $9\frac{1}{2}$  inches in diameter and about 1 inch thick, and face it off true. On this chuck build up a ring or hollow cylinder high enough so that both halves may be cut from it. If enough is built for both halves, it will need to

be 3 inches—equal to the width of pulley face, plus 1 inch for cutting off, making in all 4 inches in height. This is to be built of straight-grained white pine about  $\frac{7}{8}$  inch thick; therefore it will take five thicknesses for the required height. These pieces will be cut into segments, or cants, of such length that four will complete the circle. They must be cut so that the grain of the wood is **parallel** to the **chord** of the **curve**. These will be cut on the band-saw or jig-saw, and made large enough so that the ring may be turned and still allow for draft and finish. As  $\frac{1}{16}$  inch is to be allowed for draft and  $\frac{1}{8}$  inch for finish, and as the finished pattern will need to be  $8\frac{3}{8}$  inches in diameter at the center, the rough, built-up ring should be about  $8\frac{3}{4}$  inches in diameter. For a guide in building, make a pencil mark on the chuck while it revolves in the lathe, so that the circle thus made will be of the required diameter. To mark out the segments, proceed as follows: Set the dividers at the radius required,  $4\frac{3}{8}$  inches, and describe an arc tangent to the edge of the board farthest from you, from which it is proposed to cut the cants. Set the dividers to  $3\frac{1}{2}$  inches, and describe another arc concentric with the first one; this will leave the cants  $\frac{3}{4}$  inch wide; lay a framing-square on the board at an angle of 45 degrees with its edge, with the heel exactly over the center from which the arcs were struck; and at the points where the sides of the square cross the arcs, make marks. This will give the length of the required segment and at the same time give the radial line which is the correct line for cutting the ends of the cants. If the board is too long to carry to the band-saw conveniently,



cut off with the handsaw a piece just long enough for the segment. Saw out this one segment, using it as a pattern with which to mark out all the other nineteen cants required. This pattern segment should be cut out so that it will be a little too long; then the others, when marked out by it, may be cut to the mark and still be long enough to allow for fitting, as




FIG. 125.

the joints must be exact. Now saw out four more and then proceed to fasten them on the chuck. The others may be sawn out while the glue is drying. A trimmer or shoot-board will be needed on which to shoot or plane the ends of the pieces. The shoot-board and the method of its use are shown in Fig. 125. The trimmer is a more complicated machine and is



represented in the frontispiece., Plane or trim both ends of one of the segments and drive a 2-inch brad into it at each end from the top side almost through it; put some glue on the ends and on the under side, and place it on the chuck just inside the circle already made, driving the brads down until the heads protrude just far enough so that they may afterwards be withdrawn with the claw-hammer. Now fit another segment up to this one, being sure that it makes a good joint, especially on the inside of the ring, for if the joint is not good the small triangular pieces formed in cutting the segments will be torn out by the chisel during the process of turning. The second piece may now be glued into place, being sure as before to put glue on **both ends** and also on the **end of the piece** that is in **place**. Thus the ends of the pieces are glued twice, which is very necessary if a strong joint is wanted. This is called **sizing** the joint. If it is not done, the first coat of glue will be absorbed by the wood and the joint will be weak. This course may be followed until the first ring or layer of segments is complete, when it should be allowed to dry. After the glue is dry, the brads may be pulled out and the chuck put in the lathe and the ring faced off, making it true in both directions. The next layer may now be put on in the same way. The ends of the cants should be placed about in the center of those in the lower layer so as to break joints.

The above is the method usually followed in making this form of pattern when the cross-section of the ring is small—that is, of  $\frac{3}{4}$  inch, or less. If the ring is to be 1 inch or more thick, it is best to use hand-screws

to hold the different layers down until the glue is dry. If simply a ring is wanted that is 1 inch or more in thickness, and we are sure there is no cutting to be done on it in the future, then the brads may be driven clear in and left in the work, except in the first layer. This will, of course, obviate the waiting for the glue to dry, so that a ring may be built up very rapidly. Zinc nails or wooden pegs may also be used in this




FIG. 126.

class of work, but if a good quality of glue is used, they are not necessary. The work is now ready for the lathe. It is advisable before turning it to glue up the stuff for the arms and hub; then we need not wait for the glue to dry, as it will dry by the time the rim is turned, unless this is done much more quickly than it usually is.

There are two general ways of building up the spider, as it is sometimes called, of a pulley; which is the better way is determined by the size, number of arms, and some other things. One way is what is known

as **checking** the arms together, and then gluing the boss on afterwards. This is a good way, if care is taken so that they fit exactly. If they are made too tight, however, the ends are likely to be bent out of the correct position by the springing of the timber. This method, of course, cannot be used for spiders having an odd number of arms. A better way for most work is to miter the arms together. The only objection to this method is that it is comparatively weak. But this defect is easily overcome; for, if there is no hub or boss required, a recess may be turned into the arms after they are glued together, and a piece of hardwood, or metal, set in and a screw put into each arm, as shown in Fig. 126. If a hub is wanted, and it usually is, this will give the required strength. This method may be used for spiders of any number of arms.

To make the spider, then, for this pattern and in the last mentioned way, the first thing to do is to get out eight pieces,  $4\frac{1}{2}$  inches long, 2 inches wide, and about  $\frac{5}{16}$  inch thick; cut one end of each piece so as to make an angle of 90 degrees at an angle of 135 degrees to each edge. Now saw out on the band-saw, or jig-saw, two disks about 3 inches in diameter, and  $1\frac{1}{4}$  inches thick, and glue four of the thin pieces on to each disk, with the point of the 90-degree angle directly in the center. The best way to do this is to start three 1-inch brads, one in each corner of each of the triangles; put on some glue, lay the piece in place and drive the nails down, leaving the heads projecting so the brads may be afterwards withdrawn with the claw-hammer or pincers. Now these may be set aside to allow the glue to dry. The way these five pieces will appear after

being glued together is shown by Fig. 127. While these are drying, the chuck, with the built-up rim on it, may be put in the lathe and the rim turned to size. The extreme outside diameter should be  $8\frac{3}{8}$  inches. This is at the central plane through the hollow cylinder. At the ends of the hollow cylinder, or rim, that is at the point where it is glued to the chuck, and the




FIG. 127.

opposite or outer end, the diameter should be  $8\frac{1}{4}$  inches. These measurements must be made with the shrink rule. Before starting the lathe, see to it that it will not run too fast. The work to be turned should run at a surface velocity of from 1200 to 1400 feet per minute for pine wood. This will also give very satisfactory results on all ordinary soft wood. If the wood is unduly soft, a higher speed may be required. It may run much faster than this with safety, but it is best to keep the speed down as low as may be and still do good work. The work in hand should be run comparatively slow at first, so as to turn off any inequalities of building, both on the inside and outside; as the

work becomes cylindrical in form, a higher rate of speed may be used. The inside had better be turned first, and a diamond-pointed tool will be the best to rough it out with, using a regular scraper for the finishing. The size inside at the center will be  $7\frac{1}{2}$  inches in diameter, at the two ends  $7\frac{5}{8}$  inches in diameter. Finish the outer end back to a short distance beyond the center; in other words, back far enough to make a little more than one-half of the rim, which will be  $1\frac{5}{8}$  inches.

When it has been turned as suggested, it is ready to be cut off. Locate the cutting-off point by holding a pencil exactly  $1\frac{5}{8}$  inches from the edge, while it is revolving; this will make a mark at the proper point. Now take a parting tool, and cut into the work just outside this mark and almost through, leaving a very thin section which may be cut through with a knife. It is not good practice to cut clear through, for the work may fall on the floor, receiving more damage than can be repaired in the time it takes to cut it off with a knife. If the work has been done correctly, we have one-half of the required rim. As for the other half, it is already turned to size at the outer end, and all that needs to be done is to turn the rest of it to the size and shape of the first one.

Before being cut off, both of these halves should be thoroughly sandpapered, first with coarse, and then with finer; No. 2 for the coarse, and No. 1 for the fine are the best numbers to use. As soon as they are taken from the lathe, it is well to give the rims a good coat of black varnish; this will prevent, to a degree, their tendency to warp out of shape.

The spiders are probably dry by this time, so that work can be resumed on them. First, they must be planed to a perfectly plane surface on what will be the parting in the completed pattern, so that they will exactly fit each other. Now take the chuck you have just used for turning the rim, and face it off to a surface that is a very little concave; then while the lathe is revolving, make a circle about the size of the disk in the spider. Set one-half of the spider on the chuck so that the disk coincides with this circle, and drive a brad in two of the arms and into the chuck. Before doing this, though, it is well to select two 1-inch screws, and with brace and drill bore a hole through two of the arms just the size to fit the screws; these holes should be countersunk for the head of the screw, so that they will set in below the surface of the arms, to permit of their being turned to the proper thickness. Now the half spider may be set as suggested, and the brads driven far enough so that they will hold the spider while the screws are being turned in. With the scraping tool face off the whole thing in order to true up the faces so that a mark can be made, and make a circle on the face of the arms equal in diameter to the outside of the rim on the center of the pattern. Notice that this is where the arms will finally be joined to the rim. **Inside** of this circle the arms will be cut down to the required thickness ( $\frac{1}{4}$  inch), and to the required thickness at the hub ( $\frac{5}{16}$  inch). The surface of the arms should be a straight line between these two points. The hub can now be turned to size ( $2\frac{1}{4}$  inches in diameter). There must be a fillet in the **angle** between the arms and hub of about  $\frac{1}{4}$ -inch

radius. In the center of the hub turn a hole about  $\frac{3}{4}$  inch in diameter, and  $\frac{1}{2}$  inch deep, to receive a core-print. Sandpaper the hub and also the arms for a short distance from the hub, taking care not to get your fingers caught by the arms as they swing around. On the arms should be marked a circle whose diameter is the same as the inside of the rim at the center of the pattern. This circle will serve two purposes, as it furnishes a place to space around to locate the center of the arms, and also locates the point of tangency between the arm and the fillet that must be formed on the arm. Another circle should be made on the arms around the hub; this may be about 3 inches in diameter; the exact size is not material. Now this half may be removed and the other half put on and treated in the same way, except that the two circles last mentioned need not be made. The next thing to do is to lay out the lines for the shape of the arms. First make a mark that is exactly radial along the whole length of one arm, and as near the center as can be. Starting from this line, by the use of the dividers divide the circle near the outer end of the arms into four spaces; the points thus formed will locate the center line of each of the arms. Divide the circle that is near the hub in the same way, starting from the same line. Set the dividers to one-half the width of the arms at these points, and make marks on each side of these points; these marks will locate the sides of the arms; now with a short straight-edge join the marks by a line; these last marks will locate the sides of the arms. It is required to have fillets at the intersection of the last made lines and the outer circle, which may be marked out by setting the

dividers to the required radius ( $\frac{1}{4}$  inch), and describing an arc that shall be tangent to the straight line and the circle. Fillets are also required at the point where the arm joins the hub; these should be tangent to a circle about  $\frac{1}{4}$  inch out from the hub, and to both arms, the radius to be such that one arc shall touch all three points. The sides of the part of the arms that are set into the rim are now to be located and marked. This is done by making a mark parallel with the center line of the arm; it should start from the point of tangency of the fillet arc and the circle representing the inside of the rim, and should extend to the end of the arm. All of the above marks should be on the same side as the hub. The laying out of these arms is clearly shown by Fig. 128. Part of this figure shows one of the arms cut to shape ready to be set into the rim.

Next put the two half spiders together so that one of the hubs shall be exactly over the other, or exactly concentric, and fasten them temporarily by driving a small brad through two of the arms. These brads had better be put as near the end of the arms as may be. With a brace and  $\frac{5}{16}$ -inch auger-bit bore holes for pattern pins through two of the arms. These pins should be located so that they will not be symmetrical with the center of the pattern; that is, one should be about  $\frac{3}{4}$  inch further from the center than the other, so that when the two halves are put together incorrectly the error may readily be seen. These are now ready to be sawn out, which can be done either on the band-saw, jig-saw, or with the key-hole saw, sawing out one-half at a time. This will be easy to do in the



case of the first half, but in that of the other, not so easy; for, as the second has been marked from the first one, the marks will be on the flat side, so that the hub will come on the under side. To do the work more easily, take a small block of wood with one dimension




FIG. 128.

equal to the distance that the hub projects above the arms, and set it under the end of each arm as it is being sawn. It will be safer to drive a brad through the arm into the block, so that in moving it around on the table of the sawing machine it cannot get out of place. If it is preferred, both halves may be sawn at once; but if this is done, the pattern pins should first be put in so as to make sure that the two halves will be exactly alike, and will set over each other just right. After these are sawn out they must be filed nicely to the

lines; then with knife or chisel give them the required elliptical form by rounding off the corners and blending in all the curves with each other so that a uniform surface is produced.

The rims and spiders are now ready to be put together. Lay one of the half rims on the bench with the side up that will be the center of the pattern, and lay on one of the half spiders. If everything has been done as directed, they will be self-centering because of the extra thickness that was left on the end of the arms when turning them. If this has not been done, they may be centered by the use of inside calipers, measuring from the side of the rim to the hub on three or more sides. This should be done very carefully, for if the hub is not in the center it will not look very well when the hole is bored for the shaft, and of course it will not be balanced. When the spider has been correctly located, make a mark with a knife on the edge of the rim on both sides of each arm; before taking the spider off be sure to mark one of the arms and the place where it belongs, so that it can be put back into the same position. Now set a gage to the thickness of the ends of the arms, and gage a line parallel with the edge of the rim between the marks on the edge for the recess for the arms. Now saw down to this gage mark and remove the wood, making a nice clean gain exactly to lines. Now the arms may be glued and nailed in place.

The other half should be treated in the same way. Before marking recesses, lay them together and notice if everything is coming concentric; if not, you can change the position of the second spider slightly, so

as to make it right. After getting them together in this way, the extra length of the arms may be sawn off and the parts smoothed up. Two core-prints will




FIG. 129.

be wanted for the hubs; these, of course, will be tapered because the core will be vertical. A coat of varnish should be put on the spider, the rim having been varnished before. The whole thing is now ready to be finished. First, fill up with beeswax any small

holes and any other defects in wood or work. A fillet is needed on the inside of the rim, on the side of each arm of both halves. This can also be of wax, put in with a filleting tool of one-half inch diameter. Further directions for finishing will be found on page 225. To make this job complete, a core-box will be needed, the same as one described on page 139, Fig. 109, except as to dimensions.

The next example to be taken up is typical of a large and interesting class of patterns, and belongs to the general class known as **parted patterns**. One interesting feature of this example is the fact that to produce the casting, one core of each of the two general classes of cores mentioned in Chapter X, viz., vertical and horizontal, are required. The drawing representing the casting is given in Fig. 129 and the drawing of the pattern to produce that casting in Fig. 130. Before starting to build this pattern it should be noticed that the pattern-maker's parting is through the axis of one cylinder and the center of the length of the other, so that the central web will be parallel with the parting. This central web is  $\frac{5}{8}$  inch thick, and will be made of two pieces  $\frac{5}{16}$  inch thick, 4 inches wide and 9 inches long, or large enough so that the outline in the right-hand view of Fig. 130 may be drawn on them, with the exception of the core-prints of the larger cylinder. These two pieces should be planed flat and smooth and then fastened together side to side temporarily by driving two small brads through them. Now lay out on both sides of this double piece the




FIG. 130.

outline as it appears in the right-hand view of Fig. 130, observing to locate both sets of lines so they will be exactly over each other. Now locate and bore holes for two pattern pins, boring the holes through both pieces. Get out and glue together two or more pieces, from which to turn the larger cylinder, being sure to make them long enough to include core-prints. While the glue is drying, get out stock and turn to size the smaller cylinder, remembering that core-prints are



FIG. 131.

needed on this also. The best form in which to turn this is indicated by Fig. 131, both being turned from the same piece of wood. These may now be nailed in place inside the circles already drawn for them on the double web piece. Next turn the larger cylinder to size, including the core-prints. There are two ways this may be fastened to the web part of the pattern. One is to saw off enough from two sides of the cylinder so that when they are glued to the web they will equal the diameter of the cylinder. These may now be glued on, locating them by the center lines already drawn on the web pieces. The other way, which is in some respects the better way, is to put together two pieces of wood as was done for the second example, Fig. 116, and do not forget the core-prints, but turn them at the same time. Cut the web pieces off at the center line of the

cylinder, and cut a recess in each half of the cylinder, the depth of recess to equal the thickness of one of the web pieces, measuring from the flat surface of the half cylinder, and extending to the center of the cylinder. Do not cut this recess into the core-prints. This recess must be cut of an even depth so that the diameter line of the half cylinder and one side of the web shall be in the same plane when put together. Of course both halves must be treated in the same way. This makes a good workmanlike job, leaving no end grain at that end of the pattern as would be the case if it was built the other way. After fastening the cylinders in place the cross webs may be made, fitted and fastened in place. The corners of the web pieces should be rounded before they are fastened in place, as it can now be done with a plane. The pattern pins may now be put in, the two halves put together and finished up. The small fillets required may be put in with wax after the first coat of varnish is dry. These fillets should extend throughout all internal angles, except those between the pattern and core-prints. The two core-boxes may now be made. As these are of the same general shape already described, it will not be necessary to repeat that description here.

The pattern and core-boxes may now be finished as directed on page 225.

## CHAPTER XV

### PATTERNS FOR CAST GEARS

The next class of work to be taken up requires the greatest amount of care and attention on the part of the pattern-maker, as in order to obtain the best results his work must be correct in all its details. The class of work referred to is the making of gear patterns, especially patterns for what are known as **cast gears**. By this is meant gears of which the teeth are **cast** to the required size and shape.

There are two general ways of manufacturing gears. One way is to cast what is known as a **gear blank**, which is turned to size and the teeth cut from the solid metal. This is the method usually employed for small work, and for gears that are required to run very smoothly. They are spoken of as a class as **cut gears**. But if the gears are large and of coarse pitch, the patterns are made with the teeth of the approximate size of the finished teeth. That is, each surface of each tooth on the pattern is treated the same as a finished surface on any pattern, i. e., about one-eighth inch is allowed for finishing or machining. After the casting is made, the teeth are cut on the gear cutter just as the full blank would be for a small gear. Casting them in this way, of course, saves an immense amount of cutting, thereby economizing on time and the wear of cutters.

The other of the two ways of manufacturing gears



is by making a pattern of the gear with teeth complete, and then making a casting from that pattern. Gears made in this way are called **cast gears**, and the making of patterns for this purpose will now be explained:

It best serves the purpose of this volume to illustrate some general principles in regard to making gear




FIG. 132.

patterns that can be applied by the student to any particular case. Consequently, in preference to a gear of any specific size, patterns for cast gears in general will be considered. The part to be considered first is the rim or periphery of the wheel, to which the teeth are fastened. There are several ways that this may be built up; the difference is mainly in regard to the

method of holding it in the lathe while being turned. The actual building should be done as explained for the pulley rim, that is, with segmental pieces of wood of the required size and thickness. As the cross-section is of somewhat different shape, the segments will of course vary also. If the gear is to be large enough so that both sides can be gotten at at the same time while running in the lathe, the best way is to build up the rim on what may be called a three-armed chuck. This is made as illustrated by Fig. 132. The width of the arms will be determined by the size of the gear. For gears up to two feet in diameter, pieces  $\frac{7}{8}$  inch thick by 3 inches wide will be heavy enough. The length of the arm will be equal to the radius of the rim only. These arms are to be mitered and fastened to a disk a little larger than the face-plate that it is proposed to use; the fastening is to be done with screws, as indicated, Fig. 132. The face-plate should be put on, and the chuck put on the lathe; then the face of the arms, for a distance somewhat more than the width of the stock for the rim, should be faced off true.

It is now ready to have the segments glued on for the rim. As will be seen, the first row of segments must be made up of three pieces and jointed in the center of each arm. After this is glued in place, the rest of the structure may be made up of shorter ones, in fact, of any length desired. The building process should be continued in this way until completed, leaving the arms of the chuck as near the center of the rim as possible.

It is now ready to be turned to size and shape as shown in Fig. 133, which should be done with scrap-

ing tools; it should be tested for shape with a templet. It is not well to cut the arms down too thin until the teeth blocks have all been glued on and turned to size. In other words, all the turning to be done should be completed before cutting into the chuck arms very much; otherwise the rim may spring. When all the other turning is done, the arms may be cut almost




FIG. 133.

through with very little danger. Of course the more nearly through they are cut, the less work will have to be done by hand after it is taken from the lathe; this should be left, however, until the tooth blocks are glued on and the turning all done.

The next thing to do is to mark out the spaces in which to fasten the tooth blocks. If the pitch of the gear is not more than 1 inch, these blocks may be made of such a size that, allowing one for each tooth, they will

form a complete circumference around the rim. The grain of the blocks must be perpendicular to the side of the gear, or, in other words, parallel with the axis of the wheel. They should be made of good, clear, straight-grained wood, thoroughly seasoned. Some kind of hardwood such as mahogany or cherry is best at least for standard patterns.



FIG. 134.

There are several ways of putting these blocks on the rim. Three ways will be explained that will include all the practical ideas and principles of this branch of pattern-making. In all three, the rim at its present stage will be laid out in the same way, that is, spaced into as many spaces as it is required to have teeth in the wheel. The three ways spoken of will be more clearly understood by referring to Fig. 134.

The method shown by the tooth A is what may be called the cheap way. In this case the teeth are formed before being fastened in place. They may be formed

in two ways. One is to plane up strips of wood to the desired shape, and then cut them off to the required length. A better way is to make a box as illustrated by Fig. 135, each block being cut to exact length and held in place by a screw, as shown. Fig. 136 shows the method of getting the shape of this box. In using




FIG. 135.

this box, care must be taken not to cut away any part of it in planing the tooth to shape. To locate a tooth on the rim, set the dividers to exactly half its thickness; place one leg on the center marks already made, and with the other leg make a mark on each side; these marks will indicate the position for the sides of the tooth. Of course these marks must be squared across the face of the rim so that the teeth may set square. When gluing them on use a try-square to test them; do not depend wholly on the marks for this. The above method does very well for a job where only one or two wheels are wanted, and for cases where it is not desired to go to the expense of a good job of pattern-making. The second way is to glue all the blocks on the rim, lay them out in that position, and then cut to the lines. This makes a good job when prop-

erly done, but it is rather inconvenient to cut the teeth, especially if the face of the gear is very wide. There is another way that is known as the dove-tailing method, so named because each tooth is glued to a thin block let in to the rim. One disadvantage of this way is, that if the dovetails are driven a little too tight, it is very likely that the rim will be sprung, and the resulting casting will not be round. About the only advantage claimed for this method is that one or more




FIG. 136.

of the teeth may be removed and used by the molder for patching up a broken mold; but this can be attained in another way. The method of dovetailing is illustrated at B, Fig. 134. It is a very expensive method, and is now almost obsolete.

The best way to fasten and form the teeth on gear patterns is the one shown in the center of Fig. 134. It should be used on all standard patterns. This method was first published by P. G. Dingey in the "American Machinist." Before entering into the details of this way, some of its advantages should be noticed. It does away entirely with the objection mentioned in connection with the dovetailing method, viz., springing the rim by driving the dovetails; and at the same time it permits that one or more of the teeth be removed by the molder, if necessary. Another great advantage gained is that the fillets are made in solid wood, thus producing a much smoother pattern and

casting. None of the other methods shown have this advantage. In the dovetailing method a very thin edge must necessarily be left at this point. In the first method described a wax fillet would generally be used, which in the course of frequent use is very liable to be loosened by the shrinking and swelling of the wood, leaving the pattern rough just where it ought to be the smoothest. Another advantage in the method under consideration is that one-half of the teeth being fastened on with screws, each alternate tooth may be removed, thus making room for working those glued on.

In this method the first thing to be done, after building up the rim, is to turn the rim down about  $\frac{1}{2}$  inch smaller in diameter than the diameter of the whole depth circle, or to the point lettered D in Fig. 134. Then, of course, the tooth blocks will have to be made larger by that amount than the size of the tooth proper. After the rim is turned to size it should be spaced as previously suggested. This should be done accurately so that each tooth may come in the center of each block. One set of lines will do if the pitch of the gear is not too coarse to allow the stock of which the tooth blocks are to be made, to fill the spaces. Otherwise, two sets of lines will be required, and pieces must be glued in between the blocks, as represented at E, Fig. 134. When the blocks are ready and the rim is marked out, one of the blocks may be glued in place. Do not get too much glue on, as it will be likely to make trouble in putting on the next block, for this is to be fastened on without any glue. With a brace, and a bit, of the proper size for the screws to be used, bore two holes through the rim as near the center of the space for the

next block as may be; counter-sink them on the inside of the rim to receive the heads of the screws. Hold the second block in position, and with a brad or small drill mark on the block the places for the screws, and bore them with a suitable sized drill. Now, holding the block in position again, insert the screws, driving them in until the heads are slightly below the surface of the rim. This process should be carried on until the blocks are all fastened on. Be very careful **not** to glue the blocks together for at least half an inch from the surface of the rim, and also **not** to glue the blocks having screws, to the rim, or it will make trouble later on. In getting out the blocks for any of the last three methods described, they should be made about one-eighth inch longer than finished size, and then turned off in the lathe so as to make a good smooth surface on which to lay out the pitch circle, base circle and tooth curves, and also on which the spacing of the teeth may be done. When the blocks have been glued on and allowed to dry, the whole of the work should be put in the lathe, the ends of the tooth blocks turned off even with the edge of the rim, and the face turned down to the required size. After this is done, a coat of yellow varnish may be put on the parts that are to form the teeth. This makes a much better surface on which to make lines than does the bare wood.

There are several ways of laying out the tooth curves on the pattern. First, however, it must be decided what method is to be used for developing these tooth curves. These may be developed by the epicycloidal curve, by the odontograph, or by the involute curve. It is not intended in this volume to enter into



a discussion of the merits or demerits of any one of these systems, or even to explain them, but simply to call attention to them and to indicate one or two ways of applying them to the pattern. Theoretically, the use of the odontograph is probably the best, especially for large work; but for comparatively small work a careful use of the dividers will give as good results, and if only single curve, or involutes, are desired, the use of the dividers afford the quickest way. In deciding what method of development is to be used, one or two further facts should be considered. The involute form will give uniform angular velocity if the distance between the centers of any two gears does not remain uniform, as, for instance, in the feed rolls of the common rotary knife planer. Other forms of teeth will not do this. Again, if dividers are used for marking out these forms on the pattern, the single curve is much more quickly laid out. The single curve method is fully illustrated by Fig. 137, and is what may be called a simple shop method. It can be used to advantage when the data supplied by the draftsman to the pattern-maker does not indicate any particular method.

The first thing that needs to be known is the pitch and number of teeth. Of course this was learned before building up the pattern; so all that needs now to be done is to apply this knowledge to the work.

In order that the student may apply this knowledge intelligently it will be well for him to make a copy of Fig. 137, using data obtained by computing the different dimensions for some specified gear; for instance, a gear that must have 45 teeth,  $1\frac{1}{2}$  inches circular pitch, single curve involute tooth curves. To find the diameter

of the gear, which is the first thing to do, multiply the number of teeth by the circular pitch— $45 \times 1\frac{1}{2}$  inches = 67.5 inches  $\div$  3.1416 =  $21\frac{1}{2}$  inches, = diameter of the gear. Then the **radius** of the gear and also of the pitch circle will be  $10\frac{3}{4}$  inches. With this as radius, draw arc, A. Now set the dividers to  $1\frac{1}{2}$  inches (the circular pitch), and space off four or five spaces along the arc A for the centers of the teeth. Next space off the thickness of the teeth, a, which, according to the data given in connection with Fig. 137, is  $\frac{7}{15}$  of the pitch— $\frac{7}{15}$  of  $1\frac{1}{2}$  inches =  $\frac{11}{8}$  inch; set the dividers to one-half of this and set off on each side of the center points already located. This will leave  $\frac{8}{15}$  of an inch, or approximately  $\frac{13}{18}$  inch for spaces between the teeth. Compute the distance, c, the face of the tooth, which must be  $\frac{5}{15}$  of the pitch, or approximately  $\frac{3}{4}$  inch; measure that distance outside of arc A, and describe another arc B, thus forming the addendum circle. Now draw arc F with radius equal to  $\frac{1}{4}$  of the pitch **diameter**, viz.,  $5\frac{3}{8}$  inches. Next set dividers to a distance equal to  $\frac{1}{4}$  of the pitch **radius**; set one leg of the dividers in one of the points representing the sides of the teeth and draw arc G. The point where arcs F and G intersect is the point through which to draw the **base circle** C; draw base circle through this point. Now set dividers to radius of arc G, and, with one leg on this base circle as center, draw the tooth curves through the points already located. The making of this drawing on paper will furnish all that is necessary for laying out the teeth on the pattern, which may now be done.

The first line to put on the work will be the pitch circle; divide this into as many equal parts as there are to be teeth in the gear; this is for the purpose of locating the center of each tooth. In doing this it will be found advantageous to commence at one side of




FIG. 137.

the center of tooth block for the trial spacing; then having the dividers set to the correct distance, start from the center of a block. Then there will not be several points to confuse one in fixing the correct one for the center of the tooth, as is likely to be the case

if the centers of the blocks are used for the trial division. Now set the dividers to one-half of the tooth thickness as derived from Fig. 137 at a, and mark a point on each side of the tooth centers; this will locate the sides of the teeth. The base circle C, Fig. 137, should now be put on; its diameter is found as indicated by arcs F and G. Now setting the dividers to one-fourth of the radius gear, as at G, Fig. 137; proceed to describe tooth curves, being very careful that the arc runs through the points located for the side of the tooth on the pitch circle. The centers for these tooth curves are all on the base circle. At the points where these tooth curves intersect the addendum circle, B, Fig. 137, lines must be drawn square across the face of the pattern, and the opposite side laid out with corresponding curves, each curve starting from the point where these squared lines intersect the corner. Arcs with radius of  $\frac{1}{6}$  of  $f$  for fillets at the base of all the teeth will now be put in, which will complete the laying out of the teeth.

The next work to be done is to saw out on a band-saw, if one is available, the wood between the teeth to form the spaces. This should be done very carefully; leave one-half of the marks on the work so that there will remain very little to be done with chisel and gouge. The fillets will have to be made with small gouge, as the ordinary band-saw is too wide to turn in so small a curve as is required in small or medium sized work. If a gear of coarse pitch was being made, there would be little difficulty in making the saw do most of that work also. If the teeth were put on the rim as suggested for standard work—that is, each alternate tooth glued

on, and the others fastened with screws—then by taking out those with screws, the finishing can be done very easily; the teeth so taken out should be numbered and corresponding numbers put on the spaces, so that they may be put back in their proper places after being finished. The temporary arms of the chuck may now be cut through, thus finishing up the work of making the rim and teeth. The shape of this rim may be more clearly seen by referring to Fig. 133. The way of attaching the arms also is shown in this figure, as well as in Fig. 134.

The next process is to make the spider, or arms. This may be done as described in the making of the 8-inch pulley pattern, except that in this case they must be made of one thickness and fastened in as shown in Figs. 133 and 134.

As these arms are made of one thickness, one side will be turned up after the face-plate is removed. This may be done in a cup-chuck shown by Fig. 56, in the chapter on Turning. In this case the cup will be turned out to fit the hub already turned. The arms will be made of the same elliptical shape and in the same way as described in the case of the 8-inch pulley, Fig. 124.

## BEVEL GEAR PATTERNS.

Before taking up the construction of bevel gear patterns, it will be well to say something about the lines required for laying them out. The first thing is to make two lines at right angles to each other, to repre-




FIG. 138.

sent the center line of the shafts on which the bevel gears are to be fastened. Bevel gears may be made to run shafts at other angles than right angles; if this is required, the first two lines laid down must be drawn to this angle. The next step is to determine the size and the ratio of the pair of bevel gears to be made.

The pitch diameter of a bevel gear is always measured at the large end. The pitch of the teeth is also measured and calculated for this end. Having determined on the size of the gear, set the dividers to the pitch radius of the gear and prick off this, equidistant from line A B, in Fig. 138, which will give the pitch diameter. Now proceed by laying down the other lines as




FIG. 139.

in Fig. 138. Notice that the teeth are not developed on the pitch circle, but on a projected circle, the center of which is obtained by producing the line that forms the end of the teeth back until it intersects the center line of the gear at H; the small end is treated in the same way, which locates the center for that end at I. The dimensions of tooth elements may be obtained from Fig. 137. The drawing makes it clear as to how a bevel gear should be laid out.

The building of the pattern may now be considered. The first thing to do is to select a chuck of proper size, if we have one, or make one if we have not. A chuck

for this purpose may be built as shown by Figs. 139 or 140, if very large. The rim at A may be left off if thought best; but its presence is an advantage if it becomes necessary to use handscrews for holding the material on the chuck during the process of gluing, for the handscrews may all be set to the same size, and so more quickly applied. This is quite an advan-




FIG. 140.

tage, because the glue dries very quickly. The chuck will need to be faced off to a true surface, and some fairly thick paper glued on the part where the segments for the rim are to be fastened on. With this exception, the process of building this rim will be the same as for the 8-inch pulley. The laying out and the sawing of the cants will also be the same, except that each layer will have to be described with different radii. The necessity for this will be readily seen by consulting Fig. 141, which shows the rim as it will appear after being built on to the chuck, and before it is turned. When there have been enough segments



built on, and the glue has dried, it is ready to be turned to shape, as shown by Fig. 141; in turning it, get around into the work at point P as far as possible.

It is now ready to be taken off the chuck, which can very readily be done by introducing a chisel between




FIG. 141.




FIG. 142.

the work and the chuck, and driving it lightly at several places around the circumference. This will cause the paper that is glued between the work and chuck to split, allowing the work to come off, without any damage to either. The rim must now be mounted on the chuck, with the opposite side out. The best way to locate it on the chuck so that it will be concentric with the lathe spindle (as it must be in order that the inside and outside may be concentric) is to turn a small V-

shaped groove into the chuck that will exactly fit the corner of the rim at the point marked R, Fig. 142. The work must be fastened to the chuck this time with screws put through the chuck. To do this, bore holes through the chuck, at the bottom of the V-groove just made, of a suitable size for the screws selected. The number of screws to be used will, of course, be deter-




FIG. 143.




FIG. 144.

mined by the size of the work; from four to six will be enough for work up to three feet in diameter. Now take the chuck off the lathe, and, having laid the rim on the bench with its proper side up, lay the chuck on it and drive the screws through the chuck into the rim. It is now ready for the lathe again, and may be turned to the size and shape indicated at S and S, Fig. 142. Turn it small enough so that the tooth blocks may be put on as indicated at K, Fig. 143, and more plainly shown in Fig. 134 at C C. The arms may now be made, and mitered together in the center, with a piece on each side for strength; the same pieces also serve as fillets, as indicated at B, Fig. 144. The arms

should be set into the rims as shown at D, Fig. 144, before the work is taken from the chuck. The vertical arms C C, with the central hub E, must be left loose so they will lift with the cope. These will be built together as shown by Fig. 145.



FIG. 145.

## CHAPTER XVI

### PIPE FITTINGS

Another large and interesting class of patterns are those required in the manufacture of cast-iron pipe fittings, two types of which will now be taken up. The castings are what is known as a bend, shown at Fig. 146, and an elbow, shown at Fig. 153. The larger part




FIG. 146.

of the pattern work can be done on the lathe for both of these examples.

The pipe bend will be taken up first. The first thing to do is to prepare a chuck large enough in diameter, turn its face perfectly flat, and glue paper all over it.

The stock required, as illustrated by Fig. 147, must be large enough to contain the size of pattern it is proposed to build, indicated by the circle on the figure.

This should be put on the chuck in two pieces, as shown in the cut; each half has one side and one edge planed straight and at right angles to each other, as




FIG. 147.




FIG. 148.

the edges are to form the joint. These must be so placed on the lathe that the joint shall be exactly on the center of the lathe. The best way to do this has already been explained in connection with core-box ends, page 146. They are now to be turned to the shape

indicated by Fig. 148. The next parts to be made are those shown at Fig. 149. These must be made in halves and turned. Before they are turned, a pattern pin should be put into each, so that it will not have to be done after the pattern is completed. It is always




FIG. 149.




FIG. 150.

best to put in these pins before the turning is done. After the pieces are turned, the parts should be fitted together as shown at Fig. 150. The part marked a should be made square, as shown at e, Fig. 149. Of course, both halves are to be made in the same way. The core-box for this pattern is shown at Fig. 151. The circular part d can be made on the lathe; the way is clearly shown in Fig. 152. The grooves marked b may be made in one piece of lumber, and made, of

course, with the core-box plane. If it is desired to make this very strong, a piece of board is nailed on the bottom, as indicated at c.




FIG. 151.




FIG. 152.




FIG. 153.

As elbows are usually cast in pairs to save work in the foundry, the pattern must be made double. The economy resulting is great, as it will take but very

little more of the molder's time to make the mold for both than for one. Besides the core can be more easily set and held in place if two are made in the one mold. If only one is made, a chaplet would be needed to hold the core; or else very long prints would have to be put on the pattern, either of which would increase the work of the molder.




FIG. 154.

The pattern for the elbow is a little more complicated than for the bend, though the work is quite similar in character. It is made as follows: A ring, as shown at Fig. 154, is first turned, with its cross-section as indicated at a. The best way to make this is to get out four pieces with the grain as indicated in the figure; that is, the chord of the curve should be parallel with the grain of the wood. Fit them together very accurately, and glue them to a chuck (but not to each other) that has been previously covered with paper, and turn them to the required shape. A solid piece



may be used and cut into the required number of pieces after being turned, but this method is not as good. In mounting these pieces on the chuck, care should be




FIG. 155.

taken to see that the point where they meet is exactly on the center of the lathe. Now two pieces are required like Fig. 155. These will be made in halves and




FIG. 156.

turned. Both will be alike, except that on one the shape at A will be left the full size and of a length to equal A in Fig. 156. The one made like Fig. 155 will be cut in two, the parts B and C squared as at E,

Fig. 149. They are then fitted into the first piece as shown at B and C, Fig. 156.

The core-box to go with this pattern is shown at




FIG. 157.

Fig. 157. The circular parts A and B can, of course, be made on the lathe in the same way as for the core-box shown at Fig. 151.

## CHAPTER XVII

### ESTIMATING WEIGHT OF CASTINGS

As the pattern-maker is frequently required to estimate the weight of a casting from the pattern, and sometimes even from the drawing, with more or less accuracy, we will here point out some of the methods employed in arriving at such an estimate. The degree of accuracy demanded is generally determined by the value of the metal or by the purpose of the required casting. In the case of large castings it may be sufficient to arrive at the weight within two or three hundred pounds, but for small castings it may be necessary to come within one pound or even a few ounces. One way in which this may be done is to calculate the number of cubic feet in a large casting or cubic inches in a small one, and then convert this number into pounds by multiplying it by a given constant. The constant will of course be different for each kind of metal. A list of constants for this purpose for metals in common use may be found at the end of this chapter.

When the weight of a given casting is required, the following rule is applied: First, find by measurement and calculation the cubical contents of the pattern in feet or inches; multiply this by the given constant for the metal to be used; the quotient is the number of pounds the casting may be expected to weigh. We use the word "expected" advisedly, as there are so many contingencies that may arise in the making of the casting over which the pattern-maker has no con-

trol that the estimate made can be only an approximate one. One of these contingencies is the **rapping** of the pattern which may make an appreciable difference in the weight of small castings. Another is the different densities of the metal in the same mold, which will cause variations that cannot be computed. Again, a mold that is unevenly rammed—harder and softer in different parts—will make a casting that will vary in weight. The softer parts of the mold will allow the casting to swell, and so, being larger than the pattern, will be heavier than calculated. These and many other things will interfere to make the weight of a casting vary from its calculated weight.

The most accurate way to obtain the weight of a casting from the pattern is by what is known as specific gravity. The pattern is steadily immersed in water in a tank, the displaced water is allowed to overflow into another vessel and is then weighed. Thus, suppose a pattern displaced  $3\frac{3}{4}$  pounds of water; if this is multiplied by the specific gravity of iron (7.3), the resulting quotient will give the weight of the casting in pounds. Because of the many difficulties to be overcome, such as suitable apparatus, the injury to wood patterns, the presence of core-prints, etc., this method is not employed except where accurate weight is of great importance.

Another way is to weigh the pattern and multiply that weight by 16, the generally accepted ratio between pine wood and cast-iron. This leaves out of consideration the various densities of different specimens of wood, the presence of nails or screws or other foreign substances in the pattern, and core-prints, if any.

The best practical way is the method first mentioned, viz., ascertaining the cubical contents of the pattern and multiplying it by a known constant. This method may be used before the pattern is built, as the drawing




FIG. 158.

will give all the necessary data. The accuracy attained by this method will depend largely on the correctness with which the measurements and computations are made. To illustrate this method we will use just one example, a drawing of which is found in Fig. 158, which represents the bottom plate for a cupola furnace.

In this example the length, width and thickness may be multiplied together to obtain its cubical contents. These sizes are 9 feet 6½ inches x 8 feet 9 inches x 2 inches = 24045 cubic inches; add to this 659.73 cubic inches for the ring A, and also 192 cubic inches for four door-hinge lugs B, giving as the total 24896.73 cubic inches. From this number must be subtracted the cubical contents of the circular opening C, which is 8143.02 cubic inches, thus leaving 16753.71 cubic inches to be multiplied by the constant .263 for cast-iron, so that this casting, if made of iron, will weigh approximately 4406.22 pounds. This will be very nearly correct if the mold is rammed so that the casting is like the pattern, that is, without any swollen places.

For a rough approximation, weighing the pattern and multiplying its weight in pounds by 16 is of course the easiest and quickest way and is the one most used by foundry men in estimating the amount of iron to be melted for a heat or a certain casting.

The following constants may be used as multipliers for the metals named when cast:

TABLE OF CONSTANTS.

METAL.	WEIGHT PER CUBIC INCH.	WEIGHT PER CUBIC FOOT.
IRON.....	.263 lbs.	451 lbs.
STEEL .....	.288 lbs.	499 lbs.
BRASS.....	.3 lbs.	524 lbs.
LEAD .....	.41 lbs.	708 lbs.
COPPER.....	.32 lbs.	537 lbs.
TIN.....	.266 lbs.	451 lbs.

## CHAPTER XVIII

### MISCELLANEOUS PATTERN WORK

Fig. 160 shows a good method of building patterns that are flat, square, or rectangular, and of comparatively thin in cross section. The casting required is shown by Fig. 159. It is a common form of steam chest




FIG. 159.

cover. In building the pattern, the central part is made up of narrow strips set into a grove in the outside pieces. These are mitered together and tongues driven into grooves as shown by dotted lines at A, Fig. 160. The diagonal ribs are made and halved together and then cut to the shape shown. They should be left loose and pinned in place with pattern pins, so that the

molder may take them off in order to lay the pattern flat on the molding board during the first operation in molding. This is necessary, as in order to have the side C good and sound, it must be cast with that side down; then the ribs will come in the cope.




FIG. 160.



## SKELETON PATTERNS

The term "skeleton patterns" embraces a large variety of patterns; it refers to those that are made of a combination of wood and sand; that is, both wood and sand are used to form the complete pattern. The pattern-maker constructs the required woodwork, and




FIG. 161.

the molder makes the rest of the pattern with sand. The sand commonly used for this class of work is called loam.

One example of this class of patterns is shown by Fig. 161. It is a skeleton pattern of a pipe bend, from which only one or two castings are wanted. The drawings give a good idea of the general make-up of the pattern. The core and method of making it are

shown at Fig. 162. The parts the pattern-maker would have to make in order that the core-maker could produce this core, are the core-board, as it is called, indicated by *b* and the strickle shown at *c* in Fig. 162. The core-board is simply a piece of board planed up true on both sides, and cut to the correct shape. Its side *d* is cut in such a way that when the strickle is set at




FIG. 162.

right angles to it and slid along its length, it will give the desired size and shape to the core. When the molder uses this apparatus, he first lays this prepared core-board on an iron plate, and clamps or fastens it down so it cannot move. He piles on some sand and then slides the strickle along so that the point *E* remains in contact with edge *d*, taking care to keep it perpendicular to the straight part, and to keep the cutting edge exactly radial in passing along the curved part. If there is any point on the sand that the strickle does not touch, more sand is put on and the strickle again passed over it. This process is continued until a good smooth surface is produced. The core-board

is now removed, and the plate with the complete half core on it set into the core oven to be baked. To make the other half, the core-board is turned over and the process repeated. These two halves are baked, and, when hard, are pasted together, so forming the complete core.

The making of the pattern is carried out in a very similar way, but requires more work on the part of the pattern-maker. The first thing is to prepare two boards of suitable thickness for the job; this is determined by the size of the pattern to be made. One of these boards is shown at a Fig. 161. They will be sawn out to the shape of the pipe on its axial line, including the core prints.

These boards are pinned together the same as would be done if a complete wooden pattern was to be made. The flanges *ff* are also to be cut out so that they will fit over the board at the correct points. The semi-circular pieces *dd* are also cut out and fastened on at equal distances, and also for the core prints *cc*. Two strickles will be needed, similar to the one used for making the core, Fig. 162 *c*, one for the body of the pattern, and one for the prints. The moulder completes the pattern by laying down one of these boards on the bench, with the pieces all fastened in place, puts on sand, filling up the spaces, and then passes the strickle over it, thus making a smooth surface the same as for the core. The other half is made the same way. When the pattern is complete the molder scatters parting sand all over it so it will leave the mold freely.

Another class of skeleton patterns is illustrated

by Fig. 163. It represents a pattern for a curved cast-iron plate, over which a blacksmith or boiler-maker may bend or form a plate of wrought iron or steel. Instead of making a complete pattern, which would be a slow and expensive process, a frame is made as shown, and halved together at the corners. The rest of the pattern




FIG. 163

will be made by the molder, with the strickle, shown at A in the figure. Flat plates of large area may be made in this way, that is, with the open frame and strickles, thereby saving lumber and also a large amount of pattern work. A pattern of this kind may be molded by first bedding the frame in the nowel, or if too large for that, in the floor. Then fill the inside with sand, and strike it off even with the top; put on parting sand and then ram up the cope. Lift off and set to one side. With a strickle cut like A, Fig. 163, with shoulder B the same depth as the thickness of the plate, cut out the sand to that depth. Now take out the frame or pattern, and there is left a cavity in the sand of the size and thickness of the required casting.

## GLUING FEATHER-EDGED BOARD

In building some large patterns it becomes necessary to glue on what may be called a **feather-edged** piece of wood, in order to make a shape something like Fig. 164.

This cannot well be made with solid wood on account of the difficulty of guiding a rabbet plane along




FIG. 164.

the obtuse angle, without the corner of the iron cutting into the other side. The best way of overcoming this difficulty is to use the method as shown at Fig. 164. But this introduces another problem. How can the feather-edge be glued on and still be smooth, without a subsequent planing? Of course the trouble comes from the fact that a thin piece of wood on being made wet with glue, will, unless held in some way, warp and curl all out of shape while drying. A way of overcoming this difficulty will now be described. After having prepared both pieces to the shape indicated in the figure, get out a strip of wood about  $\frac{1}{2}$  inch by 1 inch, and long enough to extend the whole length of

the piece to be glued; drive a number of brads through it about 6 inches apart. This strip must exactly fit the whole length. Now prepare a piece or pieces of good paper about  $1\frac{1}{2}$  or 2 inches wide, and long enough to extend the whole length. Apply the glue to the feather-edged piece, put it in place, and tack it with a brad or two so that it will not slip around out of place. Then lay the paper on top of the thin feather-edge of the piece being glued on, and on this lay the strip of wood so that one edge comes exactly along and even with the thin edge; then drive the brads down, which will pull down the thin edge into place. Examine the feather-edge to see that it is down tight to the other piece. If any spots are found that are not in contact, put in another nail at that place. The paper is employed in this case to prevent the strip from sticking to the work, if by chance some glue should get on to the upper side of the thin edge. Moreover, if the edge is very thin, the glue is very likely to ooze through the pores of the wood and thus glue the strip to the work; when taken off, it would tear up some of the wood and make it rough. By interposing the paper, this is prevented.

The work should now be allowed to stand for several hours, or until the glue is thoroughly dry. If the strip be then removed, it will be found that the feather-edge has become practically one with the other piece, and all that is needed to finish the job is to sand-paper the surface.

## LARGE LATHE CHUCKS

The method of building a chuck shown at Fig. 139, on page 197 is very good for one of 12 to 20 inches in diameter; but larger ones should be built as illustrated by Fig. 140 on page 198. Of course the size will determine the number of arms required; for chucks up to four feet in diameter, four arms of two inches by six inches in cross section would be suitable; if larger than that, it would be preferable to use more arms, so that the segmental pieces joining the arms need not be so long or wide. In building all these chucks, each piece of corresponding shape and position should be of the same size and weight as nearly as possible, so that the chuck will be accurately balanced; otherwise, it will be impossible to do good work, and besides, an extra strain will be put on the lathe, which may cause an accident. If, after building a chuck, it is found to be out of balance, it can be balanced by fastening a block of wood to the back on the light side.

## LUGS OR PROJECTIONS FOR MACHINISTS' USE

Some castings must have special parts cast on them which serve the purpose of holding them in a machine while they are being worked upon, but are usually cut off after the machine work is completed. It is the pattern-maker's business to provide for these parts on the pattern. One form of such a casting is a piston-ring shown at Fig. 165. The pattern for this




FIG. 165.




FIG. 166.

should be made large enough so that two to four rings may be made from the same casting, leaving plenty of stock for finish. A good allowance for this is about  $\frac{1}{4}$  inch on each surface. The reason for this extra allowance is that these rings, being comparatively small in cross section, the metal must be very clean and sound to give the required strength. As the surface of castings is usually more or less porous, it is necessary to turn off this outside part in order to get down to the more solid metal on the inside. The pattern for a piston-ring of this size should be made as represented by Fig. 166. The projections, c, c, c, called lugs,



are for the purpose of bolting the casting to the lathe chuck while the rings are being turned. This is the usual form in which piston-ring castings are sent to the machine shop and is the best way for this particular job. If these lugs are not provided, the machinist has to grip the casting in a chuck; this is liable to spring it, so that the resulting rings will not be true, as they must be, to fit the cylinder.




FIG. 167.

Another way of providing for the convenience of the machinist is illustrated by Fig. 167. Two different methods are illustrated here—one being on the outside of the casting, the other on the inside. This casting is the column for a small drill press. It is finished the whole of the distance A, so it will have to be mounted in the lathe between centers. In order that this may be done, there will have to be a boss cast on at C and a bar cast in across the round opening at B. This latter need not be cut out, as it will be entirely hid and out

of the way in the completed machine. The boss at C may be cut off or allowed to remain to suit the fancy of the designer. These are examples of simple contrivances to accommodate the machinist.

## FINISHING PATTERNS

After the woodwork of the pattern is completed it must be "finished" by the application of one or more coats of varnish, all small holes or other defects in the material and workmanship filled with beeswax, and the whole surface made smooth so that it will draw easily.

This is usually done in the following manner: The dust from sandpapering is all cleaned off with either brush or waste and then a coat of moderately thick varnish is evenly applied. When this is dry all nail-holes and any defects in material are filled with beeswax; if any wax fillets are to be put in they should also be done at this stage. As this first coat of varnish dries it leaves the surface of the wood slightly rough; this is caused by the wetting and drying of the varnish which raises the grain of the wood. This may now be smoothed down by sandpapering it with fine and partly worn sandpaper until it becomes smooth to the touch. This is all that needs to be done if the pattern is to be used but once or twice. If it is to be used frequently one or two more coats should be applied. For a permanent finish, several thin coats will give better results than one or two thick ones, and will also make a better appearance. To make a very nice finish each coat should be rubbed smooth with fine sandpaper before applying the next. When patterns become rough from use in the foundry, or from any cause, they should be cleaned and refinished, for if a pattern is smooth and well finished it will give the molder little trouble and hence will not receive such hard usage. If a pattern

is rough the molder must rap and jar it considerably in order to draw it, and such treatment always injures wood patterns. In finishing patterns a varnish differing in color from that used for the body of the pattern should be put on all core-prints, so that the molder can tell at once the general position the cores will occupy in the mold.

## LOOSE PIECES

It is almost impossible to make some patterns without **loose pieces**, however objectionable they may be. They are, in some cases at least, preferable to cores. When a choice must be made between a core and a




FIG. 168.

loose piece the latter should generally be chosen, as it will insure a truer casting. These loose pieces are usually held in place on the pattern during the process of molding by skewers or draw-pins. Brads of suitable size for the job in hand and bent to a right angle near the head make good draw-pins. For standard patterns it is better to fit these loose pieces to the pattern

with dovetails, because when so fitted they are less liable to be pushed out of place by the molder in ramming the sand around them. Another reason is that the moulder does not have to stop and take out any skewers, but can go right on until the mold is all rammed up. In fact no notice need be taken of the loose pieces until after the main part of the pattern has been pulled. The best way to fit these dovetail pieces is to bevel them on the edges, and also in their thickness as shown in Fig. 168. They should be fitted very accurately as, if they are not, they are very liable to stick when drawing the pattern. The fact that they are beveled in both directions as suggested above and shown in the cut will almost always insure them against sticking.

## STANDARD PATTERNS

Standard patterns made of wood, and often used, should be made as durable as it is possible to make them, using hard wood, such as mahogany or cherry, for all the parts that come in direct contact with the sand. For all parted patterns, metal pattern pins should be used, brass being the best. The first cost is greater, but time and labor required for applying them is less, and, most important of all, they never stick, if properly fitted at first, so that in the "long run" they are the cheapest; and standard patterns are usually made for the "long run."

Rapping and draw-plates should always be fitted to all standard patterns, as they will save their cost in repair work in a very short time, to say nothing about the convenience of the molder. There are several kinds of these plates on the market at very reasonable prices. For anything except very large patterns, plates combining both rapping and drawing holes are the best. The rapping holes in these plates are simply drilled; drawing or lifting holes are taped to fit some standard screw thread. Another method of preparing standard patterns for the foundry is to fit them to a **follow-board**. This is almost always done when a large number of castings are wanted from a pattern that requires an irregular parting, or if the pattern is thin in cross section and is liable to be injured by ramming the sand around it. The cope side of the pattern is fitted into the top side of the board down to where the molder will make his parting, and the board cut to such a shape as

will form the parting. This follow board with its pattern laid in place, is used the same as a turn over or molding board in molding a simple pattern.



## STOVE PATTERN-MAKING

The fundamental ideas underlying the making of patterns for stove castings are practically the same as for machinery pattern-making; but on account of the shape and generally delicate character of the castings required, the methods of their production are in many respects quite different. The drawings furnished the stove pattern-maker are also radically different from those sent to the maker of machinery patterns. Generally a new design of a stove is first developed by making a drawing, and, at the same time, a model is also worked out in wax or clay, and in some cases a complete model is made of wood.

This gives the designer the opportunity of comparing curves and other ornamental features of the finished stove which is impossible from drawings alone, and enables him to see how it will be best to have the different parts fit each other at the many joints necessary. This is especially advantageous in the case of artistic heating stoves, on which there is usually a large amount of carving. A model, however, is not generally made in the case of plain work, such as cook stoves or ranges, these being carried through from drawings alone. There are also several tools that are used by the stove pattern-maker that are not used by others. These are made necessary by the requirements of the art; one of which is that the castings, and therefore the patterns, must generally be of uniform thickness, and comparatively thin in cross section, usually not exceeding 1-10 inch.

Almost all machinery pattern drawings are made

and all dimensions given in finished sizes so they may be used in the machine shop as well as in the pattern shop. Stove pattern drawings seldom go farther than the pattern shop. They are usually made full size and in some cases at least, the dimensions are not marked on them, so that the pattern-maker must take the sizes directly from the drawing by measuring it, and this is usually done with trams and applied to the shrink rule to be used. The plan is first drawn and then the elevations or side views are drawn in—usually on the same paper, so that the lines of each view are all mixed up, which makes the reading of them very difficult for those unfamiliar with this kind of work. Sometimes the lines of these different views are made with different colors, so as to be more easily read. The same shrink rule to be used in making the original patterns is used by the draftsman in making these drawings.

The stove wood pattern-maker is provided with from five to seven different shrink rules; the one to be used for any given pattern is determined by the kind of metal of which the master pattern is to be made and also the method of producing it. These rules are spoken of as one shrink, two shrink, or one and a half shrink according to the ratio of the rule to the standard rule, the word "shrink" in this instance meaning the general amount allowed in making machinery patterns, viz:  $\frac{1}{8}$  inch. Which one of these is to be used is determined by the material to be used in the production of the master pattern.

Because of the necessity of beveling the edges of all stove plates where they come together, and to have these bevels uniform throughout the stove, it has been

found advantageous by stove pattern-makers to have a set of "bevel gages" for measuring and laying out these bevels. Such a set of bevel gages was originated by Mr. N. Vedder, formerly a stove designer of Troy, N. Y. These have come into extensive use among stove manufacturers during the last few years. In order that these gages may be convenient for use, they are made of thin wood or metal similar to the triangles used in making mechanical drawings. There are eight of these bevels in use ranging from one of about  $2^{\circ}$  to that of  $30^{\circ}$ , which is the largest angle used. These are numbered as follows: From two degrees to eight degrees are four bevels numbered by ciphers, two degrees being designated by 0000, the next by 000, the next by 00, and the next by 0, which is eight degrees. The other four bevels are designated by the numerals 1, 2, 3, 4, number one being an angle of  $10^{\circ}$ , number two,  $16\frac{2}{3}^{\circ}$ , number three,  $23\frac{1}{3}^{\circ}$ , and number four,  $30^{\circ}$ . As in a large part of stove patterns it is necessary to make them of curved outline, and as these curves cannot very well be marked out with trams, a set of standard curves have been adopted. These are used by having them made up of thin wood or metal (metal being best) so they may be used in the same way as the bevel gages. These are likewise used by both draftsman and pattern-maker.

It sometimes becomes necessary to make a center line across a carved or other uneven surface. For this purpose a simple contrivance known as a "vertical plumb" has been devised. It consists of two boards fastened together lengthwise at their edges and at right angles to each other. This must be set up on two parallel blocks of such a height as will raise it above a pat-

tern or other object on which it is required to make a straight line across the uneven surface. A scribe with which to make the mark is also needed. This consists of a thin flat piece of wood on which is fastened a thin plate of steel sharpened to a keen cutting edge.

Stove patterns must be carved very thin and made of uniform thickness throughout. If they are not the castings will not be of even thickness, so that one part will cool more rapidly than others, thereby causing them to warp and sometimes to crack from the shrinkage strains. To insure that the patterns are of uniform thickness, a special form of calipers is used for measuring their thickness. These calipers are made with a loose joint something like a pair of shears. Just at the back of these shear-like handles are short projections, through one of which a screw is put, the end of the screw abutting against the other. The points of the calipers may be set to a definite distance apart, the above screw turned in until its end comes in contact with the other projection mentioned. The calipers may now be opened and passed over any intervening thick part of a pattern and the points closed again to the same distance as before. Now if the screw does not touch, or come to a bearing, the pattern is too thick at that point and must be pared down. Most stove plate work is very uneven on the surface on account of the carving and other ornamental work. In order that the pattern may be of equal thickness it has to be "backed out," as it is called, that is, it has to be carved out on the back to conform to the shape of the carving on the front. This makes it necessary that the outlines of the carving be transferred to the back. This is most easily and accurately done by

the use of what are known as marking calipers. These are usually made of hard wood and similar in shape to the ordinary wing caliper, that is, hinged together at the end of what may be called the handle. One leg is provided with a steel point, the other with a pencil point. A spring is set in between the two parts of the handle that tends to open the points, so that in order to bring the points together this spring must be compressed. By following the outline of the carving with the steel point, and at the same time compressing the spring and keeping the pencil point in contact with the back of the pattern, the outline may be accurately and rapidly transferred to that side. Many parts of stove patterns have to be joined on an angle, and as the stock is generally very thin, it is quite difficult to joint the edges to the correct angles; therefore it is necessary that some device be provided for holding the stock in a fixed position with regard to the plane. For this purpose some form of shoot-board is found useful. One form of shoot-board is represented by Fig. 125 on page 166. For stove pattern work, however, it must be more complicated than is this, as it is necessary that it be adjustable to several different angles, and be set accurately to any given angle within its limits. As a large amount of carving is necessary in stove pattern-making which cannot be done with the chisels and gouges of the ordinary pattern-maker's outfit, the stove pattern-maker is provided with a series of carving tools, usually about twenty in number. In large establishments making stove patterns, the carving is usually done by men especially skilled in that work, and in some cases stove patterns pass through the hands of several men, each doing his

own special kind of work. A large quantity of very thin stock, some of which is less than  $1/12$  inch in thickness is required for this class of patterns. As this cannot very well be made on the ordinary planer without some special attachment, a suitable one is provided for the planer in stove pattern shops with which thin boards may be planed smoothly and to a uniform thickness.

Almost all machinery patterns are fairly thick and stiff enough of themselves for the purpose of molding; moreover, in the production of this class of patterns, the application of the principles of joinery is an important part. Stove patterns are usually very thin, and practically of uniform thickness throughout and therefore require special treatment. Stove patterns are rarely stiff enough of themselves for the purposes of molding and must be supported by what is called a "match" during the process of molding to produce the metal patterns. The match is very frequently made first and the pattern made or built on it. In many cases these patterns are very intricate having quite a large amount of carving on them.

Because of these many facts, stove pattern-making differs considerably from ordinary pattern-making and is a distinct branch of the art. The original pattern for stove work is usually made of wood; in some shops, however, original patterns are sometimes modeled in clay or plaster-of-Paris. From this original pattern a master pattern is made of iron. For this purpose, however, some foundries use a white metal alloy consisting of nine parts lead and one part antimony, which has a shrinkage of  $1/16$  inch per foot. This is preserved and

from this the pattern to be used in the production of the castings for the stoves is made. The original wood patterns are rarely kept as they are sure to change their form.

There are several distinct processes used in making stove-patterns, but on account of space they cannot be described and will for that reason be just barely mentioned. One of these is what is known as the "carving and backing-out wooden patterns." This is the simplest, and means that the pattern is carved out of wood to the exact shape and thickness. For a small pattern like a stove leg for instance, this would be all that is necessary from which to make the mold for the master pattern. For large patterns in this process, however, a match or follow-board must be made to support the pattern while ramming up the nowel. Another distinct process is the "wax process." This is used to avoid backing-out the wooden pattern. Considerable practice or experience is necessary to work this method successfully. Then there is the "carving and blocking" process, in which the molder surrounds the pattern with a thin layer of blocking just the thickness of the required casting, when ramming up the drag. In all these processes the block of wood used for the pattern is "built up" of thin pieces of wood, so as to reduce the effects of shrinking and swelling to the minimum. In many stove patterns allowance has to be made for the warping of the casting. This is usually done by preparing a special form of mold-board which is curved so as to give the required curve to the pattern, as it is built on to and over the mold-board. This is necessary because a casting made from a straight pattern often

comes out warped or bent and it becomes necessary to bend the pattern in the opposite direction so that the casting will come out straight.

In machinery or general pattern-making the term "master pattern" is used in speaking of the **original** wood pattern when a metal pattern is to be made, from which to make the castings wanted. It is not so used, however, in connection with stove pattern making. The use of the term in this division of the art means the metal pattern that is made from the original wood pattern, from which the regular patterns are made that are used in the foundry for making the stove castings. These **master patterns** are very costly to make and therefore are very valuable, and are very carefully stored. A set of these patterns for an ornate heating stove frequently costs from fifteen hundred to two thousand dollars.



## INDEX.

Angle of cutting wedge...	41	Carpenter's plow .....	39
Annular patterns .....	132, 163	Car wheel, double flange..	118
Architectural patterns ....	90	single flange .....	117
Arms of wheels .....	195, 201	Castings, estimating weight	
Assembling pulley .....	176	of .....	209
		Chisels .....	19
Backing out stove patterns	234	Chords of curves.....	164
Beeswax .....	98	Chuck, cup .....	62
Bench .....	9	fork .....	61
Bevel gages .....	233	large .....	221
Bevel gear patterns .....	196	screw .....	61
Bit, auger .....	27	Clamp .....	32
brace .....	29	Combining pieces of wood	
center .....	28	in patterns .....	94
countersink .....	29	Concentric .....	176
drill .....	27	hubs to be.....	177
square hole .....	27	layers .....	47
Black varnish .....	97	Constructional joints.....	125
Block-plane .....	37	Copal varnish .....	98
Board foot .....	12	Cope .....	77, 78
Boxing up patterns.....	129	bars .....	79
Brads .....	98	Core board .....	216
Brass for patterns.....	94	Core-box .....	108
shrinkage of .....	88	conical .....	144
		ends .....	146
Cabinet turning.....	60	plane .....	40
Calculating data for a cast		plane, use of.....	143
gear .....	191	Core-prints.....	108
Calipers for stove pattern-		Cores .....	107
making .....	234	Core strickle .....	216
inside .....	70	Corners in patterns.....	101
marking .....	235	inside .....	101
outside .....	70	outside .....	101

## INDEX—(Continued).

Counter ribs .....	127	Gears	
Curvature of plane-irons..	37	tooth curves for.....	191
Cutting edge, whetting of.	43	Glue .....	95
Cylindrical core prints.110, 112		Glue, to resist moisture...	96
summary of .....	115	use of .....	95
Dividers .....	16	Gluing feather edge board.	219
laying out angles with...	16	Gluing up work.....	96
Double shrinkage pattern..	94	Gouges .....	20
Draft on patterns .....	85	turning .....	63
Drawings, reading of.....	53	Grain of wood .....	47
Emery wheels for grinding		Grinding chisel .....	42
tools .....	42	cutting wedges .....	41
Engineer, requirements of.	75	plane-iron .....	41
Face-plate .....	197, 198	Handsaw .....	22
Faces, working .....	136	Handscrew .....	32
Felling trees .....	48	use of .....	32
Filing saws .....	26	Heart wood .....	47
Fillets .....	101	Irregular parting .....	119
applying leather .....	105	Jointer plane .....	33
applying wax .....	106	Joints, constructional in	
materials for .....	103	patterns .....	125
size of .....	102	molder's in patterns....	116
to strengthen castings...	102	Keyhole saw .....	23
wood .....	103	Knife, draw .....	21
Gage marking .....	17	Lagging .....	131
mortice .....	18	Lagging up .....	131
Gear patterns, arms for... 195		Lags, patterns made of....	131
teeth for .....	187, 188	Laying out gear teeth....	193
tooth blocks for .....	187	Laying out pulley arms....	173
Gears .....	183	Leather fillets .....	105
bevel .....	196	Legal standard (unit of	
laying out of.....184, 185		measure) .....	11
patterns for .....	183	Loam patterns .....	215

## INDEX—(Continued).

Lugs for machinists' use..	222	Planes, combination .....	39
Lumber, quarter-sawn..	46, 92	use of .....	34
		with narrow mouth.....	35
Mahogany .....	93	wood .....	36
Marking calipers .....	235	Plane-iron .....	35
Master patterns ...	94, 236, 238	curvature of .....	37
Match .....	236	Pulley, pattern for.....	163
Measuring appliances ....	11		
Medullary ray ....	46, 51, 92	Quarter-sawn lumber ..	46, 92
Metals, shrinkage of.....	87		
Miter-box .....	30	Sandpaper .....	95
Molding .....	77	Sap .....	47
Mortise gage .....	18	side of board.....	92
		Saw, back .....	22
Nails .....	98	compass .....	23
Nowel .....	78, 79	filing .....	25
		hand .....	22
Oilstone .....	43	kerf .....	25
Open joints .....	128, 129	keyhole .....	23
		setting .....	25
Parting, molders'.....	116	Sawing out pulley rim....	175
pattern-makers' .....	116	Sawing segments .....	164
Pattern lathe .....	60	Scale on castings.....	90
Pattern-making and mold-		Scales for measuring.....	11
ing, (connection be-		Scraping a surface .....	67
tween) .....	74	tools .....	63, 64
Pattern pins .....	148	Screwdriver .....	30
Patterns, wood for....	91, 93	Screws .....	99
Pins, pattern .....	148	in end wood.....	99
Plane, block .....	37	Sharpening lathe tools....	69
core box .....	40	Shellac varnish .....	97
dado .....	39	Shoot board .....	166
jack .....	33, 37	Snrink rule .....	11, 88
jointer .....	33	Shrink rules for stove pat-	
plow .....	39	tern-makers .....	232
rabbet .....	38	Shrinkage, double .....	94
smoothing .....	33	of aluminum .....	88

## INDEX—(Continued).

Shrinkage of		Turning	
brass .....	88	in cup chuck.....	62
iron .....	88	lathe .....	60
steel .....	88	pattern .....	60
wood .....	49, 51	pulley rim .....	170
Skeleton patterns.....	215	tools .....	63, 65
Skewering on loose pieces.	121		
Square, combination.....	15	Varnish, black .....	97
framing .....	13	copal .....	98
try .....	14	red .....	98
Stock for stove patterns..	236	shellac .....	97
Stop-off pieces .....	127	yellow .....	97
Stove pattern-making.....	231	Vertical plumb .....	233
Strickles .....	216	sides pattern .....	84
Surfacing planes .....	33	Wise, pattern-makers'.....	9
Swelling of wood.....	50, 51		
		Warp, allowance for.....	90
Taper on patterns .....	85	Warping in castings ...	91, 237
T-bevel .....	16	of wood .....	51, 91
Thin boards, building of..	126	Waxing iron patterns ....	98
disks, building of.....	126	Winding sticks .....	33
Trimmer (also frontis-		Wood drills .....	27
piece) .....	166	fillets, forming of.....	103
Turning, cabinet .....	60	for patterns .....	91, 93
chisel .....	63	Wood patterns, definition	
use of .....	66	of .....	72
gouge .....	63	Working sketches .....	138
use of .....	65	Worm wheel .....	119

# Books on the Manual Arts

---

## **HANDWORK IN WOOD.**

By WILLIAM NOYES.

A handbook for teachers and a textbook for normal school and college students. A comprehensive and scholarly treatise, covering logging, sawmilling, seasoning and measuring, hand tools, wood fastenings, equipment and care of the shop, the common joints, types of wood structures, principles of joinery, and wood finishing. 304 illustrations—excellent pen drawings by Anna Gausmann Noyes. Price, \$2.00.

## **ESSENTIALS OF WOODWORKING.**

By IRA S. GRIFFITH.

A textbook written especially for the use of grammar and high school students. A clear and comprehensive treatment of woodworking tools, materials, and processes, to supplement, but not to take the place of the instruction given by the teacher. The book does not contain a course of models; it may be used with any course. It is illustrated with photographs and numerous pen drawings by Edwin V. Lawrence. Price, \$1.00.

## **BEGINNING WOODWORK. At Home and in School.**

By CLINTON S. VANDEUSEN.

A full and clear description in detail of the fundamental processes of elementary benchwork in wood. This description is given through directions for making a few simple, useful articles, suitable either for school or home problems. The book contains more than one hundred original sketches and ten working drawings by Edwin V. Lawrence. Price, \$1.00.

## **WOODWORK FOR SCHOOLS ON SCIENTIFIC LINES.**

By JAMES THOMAS BAILEY and S. POLLITT.

The American edition of an English book containing 120 practical problems, many of which have been designed to correlate mathematics and physical science with manual training. Price, 75 cents.

---

PUBLISHED BY

**The Manual Arts Press, Peoria, Illinois**

# Books on the Manual Arts

---

## PROBLEMS IN WOODWORKING.

By M. W. MURRAY.

A convenient collection of good problems consisting of forty plates bound in heavy paper covers with brass fasteners. Each plate is a working drawing, or problem in benchwork that has been successfully worked out by boys in one of the grades from seven to nine inclusive. Price, 75 cents. Board covers, 20 cents extra.

## PROBLEMS IN FURNITURE MAKING.

By FRED D. CRAWSHAW.

This book consists of 32 plates of working drawings suitable for use in grammar and high schools and 24 pages of text, including chapters on design, construction and finishes, and notes on the problems. Price, \$1.00. Board covers, 20 cents extra.

## PROBLEMS IN WOOD-TURNING.

By FRED D. CRAWSHAW.

In the first place this is a book of problems—25 plates covering spindle, face-plate, and chuck turning. In the second place it is a textbook on the science and art of wood-turning illustrated by fifty pen sketches. It gives the mathematical basis for the cuts used in turning. In the third place it is a helpful discussion of the principles of design as applied to objects turned in wood. It is a clear, practical and suggestive book on wood-turning. Price, 80 cents. Board covers, 20 cents extra.

## PROBLEMS IN MECHANICAL DRAWING.

By CHARLES A. BENNETT. With drawings by FRED D. CRAWSHAW.

This book consists of 80 plates and a few explanatory notes, and is bound in heavy paper covers with brass fasteners. Its purpose is to furnish teachers of classes beginning mechanical drawing with a large number of simple, practical problems. These have been selected with reference to the formation of good habits in technique, the interest of the pupils, and the subjects generally included in a grammar and first-year high school course. Each problem given is unsolved and therefore in proper form to hand to the pupil for solution. Price, \$1.00. Board covers, 20 cents extra.

---

PUBLISHED BY

**The Manual Arts Press, Peoria, Illinois**

# Books on the Manual Arts

---

## **SELECTED SHOP PROBLEMS.**

By GEORGE A. SEATON.

A collection of sixteen problems in woodworking made to meet the needs of busy teachers of manual training. Each problem has been put to the test and has proven satisfactory to the teacher who designed it and the pupil who made it. Price, 20 cents.

## **COPING SAW WORK.**

By BEN. W. JOHNSON.

Contains working drawings and suggestions for teaching a course of work in thin wood that is full of fun for the children, and affords ample means for training in form study, construction, invention and careful work. Has been called "applied mechanics for the fourth grade." Price, 20 cents.

## **THE CONSTRUCTION AND FLYING OF KITES.**

By CHARLES M. MILLER.

This contains seven full-page plates of drawings of kites and fifteen figures—over forty kites shown. Details of construction given; a kite tournament is described. Full of interesting suggestions. Price, 20 cents.

## **CLAY WORK.**

By KATHERINE MORRIS LESTER.

This book has been written by a grade teacher and art worker to help teachers in acquiring the technique of clay working, and to give them suggestions concerning the teaching of the several types of clay work suited to pupils in the elementary schools. It covers the study of natural forms, the human figure in relief, and the round, animal forms, story illustration, architectural ornament, tiles, hand-built pottery, and pottery decoration. The book is richly illustrated with more than fifty half-tone and line cuts showing processes, designs, and the work of children from ten to twelve years of age. Price, \$1.00.

## **THE WASH METHOD OF HANDLING WATER COLOUR.**

By FRANK FORREST FREDERICK.

A brief, clear, comprehensive text printed in sepia and illustrated with wash drawings and a water-color painting by the author. Price, 50 cents.

---

PUBLISHED BY

**The Manual Arts Press, Peoria, Illinois**

# Books on the Manual Arts

---

## **HANDWORK INSTRUCTION FOR BOYS.**

By DR. ALWIN PABST. Translated from the German  
by BERTHA REED COFFMAN.

This is a notable discussion of the educational value of handwork, by the director of the school for training teachers of handwork at Leipsic. It traces instruction in handwork thru the history of education, points out its place in the several types of schools, and gives a rapid survey of modern systems of handwork in the leading civilized countries of the world. Price, \$1.00.

## **HANDICRAFT FOR GIRLS.**

By IDABELLE MCGLAUFLIN.

A handbook for teachers, detailing a five-years course in sewing for girls, in the public schools. Chapters on stitches, fibers and fabrics, cloth and cardboard construction, basketry, dress in its relation to art, and home furnishing. It is definite enough to be thoroly practical and elastic enough to suit the varied conditions in rural, village or city schools. Price, \$1.00.

## **SIMPLIFIED MECHANICAL PERSPECTIVE.**

By FRANK FORREST FREDERICK.

A book of simple problems covering the essentials of mechanical perspective. It is planned for pupils of high school age who have already received some elementary training in mechanical drawing. It is simple, direct and practical. Price, 75 cents.

## **CLASSROOM PRACTICE IN DESIGN.**

By JAMES PARTON HANEY.

A concise, up-to-date, richly illustrated brochure on the teaching of applied design. Price, 50 cents.

## **MANUAL TRAINING MAGAZINE.**

CHARLES A. BENNETT, Editor; WILLIAM T. BAWDEN,  
Managing Editor.

Assisted by a staff of associate and department editors. Illustrated; published bi-monthly. Subscription price, \$1.50 a year.

---

PUBLISHED BY

**The Manual Arts Press, Peoria, Illinois**







UC SOUTHERN REGIONAL LIBRARY FACILITY



**A** 000 037 567 5

